20Progress%20Report%2D10%2E10%2E1996%2Epdf

Document Type: Site Documents Document Date: 10/10/1996

Type: PROPOSED PLAN Submitted:

Submitted By: BONNIE LAM (REGULATOR)

Title: UNOCAL SERVICE STATION #7379 WORKPLAN DATED SEPTEMBER 20 1996-10.09.1996

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847567

Document Type: Site Documents Document Date: 9/20/1996

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By:BONNIE LAM (REGULATOR)Title:BILL OF LADING INVOICE NO. 1730

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847595

Document Type: Monitoring Reports **Document Date:** 6/28/1996

Type: MONITORING REPORT - QUARTERLY Submitted:

Submitted By: BONNIE LAM (REGULATOR)

Title: 1ST QUARTER 1996 PROGRESS REPORT-04.26.1996 -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/6463976800/1st%20Quarter%201996%

20Progress%20Report%2D04%2E26%2E1996%2Epdf

Document Type: Site Documents **Document Date:** 4/23/1996

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By: TORREN CAMPBELL (REGULATOR)

Title: UNDERGROUND STORAGE TANK PERMIT APPLICATION

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=6009161

Document Type: Monitoring Reports **Document Date:** 2/16/1996

Type: MONITORING REPORT - QUARTERLY

Submitted By: BONNIE LAM (REGULATOR)

Title: 4TH QUARTER 1995 PROGRESS REPORT-02.02.1996 -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3713318347/4th%20Quarter%201995%

Submitted:

20Progress%20Report%2D02%2E02%2E1996%2Epdf

Document Type: Site Documents Document Date: 2/5/1996

Type: CORRESPONDENCE Submitted:

Submitted By: BONNIE LAM (REGULATOR)

Title: MODIFICATION TO GROUNDWATER MONITORING PROGRAM-02.02.1996

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847584

Document Type: Site Documents **Document Date:** 11/30/1995

Type: TANK REMOVAL REPORT / UST SAMPLING Submitted:

REPORT

Submitted By: BONNIE LAM (REGULATOR)

Title: USED OIL TANK AND HOIST REMOVAL AND PRODUCT-LINE REPLACEMENT-11.20.1995

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847566

Document Type: Site Documents Document Date: 11/20/1995

Type: TANK REMOVAL REPORT / UST SAMPLING Submitted:

REPORT

Submitted By: KIMBERLY YEE (REGULATOR)

Title: REPORT USED-OIL TANK AND HOIST REMOVAL AND PRODUCT-LINE REPLACEMENT

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5743898

Document Type: Monitoring Reports **Document Date:** 10/20/1995

Type: MONITORING REPORT - QUARTERLY Submitted:

Submitted By: BONNIE LAM (REGULATOR)

3RD QUARTER 1995 PROGRESS REPORT-10.18.1995 -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8986067056/3rd%20Quarter%201995%

20Progress%20Report%2D10%2E18%2E1995%2Epdf

Document Type: Site Documents Document Date: 8/15/1995

Type: PROPOSED PLAN Submitted:

Submitted By: BONNIE LAM (REGULATOR)

Title: PROPOSAL FOR OFFSITE CONSEQUENCE INVESTIGATION-08.11.1995

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847613

Order No: 24072600476

Document Type: Site Documents **Document Date:** 7/31/1995

Type: OTHER REPORT / DOCUMENT Submitted:

Title:

Number of Direction Elev/Diff Site DΒ Map Key Distance Records (mi/ft) (ft)

KIMBERLY YEE (REGULATOR) Submitted By:

LETTER REPORT OIL WATER SEPARATOR ABANDONMENT Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5742635 Title Link:

Document Type: Monitoring Reports Document Date: 7/17/1995

MONITORING REPORT - OTHER Submitted: Type:

BONNIE LAM (REGULATOR) Submitted By:

GROUNDWATER MONITORING AND SAMPLING REPORT-07.12.1995 -Title:

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4574767172/Groundwater%

20Monitoring%20and%20Sampling%20Report%2D07%2E12%2E1995%2Epdf

Submitted:

Submitted:

Submitted:

Document Type: Site Documents Document Date: 5/17/1995

Type: CORRECTIVE ACTION PLAN / REMEDIAL

ACTION PLAN

Submitted By: BONNIE LAM (REGULATOR)

ORDER TO PERFORM OFFSITE CONSEQUENCE INVESTIGATION AND REMEDIAL ACTION PLAN-Title:

05.11.1995

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847581 Title Link:

Document Type: Monitoring Reports Document Date: 4/26/1995

MONITORING REPORT - OTHER Type:

BONNIE LAM (REGULATOR) Submitted By:

GROUNDWATER MONITORING AND SAMPLING REPORT-04.24.1995 -

 $https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8052306950/Groundwater\% where the control of the cont$ Title Link:

20Monitoring%20and%20Sampling%20Report%2D04%2E24%2E1995%2Epdf

Monitoring Reports Document Date: 3/7/1995 Document Type:

MONITORING REPORT - OTHER Type:

Title:

BONNIE LAM (REGULATOR) Submitted By:

GROUNDWATER MONITORING AND SAMPLING REPORT-03.03.1995 -Title:

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5446230828/Groundwater% Title Link:

20Monitoring%20and%20Sampling%20Report%2D03%2E03%2E1995%2Epdf

Monitoring Reports Document Date: 9/26/1994 Document Type: Submitted:

MONITORING REPORT - OTHER Type:

BONNIE LAM (REGULATOR) Submitted By:

MONITORING AND SAMPLING DATED AUGUST 26 1994-09.26.1994 -Title:

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7633196771/Monitoring%20and%

20Sampling%20dated%20August%2026%201994%2D09%2E26%2E1994%2Epdf

Monitoring Reports Document Date: 8/11/1994 Document Type: Submitted:

MONITORING REPORT - OTHER Type:

BONNIE LAM (REGULATOR) Submitted By:

Title: GROUNDWATER MONITORING AND SAMPLING REPORT DATED JULY 12 1994-08.11.1994 https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5127201914/Groundwater% Title Link:

20Monitoring%20and%20Sampling%20Report%20Dated%20July%2012%201994%2D08%2E11%2E1994%2Epdf

Document Type: Monitoring Reports **Document Date:** 3/23/1994 Submitted:

MONITORING REPORT - OTHER Type:

Submitted By: **BONNIE LAM (REGULATOR)**

GROUNDWATER MONITORING AND SAMPLING REPORT DATED MARCH 2 1994-03.18.1994 -Title: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5764958262/Groundwater% Title Link:

20Monitoring%20and%20Sampling%20Report%20Dated%20March%202%201994%2D03%2E18%2E1994%

Order No: 24072600476

2Epdf

Document Type: Site Documents **Document Date:** 2/11/1994

SITE ASSESSMENT REPORT Submitted: Type:

BONNIE LAM (REGULATOR) Submitted By:

SUPPLEMENTAL SITE INVESTIGATION REPORT DATED DECEMBER 22 1993 Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847660 Title Link:

Document Type: Site Documents Document Date: 12/1/1993

OTHER REPORT / DOCUMENT Type: Submitted:

KIMBERLY YEE (REGULATOR) Submitted By:

SUPPLEMENTAL SITE INVESTIGATION REPORT

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5743908

Document Type: Monitoring Reports Document Date: 8/18/1993

MONITORING REPORT - OTHER Type: Submitted:

Title:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

BONNIE LAM (REGULATOR) Submitted By:

GROUNDWATER MONITORING AND SAMPLING REPORT DATED JULY 30 1993-08.06.1993 -Title: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/2385421574/Groundwater% Title Link:

20Monitoring%20and%20Sampling%20Report%20Dated%20July%2030%201993%2D08%2E06%2E1993%2Epdf

Monitoring Reports Document Type: Document Date: 6/11/1993

MONITORING REPORT - OTHER Type:

BONNIE LAM (REGULATOR) Submitted By:

Title: GROUNDWATER MONITORING AND SAMPLING REPORT DATED MAY 18 1993-06.08.1993 https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3790480673/Groundwater% Title Link:

20Monitoring%20and%20Sampling%20Report%20Dated%20May%2018%201993%2D06%2E08%2E1993%2Epdf

Submitted:

Document Type: Monitoring Reports **Document Date:** 2/26/1993

MONITORING REPORT - QUARTERLY Type: Submitted:

Submitted By: BONNIE LAM (REGULATOR)

FOURTH QUARTER 1992 GROUNDWATER MONITORING REPORT DATED FEBRUARY 16 1993 -Title: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3362715005/Fourth%20Quarter% Title Link: 201992%20Groundwater%20Monitoring%20Report%20Dated%20February%2016%201993%2Epdf

Monitoring Reports Document Date: 2/5/1993 Document Type:

MONITORING REPORT - QUARTERLY Type:

BONNIE LAM (REGULATOR) Submitted By:

3RD QUARTER 1992 GROUNDWATER SAMPLING AND ANALYSIS-02.02.1993 -Title:

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/9215502679/3rd%20Quarter%201992% Title Link:

20Groundwater%20Sampling%20and%20Analysis%2D02%2E02%2E1993%2Epdf

Submitted:

Site Documents Document Date: 12/24/1992 Document Type:

CORRESPONDENCE Submitted: Type:

BONNIE LAM (REGULATOR) Submitted By: SS# 10-HTO-12.18.1992 Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847571

Document Type: Site Documents Document Date: 11/6/1992

WELL INSTALLATION REPORT Submitted: Type:

Submitted By: BONNIE LAM (REGULATOR)

Title:

SUBSURFACE ENVIRONMENTAL INVESTIGATION REPORT-11.05.1992

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847570 Title Link:

Document Type: Monitoring Reports 10/1/1992 Document Date: Submitted:

Type: MONITORING REPORT - QUARTERLY

BONNIE LAM (REGULATOR) Submitted By:

QUARTERLY SUMMARY RÉPORT OCTOBER TO DECEMBER 1992-10.01.1992 -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5872678458/Quarterly%20Summary%

20Report%20October%20to%20December%201992%2D10%2E01%2E1992%2Epdf

Site Documents Document Date: 10/1/1992 Document Type:

SOIL AND WATER INVESTIGATION Submitted: Type:

REPORT

KIMBERLY YEE (REGULATOR) Submitted By:

SUBSURFACE ENVIRONMENTAL INVESTIGATION REPORT

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5743906 Title Link:

Document Type: Monitoring Reports Document Date: 8/28/1992 Submitted:

MONITORING REPORT - QUARTERLY Type:

BONNIE LAM (REGULATOR) Submitted By: Title:

2ND QUARTER 1992 GROUNDWATER SAMPLING AND ANALYSIS REPORT-08.26.1992 -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4723454356/2nd%20Quarter%201992%

20Groundwater%20Sampling%20and%20Analysis%20Report%2D08%2E26%2E1992%2Epdf

Monitoring Reports Document Date: 7/8/1992 Document Type: Submitted:

Type: MONITORING REPORT - QUARTERLY Submitted By:

BONNIE LAM (REGULATOR)

QUARTERLY SUMMARY REPORTS FOR APRIL - JUNE 1992-07.08.1992 -

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/6340971231/Quarterly%20Summary% Title Link:

20Reports%20for%20April%20%2D%20June%201992%2D07%2E08%2E1992%2Epdf

Order No: 24072600476

Document Date: 5/19/1992 Document Type: Site Documents

WELL INSTALLATION REPORT Submitted: Type:

Submitted By: **BONNIE LAM (REGULATOR)**

Title:

Title:

Title:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

RESULTS OF SHALLOW GROUNDWATER SURVEY AND PROPOSED LOCATIONS FOR MONITORING Title:

WELLS-05.18.1992

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847574 Title Link:

Document Type: Monitoring Reports Document Date: 5/4/1992

MONITORING REPORT - QUARTERLY Submitted: Type:

BONNIE LAM (REGULATOR) Submitted By:

1ST QUARTER 1992 GROUNDWATER SAMPLING AND ANALYSIS-04.30.1992 -Title:

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7736605584/1st%20Quarter%201992%

20Groundwater%20Sampling%20and%20Analysis%2D04%2E30%2E1992%2Epdf

Monitoring Reports 4/6/1992 Document Type: Document Date:

MONITORING REPORT - QUARTERLY Type: Submitted:

BONNIE LAM (REGULATOR) Submitted By:

QUARTERLY SUMMARY REPORT JANUARY - MARCH 1992-04.06.1992 -Title:

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1869535684/Quarterly%20Summary% Title Link:

20Report%20January%20%2D%20March%201992%2D04%2E06%2E1992%2Epdf

Monitoring Reports Document Date: 3/19/1992 Document Type: Submitted:

MONITORING REPORT - QUARTERLY Type: **BONNIE LAM (REGULATOR)** Submitted By:

DECEMBER 1991 QUARTERLY GROUNDWATER SAMPLING AND ANALYSIS-03.05.1992 -Title:

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/2262654185/December%201991% Title Link:

20Quarterly%20Groundwater%20Sampling%20and%20Analysis%2D03%2E05%2E1992%2Epdf

Site Documents Document Date: 7/26/1991 Document Type:

PRELIMINARY SITE ASSESSMENT Submitted: Type:

WORKPLAN

BONNIE LAM (REGULATOR) Submitted By:

WORKPLAN FOR SITE INVESTIGATION-07.01.1991 Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847564

Document Date: Document Type: Site Documents 5/6/1991

CORRESPONDENCE Submitted: Type:

TORREN CAMPBELL (REGULATOR) Submitted By:

CORRESPONDENCE Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=6009159 Title Link:

Site Documents Document Type: Document Date: 1/25/1991

Type: TECHNICAL CORRESPONDENCE / Submitted:

ASSISTANCE / OTHER

Submitted By: TORREN CAMPBELL (REGULATOR) HAZARDOUS MATERIALS RELEASE Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&enforcement_id=6421135

Document Type: Site Documents **Document Date:** 11/9/1990

Type: PROPOSED PLAN Submitted:

Submitted By: **BONNIE LAM (REGULATOR)**

GROUNDWATER ANALYTICAL RESULTS AND RECOMMENDATIONS FOR FUTURE WORK-10.01.1990 Title: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847592 Title Link:

Site Documents Document Date: 8/27/1987 Document Type:

SOIL AND WATER INVESTIGATION Type: Submitted:

REPORT

TORREN CAMPBELL (REGULATOR) Submitted By: SUBSURFACE INVESTIGATION REPORT Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=6009163

Document Type: Site Documents Document Date: 10/27/1986

OTHER REPORT / DOCUMENT Type: Submitted:

Submitted By: TORREN CAMPBELL (REGULATOR) Title: GROUNDWATER MONITORING SYSTEM

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=6009160 Title Link:

Order No: 24072600476

Site Documents 8/21/1986 Document Type: Document Date:

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

BONNIE LAM (REGULATOR) Submitted By: Title: TANKAGE PROJECT-08.18.1986

Number of Elev/Diff Site DB Map Key Direction Distance Records (mi/ft) (ft)

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847569 Title Link:

8/5/1986 Document Type: Site Documents Document Date:

PROPOSED PLAN Submitted: Type:

Submitted By: **BONNIE LAM (REGULATOR)**

LAB RESULTS AND PROPOSAL FOR MONITORING WELLS-08.05.1986 Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=5847585

Site Documents **Document Date:** 6/11/1986 Document Type: Submitted:

UNAUTHORIZED RELEASE FORM Type: Submitted By:

TORREN CAMPBELL (REGULATOR)

Title: **FUEL LEAK CASE FORM**

30-0353

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=6009162

Document Type: Site Documents Document Date: 6/9/1986

UNAUTHORIZED RELEASE FORM Type:

Submitted By: TORREN CAMPBELL (REGULATOR) Title: UNAUTHORIZED RELEASE FORM

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100088&document_id=6009164

3 of 10 NW 0.12/ 6.42/ Circle K Stores, Store #5784 42 **CUPA MARIN** 630.05 2 981 Francisco Boulevard East,

Submitted:

San Rafael CA

Permit No: Type of Permit:

Cross Ref:

Status: Active US Tanks: 3 AG Tanks: 0 нмвр: 3

Cal ARP: No

UFC: No **HWG Tons:** 0.0

> HWG Recycle: No HWG Type Gen: Tiered: No PBR HHW: No Green: Nο

Facility Phone No: (415) 457-8090

4 of 10 NW 0.12/ **MOBIL SERVICE STATION** 42 6.42/ **HHSS** 630.05 981 FRANCISCO BL. SAN RAFAEL CA 94901

Marin County:

Tank Details Microfiche: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/000292f3.pdf

42 5 of 10 NW 0.12/ 6.42/ Circle K Stores, Store #5784 **CERS TANK**

630.05 981 FRANCISCO BOULEVARD

EAST

SAN RAFAEL CA 94901

Order No: 24072600476

Site ID: 19250 Latitude: 37.960938 Longitude: -122.504920

Regulated Programs

EI ID: 10031515

El Description: Underground Storage Tank

EI ID: 10031515

El Description: Chemical Storage Facilities

EI ID: 10031515

El Description: Hazardous Waste Generator

Violations

Violation Date: 07/02/2019 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2712(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(f)

Violation Notes:

Returned to compliance on 07/12/2019. Owner/Operator did not implement the corrections specified in the March 2018 inspection report within 30 days of receiving an inspection report from either the CUPA or special inspector. Correct all deficiencies identified on the inspection report (same deficiency identified in this report) provided by the CUPA or special inspector within 30 days.

Violation Description:

Failure to implement the corrections specified in the inspection report within 30 days of receiving an inspection report from either the UPA or special inspector.

Violations

Violation Date: 03/10/2022 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.7 25284 - California Health and Safety Code, Chapter 6.7, Section(s) 25284

Violation Notes:

Returned to compliance on 03/11/2022. Permitting fees for 2022 period invoiced 11.21.2021 unpaid as of 03.10.2022 Pay invoice to return to compliance

Violation Description:

Failure to obtain a valid permit to operate from the UPA including but not limited to unpaid permit fees.

Violations

Violation Date: 03/15/2023 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)

Violation Notes:

The Veeder-root 208 liquid sensors in all three (3) STP sumps were found raised upon opening the sumps. I found alarm history and work orders from early to mid January for alarms in these sumps and water removal. All of the work orders seemed to address water removal only and not the root cause. Please investigate how and why these sensors were raised. Provide the CUPA with a written letter of the findings of this investigation and a solution to prevent this from happening in the future.

Violation Description:

Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.

Violations

Violation Date: 03/20/2018 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)

Violation Notes:

Returned to compliance on 03/21/2018. Facility does not have an approved Monitoring Plan. At time of inspection monitoring plan did not reflect the correct equipment. Interstitial sensor is a 409 not 407. The line leak detectors for diesel and 91 is VMI not Fe Petro. The 91 sensor was correct wirh Fe Pertro. Please update your monitoring plan and update in CERS. Thank you. Julia Barnes Please update monitoring plan.

Violation Description:

Failure to have an approved UST Monitoring Plan.

Violations

Violation Date: 03/12/2024 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.7 25299(a)(9) - California Health and Safety Code, Chapter 6.7, Section(s) 25299(a)(9)

Violation Notes:

Owner/Operator tampered with and/or disabled leak detection equipment in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak. Owner/Operator shall not disable or tamper with monitoring equipment. Repair/replace equipment so that it functions per manufacturer's specifications. Submit verification.

Violation Description:

Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak.

Violations

Violation Date: 10/25/2021 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.7 25291(a)(2) - California Health and Safety Code, Chapter 6.7, Section(s) 25291(a)(2)

Violation Notes:

Returned to compliance on 12/03/2021. UDCs 5/6 and 7/8 failed during the hydrostatic test for the SB989 test today. Addressed and retest within 60 days or by December 24, 2021.

Violation Description:

Failure to maintain secondary containment (e.g., failure of secondary containment testing).

<u>Violations</u>

Violation Date: 03/23/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2636(f)(1) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(1)

Violation Notes:

Returned to compliance on 03/23/2017. At time of inspection visual alarm was not working, contractor replaced light bulb. Corrected On Site. No Violation.

Violation Description:

Failure of the leak detection equipment to have an audible and visual alarm as required.

Violations

Violation Date: 03/12/2024 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: HSC 6.7 25291(b) - California Health and Safety Code, Chapter 6.7, Section(s) 25291(b)

Violation Notes:

Owner/Operator failed to design or construct a UST system with a monitoring system capable of detecting the entry of the hazardous substance into the secondary containment. UST system must be modified or repaired so that the monitoring system is capable of detecting the entry of the hazardous substance into the secondary containment. Submit verification.

Violation Description:

Failure of the UST system to be designed and constructed with a monitoring system capable of detecting the entry of the hazardous substance into the secondary containment.

Violations

Violation Date: 03/12/2024 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.7 25290.1(c)(3).25290.2(c)(3) - California Health and Safety Code, Chapter 6.7, Section(s) 25290.1(c)(3).

25290.2(c)(3)

Violation Notes:

87, 91 and diesel stp sumps had liquid Keep all secondary containment free of water.

Violation Description:

Failure to keep water out of the secondary containment of UST systems installed on or after July 1, 2003.

Violations

Violation Date: 03/15/2023 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.7 25299(a)(9) - California Health and Safety Code, Chapter 6.7, Section(s) 25299(a)(9)

Violation Notes:

Owner/Operator tampered with and/or disabled leak detection equipment in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak. Please refer to violation item #28, "Leak detection equipment properly installed, calibrated, operated, and maintained (TCR 9d)"

Violation Description:

Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak.

Violations

Violation Date: 03/15/2023 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(a)

Violation Notes:

Owner/Operator failed to install, maintain, or position leak detection equipment so that it is capable of detecting a leak at the earliest possible opportunity. Please refer to violation item #28, "Leak detection equipment properly installed, calibrated, operated, and maintained (TCR 9d)"

Violation Description:

Failure of leak detection equipment to be located such that equipment is capable of detecting a leak at the earliest possible opportunity.

Violations

Violation Date: 07/02/2019 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)

Violation Notes:

Returned to compliance on 07/12/2019. Facility does not have an approved Monitoring Plan. The monitoring plan has incorrect line leak detector equipment information for tank 1. Update Mechanical Line leak detector for tank 1 to reflect equipment. Should say VMI 99LD-2000 or Vaporless LD2000 (same as tank 3)

Violation Description:

Failure to have an approved UST Monitoring Plan.

Violations

Violation Date: 03/10/2022 Violation Source: CERS

Violation Program: HMRRP Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)

Violation Notes:

Returned to compliance on 09/06/2022. The employee training plan document in CERS and observed in the regulatory binder on site showed training, and associated training records specific to hazardous materials as required by the HMBP program, called "California On-site station Form" with an associated "Record." While the training materials were compliant, no completed forms or training records were available at the time of inspection. Please provide completed training forms and records for the staff at the site.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violations

Violation Date: 03/10/2022 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Notes:

Returned to compliance on 04/06/2022. 1. Paint that was dumped at site by the public was unlabeled in the secured area where the haz waste drums are stored. Mr. Manucheri stated he has been attempting to have the dumped paint picked up, however the haz waste hauler for the current liquid and solid waste would not take the dumped paint. 2. Accumulation start date not shown on 55 gallon liquid waste container. 1. The dumped paint must be labelled with appropriate haz waste labeling and disposed of in a timely manner. In order to comply with this violation, please provide photos of the items showing haz waste labeling. 2.The requirements were discussed with the store manager, Mr. Manucheri, and the date was added to the liquid haz waste drum during the inspection. Chris Rundell, crundell@marincounty.org / 415-419-7730

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 03/10/2022 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(a)

Violation Notes:

Returned to compliance on 03/10/2022. Leak sensor in supreme STP sump not in lowest position and contained a significant amount of water, which in the opinion of the testers and inspector would has caused an alarm. The testers on site removed the water and placed the sensor in the lowest position in the sump. Ensure that anyone performing maintenance or removing water from the STP sumps returns the sensor to the lowest position in the sensor sleeves in each sump. In order to close this violation and show compliance, please provide a copy of correspondence (email is fine) with DO company that this issue and these requirements have been communicated to the DO company on file in CERS. Chris Rundell, crundell@marincounty.org / 415-419-7730

Violation Description:

Failure of leak detection equipment to be located such that equipment is capable of detecting a leak at the earliest possible opportunity.

Violations

Violation Date: 03/12/2024 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2712(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(f)

Violation Notes:

Owner/Operator did not implement the corrections specified in the inspection report within 30 days of receiving an inspection report from either the CUPA or special inspector. Correct all deficiencies identified on the inspection report provided by the CUPA or special inspector within 30 days.

Violation Description:

Failure to implement the corrections specified in the inspection report within 30 days of receiving an inspection report from either the UPA or special inspector.

Violations

Violation Date: 03/12/2024 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)

Violation Notes:

Owner/Operator did not properly install, calibrate, operate and/or maintain leak detection equipment. Properly install, calibrate, operate and/or maintain leak detection equipment.

Violation Description:

Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.

Violations

Violation Date: 03/20/2018 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665

Violation Notes:

Returned to compliance on 03/20/2018. Owner/Operator did not install or maintain spill bucket which is liquid-tight, has a minimum capacity of five gallons, has a functional drain valve or other method for the removal of liquid from the spill bucket/spill container, or is resistant to galvanic corrosion.

Violation Description:

Failure to comply with one or more of the following:

Failure to install or maintain a liquid-tight spill bucket.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container.

Be resistant to galvanic corrosion.

Violations

Violation Date: 03/23/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665

Violation Notes:

Returned to compliance on 03/23/2017. 87 and 91 spill bucket both had ~3 quarters of a gallon of water. Contractor removed water. Corrected onsite. No violations.

Violation Description:

Failure to comply with one or more of the following:

Failure to install or maintain a liquid-tight spill bucket.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container.

Be resistant to galvanic corrosion.

Violations

Violation Date: 03/12/2024 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(a)

Violation Notes:

Owner/Operator failed to install, maintain, or position leak detection equipment so that it is capable of detecting a leak at the earliest possible opportunity. Install, maintain and position leak detection equipment so that it is capable of detecting a leak at the earliest possible opportunity.

Violation Description:

Failure of leak detection equipment to be located such that equipment is capable of detecting a leak at the earliest possible opportunity.

Violations

Violation Date: 03/12/2024 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2

Violation Notes:

Owner/Operator failed to meet one or more of the following spill container requirements: install or maintain spill container which is liquid-tight, has a minimum capacity of five gallons, has a functional drain valve or other method for the removal of liquid from the spill container, and is resistant to galvanic corrosion; did not perform tightness test at installation, every 12 months thereafter, or within 30 days after a repair; did not have tested using manufacturer's guidelines, industry codes, engineering standards, or method approved by PE, or was not tested by a certified UST service technician; or failed to maintain testing records for 36 months. Diesel bucket is not 5 gallons. Install or repair spill buckets to meet all of the listed requirements, have tightness tested using approved method, by certified UST service technician, and submit documentation to verify compliance. Maintain all testing records for 36 months. Must provide proof that diesel spill bucket is 5 gallons

Violation Description:

"Failure to meet one or more of the following requirements:

Install or maintain a liquid-tight spill container.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill container.

Be resistant to galvanic corrosion.

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Tested by a certified UST service technician.

Maintain records of spill containment testing for 36 months.

Violations

Violation Date: 03/23/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mamt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2715(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(f)

Violation Notes:

Returned to compliance on 04/07/2017. At time of inspection one employee had not been trained in UST operations and maintenance. Employee has been employed for over 30 days.

Violation Description:

Failure to have at least one employee present during operating hours that has been trained in the proper operation and maintenance of the UST system by a designated operator (DO).

Evaluations

Eval Date: 10/25/2021

Violations Found: No

Eval General Type:Compliance Evaluation InspectionEval Type:Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW
Eval Source: CERS

Eval Notes:

Eval Date: 12/03/2021

Violations Found: No

Eval General Type: Other/Unknown

Eval Type: Other, not routine, done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

UDCs 5/6 and 7/8 failed during the SB989 test on 10/25/2021. UDCs 5/6 and 7/8 passed today during the retest.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/12/2024 Violations Found: Yes

Eval Type: Compliance Evaluation Inspection
Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

FR expires 7/13/2024 Walton Engineering -Nicholas Janie Veeder -Root B49017 exp 9/28/25 ICC # 8712764 SB989 10/25/21 Vaporless #5096 expires 12/28/25 ICC #8712764 expires 12/13/2025 DHD unable to accept signature from store rep. *Tampering (raising) of Veeder-Root 208 liquid level sensors was observed in all three (3) turbine sumps. Please submit test results to this Agency within 30 days. On-site for monitoring system certification, spill bucket test, and routine UST inspection. The site has the following double-walled tanks: - diesel, 8k gal - 87, 12k gal - 91, 10k gal - Diesel, 10k gal Product piping for all tanks is double-walled and pressurized. UST system is monitored via TLS-350 panel. The site has the following sensors: Annular: - VR-409 (3) Fill/STP/Piping/UDC sumps - VR-208 (7) - FE Petro MLLD (3) The following were tested and passed: - Spill buckets (hydrostatic test) Diesel Failed- Does not h... [TRUNCATED: Refer to full Inspection Report]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 10/25/2021 **Violations Found:** No

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HMRRP Eval Source: CERS

Eval Notes:

Eval Date: 10/25/2021 Violations Found: Yes

Eval General Type: Other/Unknown

Eval Type: Other, not routine, done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

**** Notice to Comply **** Onsite for the SB989 test today 10/25/2021 Verified Juan Jauregui's certs during the inspection UDCs 5/6 and 7/8 failed during the hydrostatic test for the SB989 test today. Addressed and retest within 60 days or by December 24, 2021.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/10/2021

Violations Found: No

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Certifications for Max Hines were verified during the inspection. OPE inspection test was completed today.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/20/2018

Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

91 Spill Bucket failed at time of inspection, Corrected on site. Walton Engineering Curtis Carpenter ICC 8167865 Manager is Brian str05784@circlek.com; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/28/2016

Violations Found: No

Eval General Type:Compliance Evaluation InspectionEval Type:Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HMRRP
Eval Source: CERS

Eval Notes:

Eval Date: 03/15/2023 Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

*Tampering (raising) of Veeder-Root 208 liquid level sensors was observed in all three (3) turbine sumps. Please submit test results to this Agency within 30 days. On-site for monitoring system certification, spill bucket test, and routine UST inspection. The site has the following double-walled tanks: - diesel, 8k gal - 87, 12k gal - 91, 10k gal - Diesel, 10k gal Product piping for all tanks is double-walled and pressurized. UST system is monitored via TLS-350 panel. The site has the following sensors: Annular: - VR-409 (3) Fill/STP/Piping/UDC sumps - VR-208 (7) - FE Petro MLLD (3) Testing was conducted by Nick Janoe of Walton Engineering, Inc. Technician's certifications are: ICC: #8712764, Exp: 1/28/2024 VR #B49017, Exp: 11/12/2023 OPW #1793611, Exp: 2/21/2024 VMI: #5096, Exp: 12/30/2023 The following were tested and passed: - Spill buckets (hydrostatic test) - All liquid detection sensors (positive shut... [TRUNCATED: Refer to full Inspection Report]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Order No: 24072600476

Eval Date: 04/01/2014

Violations Found: No

Eval General Type:Compliance Evaluation InspectionEval Type:Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Eval Date: 04/14/2015

Violations Found: No

Eval General Type:Compliance Evaluation InspectionEval Type:Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Eval Date: 07/02/2019

Violations Found: Yes

Eval General Type: Other/Unknown

Eval Type: Other, not routine, done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Eval Date: 07/02/2019

Violations Found: No

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW Eval Source: CERS

Eval Notes:

Eval Date: 03/10/2022

Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HMRRP Eval Source: CERS

Eval Notes:

Store manager Mr. Maurice Manucheri hosted the inspection. Mr. Manucheri, was professional, transparent and helpful during the inspection. Overall the site is in good compliance, and please provide the requested documents for item #14 in order to close this violation. Chris Rundell, crundell@marincounty.org / 415-419-7730; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/10/2022 Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW
Eval Source: CERS

Eval Notes:

Store manager Mr. Maurice Manucheri hosted the inspection. Mr. Manucheri, was professional, transparent and helpful during the inspection. Overall the site is in good compliance, and please provide photos of proper haz waste labeling for the dumped paint. Chris Rundell, crundell@marincounty.org / 415-419-7730; Note: data in [EVAL Notes] field for some records is truncated from the source.

Order No: 24072600476

Eval Date: 03/28/2016

Violations Found: No

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST

Eval Source: CERS

Eval Notes:

Eval Date: 03/10/2022

Violations Found: Yes

Eval General Type:Compliance Evaluation InspectionEval Type:Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Walton Engineering on site for AMC, lead tester Maxwell Hines, all applicable certifications current at time of testing. UST annual permitting fees are delinquent, please pay these fees in order to return to compliance. All sensors on site match CERS monitoring plans and site map except site map shows a different MLLD than what is in CERS or on-site: please update site map to reflect this. Chris Rundell, crundell@marincounty.org / 415-419-7730; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/23/2017 Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Affiliations

Affil Type Desc: Property Owner
Entity Name: Circle K Stores Inc.

Entity Title:

Address: P.O. Box 52085, Attn: Environmental

 City:
 Phoenix

 State:
 AZ

 Country:
 United States

 Zip Code:
 85072

 Phone:
 (657) 262-2358

Affil Type Desc: UST Tank Owner Entity Name: Circle K Stores Inc.

Entity Title:

Address: P.O. Box 52085, Attn: Environmental

City: Phoenix State: AZ

 Country:
 United States

 Zip Code:
 85072

 Phone:
 (657) 262-2358

Affil Type Desc: UST Tank Operator Entity Name: Circle K Stores Inc.

Entity Title:

Address: P.O. Box 52085, Attn: Environmental

City: Phoenix State: AZ

Country: United States Zip Code: 85072

Phone: (657) 262-2358

Affil Type Desc: Facility Mailing Address

Entity Name: Mailing Address Entity Title:

Address: P.O. Box 52085, Attn: Environmental

City: Phoenix State: AZ

Country:

Order No: 24072600476

Zip Code:

Phone:

Affil Type Desc: Legal Owner Entity Name: Circle K Stores

Entity Title:

Address: P.O. Box 52085, Attn: Environmental

85072

City: Phoenix State: ΑZ **United States** Country: Zip Code: 85072 Phone: (657) 262-2358

Affil Type Desc: **CUPA** District Entity Name: Marin County CUPA

Entity Title:

Address: 1600 Los GamosSuite 210

City: San Rafael

State: CA

Country:

94903 Zip Code:

Phone: (415) 473-6647

Affil Type Desc: **Environmental Contact** Entity Name: Reyna mendez

Entity Title:

Address: P.O. Box 52085, Attn: Environmental Phoenix

City: State: ΑZ

Country:

Zip Code: 85072

Phone:

Affil Type Desc: Identification Signer Entity Name: Robert Velasco Entity Title: Agent For Circle K

Address: City: State: Country: Zip Code: Phone:

Parent Corporation Affil Type Desc: Circle K Stores Inc.

Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:

UST Property Owner Name Affil Type Desc:

Entity Name: Circle K Stores Inc.

Entity Title:

P.O. Box 52085, Attn: Environmental Address:

City: Phoenix State: ΑZ

Country: **United States** 85072 Zip Code:

Phone: (657) 262-2358

Affil Type Desc: Operator

Entity Name: Circle K Stores Inc.

Entity Title: Address: City: State:

Order No: 24072600476

Country: Zip Code:

Phone: (657) 262-2358

Affil Type Desc:UST Permit ApplicantEntity Name:Robert VelascoEntity Title:Agent For Circle K

Address: City: State: Country: Zip Code:

Phone: (661) 250-9300

Affil Type Desc: Document Preparer
Entity Name: Robert Velasco
Entity Title:
Address:
City:

State: Country: Zip Code: Phone:

 42
 6 of 10
 NW
 0.12 / 6.42 / 630.05
 Circle K Stores, Store #5784 981 Francisco Boulevard East San Rafael CA 94901

 Facility ID:
 21-000-300353
 Latitude:
 37.960938

 CERS ID:
 10031515
 Longitude:
 -122.504929

 County:
 Marin
 CalEnviroScrn 4 Pct:
 70-75%

Permitting Agency: Marin County Dept of Public Works, Waste Management Division

Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)

Note: Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.

Order No: 24072600476

gov/search

Tank Details

Epa Region: 9 Tank Closure Date:

No. of Closed UST: 0 Tank Configuration: Stand Alone Tank
No. of Inuse UST: Tank Contents: Regular Unleaded
No. of Oos UST: 0 Tank Cp Impr Curr: No

Owner Type:Non-GovernmentTank Cp Shutoff:YesTank ID No.:31/1/1994 12:00:00 AM

Tank Status: Confirmed/Updated Information Tank No of Compart:

Tank Type:Double WallTank Pc Constructn:FiberglassTank Alarms:NoTank Spill Bucket:YesTank Ball Float:NoTribal Lands:No

Tank Operator Name: Circle K Stores Inc.

Tank Operator Mail Address:P.O. Box 52085, Attn: Environmental

Tank Operator Mail City:PhoenixTank Operator Mail State:AZTank Operator Mail Zip:85072

Tank Owner Name: Circle K Stores Inc.

Tank Owner Mailing Address: P.O. Box 52085, Attn: Environmental

Tank Owner Mailing City: Phoenix Tank Owner Mailing State: ΑZ Tank Owner Mailing Zip: 85072 Tank Capacity Gallons: 12000 Tank Piping Construction: **Double Walled** Tank Piping Type: Pressure Tank Pw Piping Construction: Fiberglass Tank Sacrificial Anode: No

Tank Details

Epa Region: 9
No. of Closed UST: 0
No. of Inuse UST:

No. of Oos UST:

Owner Type: Non-Government

Tank ID No.:

Tank Status: Confirmed/Updated Information

Tank Type: Double Wall Tank Alarms: No Tank Ball Float: No

Tank Operator Name: Circle K Stores Inc.

Tank Operator Mail Address: P.O. Box 52085, Attn: Environmental

Tank Operator Mail City:PhoenixTank Operator Mail State:AZTank Operator Mail Zip:85072

Tank Owner Name: Circle K Stores Inc.

Tank Owner Mailing Address: P.O. Box 52085, Attn: Environmental

Tank Owner Mailing City:PhoenixTank Owner Mailing State:AZTank Owner Mailing Zip:85072Tank Capacity Gallons:10000Tank Piping Construction:Double WalledTank Piping Type:PressureTank Pw Piping Construction:FiberglassTank Sacrificial Anode:No

Tank Details

Epa Region: 9
No. of Closed UST: 0

No. of Inuse UST: No. of Oos UST:

Owner Type: Non-Government

Tank ID No.:

Tank Status: Confirmed/Updated Information

Tank Type: Double Wall Tank Alarms: No Tank Ball Float: No

Tank Operator Name: Circle K Stores Inc.

Tank Operator Mail Address: P.O. Box 52085, Attn: Environmental

Tank Operator Mail City:PhoenixTank Operator Mail State:AZTank Operator Mail Zip:85072

Tank Owner Name: Circle K Stores Inc.

Tank Owner Mailing Address: P.O. Box 52085, Attn: Environmental

Tank Owner Mailing City: Phoenix Tank Owner Mailing State: ΑZ Tank Owner Mailing Zip: 85072 Tank Capacity Gallons: 10000 Tank Piping Construction: Double Walled Tank Piping Type: Pressure Tank Pw Piping Construction: **Fiberglass** Tank Sacrificial Anode: No

Tank Closure Date:

Tank Configuration:Stand Alone TankTank Contents:Premium Unleaded

Tank Cp Impr Curr: No Tank Cp Shutoff: Yes

Tank Installatn Dt: 1/1/1994 12:00:00 AM

Tank No of Compart: 1

Tank Pc Constructn: Fiberglass Yes
Tribal Lands: No

Tank Closure Date:

Tank Configuration: Stand Alone Tank

Tank Contents: Diesel
Tank Cp Impr Curr: No
Tank Cp Shutoff: Yes

Tank Installatn Dt: 1/1/1994 12:00:00 AM

Tank No of Compart:

Tank Pc Constructn: Fiberglass Yes
Tribal Lands: No

42 7 of 10 NW 0.12 / 6.42 / MOBIL SERVICE STATION 630.05 2 981 FRANCISCO BL. SAN RAFAEL CA

CISCO BL.

Order No: 24072600476

MOBIL OIL CORPORATION
612 SO. FLOWER STREET
LOS ANGELES
CA
Facility State:
CA
Facility Zip:
94901

Owner State: CA
Owner Zip: 90017

Owner Name:

Owner Street:

Owner City:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
42	8 of10	NW	0.12 / 630.05	6.42 / 2	CIRCLE K STORES INC 2705784 981 FRANCISCO BLVD SAN RAFAEL CA 94901	RCRA NON GEN

EPA Handler ID:CAL000278578Gen Status Universe:No ReportContact Name:KRISTI HODGE

Contact Address: 255 E. RINCON ST. SUITE 100,, CORONA, CA, 92879,

Contact Phone No and Ext: 951-270-5153

Contact Email: KHODGE@CIRCLEK.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

 Receive Date:
 20040123

 Location Latitude:
 37.960707

 Location Longitude:
 -122.505106

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: No Commercial TSD: Nο Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: Nο Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20040123

Handler Name: CIRCLE K STORES INC 2705784

Source Type: Implementer

Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator Street No:

Type: Other Street 1: 255 E. RINCON ST. SUITE 100

Name: KRISTI HODGE Street 2:

Date Became Current:City:CORONADate Ended Current:State:CA

 Phone:
 951-270-5153
 Country:

 Source Type:
 Implementer
 Zip Code:
 92879

Owner/Operator Ind: Current Owner Street No:

Type: Other *Street 1:* 255 E RINCON ST STE 100

Order No: 24072600476

Name: CIRCLE K STORES INC Street 2:

Date Became Current: City: CORONA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Date Ended	Current:			State:		CA	
Phone:	951-27	70-5153		Country:			
Source Type	: Impler	menter		Zip Code	:	92879-0000	

NW CIRCLE K SERVICE STATION 9 of 10 0.12/ 6.42/ 42 **EMISSIONS** 630.05 2 #5784

PM10T:

PM10T:

Order No: 24072600476

981 FRANCISCO BLVD E SAN RAFAEL CA 94901

2017 Criteria Data

Facility ID: 111498 **CERR Code:**

Facility SIC Code: 5411 TOGT: .51385292 .51385292 CO: 21 ROGT:

Air Basin: SF COT: NOXT: District: BA COID: MRN SOXT: **BAY AREA AQMD** DISN: PMT: CHAPIS:

2017 Toxic Data

Facility ID: 111498 COID: MRN

Facility SIC Code: DISN: **BAY AREA AQMD** 5411

CO: 21 CHAPIS: Air Basin: SF **CERR Code:**

District: ВА

TS:

Health Risk Asmt: Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2018 Criteria Data

111498 **CERR Code:** Facility ID:

Facility SIC Code: 5541 TOGT: .51385292 CO: 21 ROGT: .51385292

Air Basin: SF COT: District: ВА NOXT: MRN COID: SOXT: DISN: **BAY AREA AQMD** PMT:

2018 Toxic Data

CHAPIS:

Facility ID: 111498 COID: MRN

Facility SIC Code: 5541 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

2019 Criteria Data

CO: 21 CHAPIS: SF **CERR Code:** Air Basin:

Facility ID: 111498 **ROGT:** .51385292

District: BA COT:

 Facility SIC Code:
 5541
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD

PM10T:

TOGT: .51385292

PMT:

2019 Toxic Data

CO: 21 DISN: BAY AREA AQMD

Air Basin:SFCHAPIS:Faccility ID:111498CERR Code:

District: BA TS:
Facility SIC Code: 5541 Health Risk Asmt:

Facility SIC Code: 5541
COID: MRN

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2020 Criteria Data

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

Facility ID: 111498 **ROGT:** .51385292

 District:
 BA
 COT:

 Facility SIC Code:
 5541
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD 51385292

TOGT: .5138529 **PMT: PM10T:**

2020 Toxic Data

CO: 21 DISN: BAY AREA AQMD

Air Basin:SFCHAPIS:Facility ID:111498CHERR Code:

District: BA TS:

Facility SIC Code: 5541 Health Risk Asmt: COID: MRN

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Toxic Data

Co: 21 DISN: BAY AREA AQMD

Air Basin:SFCHAPIS:Facility ID:111498Cerr Code:

District: BA TS: 1.6

Facility SIC Code: 5411 Health Risk Asmt:

COID: MRN Non-Cancer Chronic Haz Ind:

2021 Criteria Data

Non-Cancer Acute Haz Ind:

 Co:
 21
 CHAPIS:

 Air Basin:
 SF
 Cerr Code

 Air Basin:
 SF
 Cerr Code:

 Facility ID:
 111498
 ROGT:
 .51385292

Order No: 24072600476

DISN: BAY AREA AQMD
TOGT: .51385292

Map Key	Number Records		Distance (mi/ft)	Elev/Diff (ft)	Site	DB
PMT: PM10T:						
<u>42</u>	10 of10	NW	0.12 / 630.05	6.42/ 2	FRANCISCO UNICAL/ SS #7379 981 FRANCISCO BLVD SAN RAFAEL CA	UST SWEEPS
C C: BOE: Comp: Status: No of Tanks: Jurisdict: Agency: Phone:		A21-028-39591 39591 ACTIVE 3 CITY OF SAN RAFAEL CITY FIRE DEPARTMEN	Τ	D Filename Page No: County: State : Zip: Latitude: Longitude: Georesult:	38 MARIN CA 94901 37.960742	
Tank Details						
Tank ID: O Tank ID: SWRCB No: Removed: Installed: A Date: Capac: Tank Use:		000002 7379-RU-1 21-028-039591-000002 09-26-91 10000 M.V. FUEL		S Contain: Stg: Storage : Storag Typ P Contain: Content: ONA: D File Name	REG UNLEADED DOLLY GROVER	
Tank Details						
Tank ID: O Tank ID: SWRCB No: Removed: Installed: A Date: Capac: Tank Use:		000003 7379-RU-2 21-028-039591-000003 09-26-91 12000 M.V. FUEL		S Contain: Stg: Storage: Storag Typ: P Contain: Content: ONA: D File Name	REG UNLEADED DOLLY GROVER	
Tank Details						
Tank ID: O Tank ID: SWRCB No: Removed: Installed: A Date: Capac: Tank Use:		000001 7379-SU-1 21-028-039591-000001 09-26-91 10000 M.V. FUEL		S Contain: Stg: Storage : Storag Typ: P Contain: Content: ONA: D File Name	REG UNLEADED DOLLY GROVER	
<u>43</u>	1 of3	wsw	0.12/ 631.11		Marin Stat, Inc. 30 Golden Gate Drive, San Rafael CA	CUPA MARIN
Permit No: Type of Perm Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	it:	30-0230 Active 0 0 4 No		UFC: HWG Tons: HWG Recyd HWG Type Tiered: PBR HHW: Green: Facility Pho	cle: No Gen: SQG No No No	

Order No: 24072600476

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
43	2 of3	WSW	0.12 / 631.11	6.74 / 2	Marin Stat, Inc. 30 GOLDEN GATE DRIVE	CERS HAZ
					SAN RAFAEL CA 94901	

Site ID: 46545 Latitude: 37.951503 -122.498200 Longitude:

Regulated Programs

EI ID: 10031164 El Description: Hazardous Waste Generator 10031164

Violations

EI ID:

Violation Date: 08/11/2016 Violation Source: **CERS**

Marin County Dept of Public Works, Waste Violation Program: HW Violation Division:

El Description:

Mgmt, CUP

Chemical Storage Facilities

22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d) Citation:

Violation Notes:

Returned to compliance on 08/23/2016. White drum located outside appears to be stored onsite more than 180 days. Please have it removed and labeled correctly within 30 days. Please submit proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms.

(2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f).

(3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.

Violations

Violation Date: 08/11/2016 Violation Source: **CERS**

HMRRP Marin County Dept of Public Works, Waste Violation Program: Violation Division:

Mgmt, CUP

HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4) Citation:

Violation Notes:

Returned to compliance on 09/08/2016. Training program/recordkeeping was not available during inspection. Please provide proof of correction to Marin County CUPA of training program within 30 days indicating employees have been trained. Last training was done on 5/7/2013.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violations

Violation Date: 08/11/2016 Violation Source: **CFRS**

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Notes:

Returned to compliance on 08/29/2016. Facility did not have correct labeling. Place start accumulation date on black drum (55 gallon). Correct hazardous waste label for 1 additional drum, with the words "Empty." Provide proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Number of Direction Elev/Diff Site DΒ Map Key Distance (mi/ft) (ft)

Records

08/11/2016 **CERS** Violation Date: Violation Program: Violation Division: Marin County Dept of Public Works, Waste

Violation Source:

Mgmt, CUP

Order No: 24072600476

40 CFR 1 262.34(d)(5)(iii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(iii) Citation:

Violation Notes:

Violations

Returned to compliance on 09/08/2016. Employees were last trained on 5/7/2013; employees are required to be trained on a yearly basis. Please train employees and provide proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to ensure that all employees are thoroughly familiar with proper waste handling and emergency procedures, relevant to their responsibilities during normal facility operations and emergencies.

Evaluations

05/23/2023 Eval Date:

Violations Found:

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Marin County Dept of Public Works, Waste Mgmt, CUP Eval Division:

Eval Program: **HMRRP CERS** Eval Source:

Eval Notes:

On-site for a routine hazardous materials and Hazardous Materials Business Plan (HMBP) inspection. Consent to enter and conduct inspection activities was provided by Michael Scevola, General Manager. Verified the business activities, owner information, chemical inventory and site map. The emergency response plan and employee training records were available for review. Contact Michael Faryna with any questions or concerns, mfaryna@marincounty.org or +1-415-473-2027.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/29/2019

Violations Found: No

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW Eval Source: **CERS**

Eval Notes:

08/11/2016 Eval Date: Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Routine done by local agency Eval Type:

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW Eval Source: **CERS**

Eval Notes:

08/11/2016 Eval Date: Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Marin County Dept of Public Works, Waste Mgmt, CUP Eval Division:

HMRRP Eval Program: **CERS** Eval Source:

Eval Notes:

08/29/2019 Eval Date: Violations Found:

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HMRRP Eval Source: CERS

Eval Notes:

Eval Date: 05/23/2023

Violations Found: No

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW Eval Source: CERS

Eval Notes:

On-site for a routine hazardous waste inspection. Consent to enter and conduct inspection activities was provided by Michael Scevola, General Manager. Facility is a small quantity generator. Generator's ID number CAL000299349 is active. Waste streams are: phosphoric acid solution and ink. Walked the facility, including the dumpster area. Hazardous waste containers were observed closed, properly labeled, and no signs of unauthorized releases. Employees were reported to be trained and emergency contact phone numbers are posted. Hazardous waste receipts and manifests were available on site for review. Please contact Michael Faryna with any questions or concerns at mfaryna@marincounty.org or +1-415-473-2027.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Order No: 24072600476

Affiliations

Affil Type Desc: Parent Corporation Entity Name: Marin Stat, Inc.

Entity Title: Address: City: State: Country: Zip Code: Phone:

Affil Type Desc: Operator

Entity Name: Stephen D. Jones

Entity Name: Entity Title: Address: City: State: Country: Zip Code:

Phone: (415) 454-6620

Affil Type Desc: Legal Owner
Entity Name: Marin Stat, Inc

Entity Title:

Address: 30 Golden Gate Drive

City: San Rafael State: CA

Country: United States
Zip Code: 94901

Phone: (415) 454-6620

Affil Type Desc: Environmental Contact Entity Name: Environmental Contact

Entity Title:

Address: 30 Golden Gate Drive

City: San Rafael

State: CA Country:

Zip Code: 94901

Phone:

Affil Type Desc: Identification Signer

Entity Name: Stephen D. Jones
Entity Title: President

Address: City: State: Country: Zip Code: Phone:

Affil Type Desc: Document Preparer Entity Name: Greg Regoli

Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

aress: y:

Affil Type Desc: Property Owner
Entity Name: Stephen D. Jones
Entity Title:

Address: City:

30 Golden Gate Drive

City: San Rafael State: CA

Country: United States
Zip Code: 94901

Phone: (415) 454-6620

Affil Type Desc: CUPA District Entity Name: CUPA District Marin County CUPA

Entity Name: Entity Title: Address:

1600 Los GamosSuite 210

City: San Rafael

State: CA

Country:

Zip Code: 94903

Phone: (415) 473-6647

Affil Type Desc: Facility Mailing Address
Entity Name: Facility Mailing Address

Entity Title:

Address: 30 Golden Gate Drive

City: San Rafael

State: CA Country:

Zip Code:

Phone:

 43
 3 of3
 WSW
 0.12 / 6.74 / MARIN STAT INC
 RCRA

 631.11
 2
 30 GOLDEN GATE DR
 NON GEN

 SAN RAFAEL CA 94901-5407
 NON GEN

Order No: 24072600476

EPA Handler ID:CAL000299349Gen Status Universe:No ReportContact Name:STEPHEN JONES

Contact Address: 30 GOLDEN GATE DR,, SAN RAFAEL, CA, 94901,

94901

Contact Phone No and Ext: 415-454-6620

Contact Email: STEVE@MSILITHO.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

 Receive Date:
 20051012

 Location Latitude:
 37.957976

 Location Longitude:
 -122.505187

Distance Number of Direction Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: Nο

Hazardous Waste Handler Details

Sequence No:

20051012 Receive Date: MARIN STAT INC Handler Name: Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

Other Street 1: 30 GOLDEN GATE DR Type:

Name: STEPHEN JONES Street 2: City:

SAN RAFAEL Date Became Current: Date Ended Current: State: CA

Phone: 415-454-6620 Country:

Source Type: Implementer Zip Code: 94901-5407

Owner/Operator Ind: **Current Operator** Street No:

30 GOLDEN GATE DR Type: Other Street 1:

STEPHEN JONES Name: Street 2:

SAN RAFAEL Date Became Current: City:

Date Ended Current: State: CA

Phone: 415-454-6620 Country:

Source Type: Implementer Zip Code: 94901

44 1 of3 SW 0.12/ 6.15/ TREADWELL PROPERTIES LUST 631.17 60 GOLDEN GATE DR SAN RAFAEL CA 94901

Global ID: T0604100135 Case Type (DL): LUST Cleanup Site

LUST CLEANUP SITE Oil Field (SRCH): Site Facility Type: LUST CLEANUP SITE Oil Field Oper (SRCH): Site Fac Type (SRCH):

Status: Census Tract (SRCH): 6041112202 Status (SRCH): Latitude (DL): **COMPLETED - CASE CLOSED** 37.957102

Status (DL): Completed - Case Closed Longitude (DL): -122.504649 Status Date (DL): 1/2/2007 RWQCB Region (DL): SAN FRANCISCO BAY RWQCB (REGION 2)

COMPLETED - CASE CLOSED Cleanup Status: Site Facility Name (SRCH): TREADWELL PROPERTIES

Order No: 24072600476

60 GOLDEN GATE DR

Address (SRCH):

City (SRCH): SAN RAFAEL
Zip (SRCH): 94901
County (SRCH): MARIN
Street No (DL): 60

Street Name (DL):GOLDEN GATE DRCity (DL):SAN RAFAELZip (DL):94901County (DL):Marin

State (DL):CABusiness Name (DL):TREADWELL PROPERTIESSite Facility Name:TREADWELL PROPERTIESAddress :60 GOLDEN GATE DR

 City:
 SAN RAFAEL

 Zip:
 94901

 County:
 MARIN

Report Source: GeoTracker Search Results (SRCH);GeoTracker Sites Data Download (DL);GeoTracker Search Results Report

GeoTracker Sites Data Download - Site Details

CUF Case:

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Worker:

Local Agency:
RB Case No: 21-0143

Local Case No:

File Location:
Potential COC:
Gasoline

Potential Media of Concern: Other Groundwater (uses other than drinking water)

Begin Date: 6/13/1986
How Discovered: Tank Closure

How Discovered Description:

Stop Method: Stop Description:

Calwater Watershed Name: Bay Bridges - San Rafael (203.20)

DWR GW Subbasin Name: San Rafael Valley (2-029)

Disadvantaged Community:

CalEnvScreen Score:

Coordinate Source: Google Geocode
Discharge Cause: Unknown
Discharge Source: Other
EPA Region: 9

Leak Reported Dt: 1986-06-13 00:00:00

Military DoD Site: No.

No Further Action Dt: 2007-01-02 00:00:00

Qty Risd Gallons:

Facility Project Sub Type:

Calenviroscreen 3 Score: 56-60% Calenviroscreen 4 Score: 70-75%

Site History:

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed

Status Date: 1/2/2007

Status: Open - Site Assessment

Status Date: 12/19/1994

Status: Open - Case Begin Date

Status Date: 6/13/1986

GeoTracker Search - Regulatory Profile (as of June 5, 2024)

Site Facility Name: TREADWELL PROPERTIES
Site Facility Type: LUST CLEANUP SITE

Order No: 24072600476

Cleanup Status: COMPLETED - CASE CLOSED

Address: 60 GOLDEN GATE DR

 City:
 SAN RAFAEL

 Zip:
 94901

 County:
 MARIN

Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0604100135

Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 1/2/2007

Project Status:

Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0604100135&tabname=regulatoryhistory

Potential COC: GASOLINE

Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)

File Location:

User Defined Beneficial Use:

Designated Beneficial Use:MUN, AGR, IND, PROCDWR GW Sub Basin:San Rafael Valley (2-029)Calwater Watershed Name:Bay Bridges - San Rafael (203.20)

Post Closure Site Management:

Future Land Use:

Cleanup Oversight Agencies: SA

SAN FRANCISCO BAY RWQCB (REGION 2) (LEAD) - CASE #: 21-0143

CUF Claim No: CUF Priority Assig: CUF Amount Paid: WDR Place Type: WDR File No: WDR Order No:

Project Oversight Agencies:

Facility Type: Composting Method:

Grndwtr Monitoring Frequency:

Designated Beneficial Use

Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply

Order No: 24072600476

Desc:

Site History:

No site history available

GeoTracker Search - Cleanup Status History (as of June 5, 2024)

Status: Completed - Case Closed

Date: 1/2/2007

Status: Open - Site Assessment

Date: 12/19/1994

Status: Open - Case Begin Date

Date: 6/13/1986

GeoTracker Search - Regulatory Activities (as of June 5, 2024)

Action Type:Other Regulatory ActionsAction:Closure/No Further Action Letter

 Action Date:
 1/2/2007

 Received Issue Date:
 1/2/2007

Doc Link:

Title Description Comments:

Case closed

Action Type:Other Regulatory ActionsAction:Site Visit / Inspection / Sampling

 Action Date:
 12/28/2006

 Received Issue Date:
 12/28/2006

Doc Link:

Title Description Comments:

Could find no evidence of old well, has been paved, site workers didn't know of well.

Action Type:Leak ActionAction:Leak DiscoveryAction Date:6/13/1986

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak StoppedAction Date:6/13/1986

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak ReportedAction Date:6/13/1986

Received Issue Date:

Doc Link:

Title Description Comments:

GeoTracker Search - Documents (as of June 5, 2024)

Document Type: Site Documents **Document Date:** 1/2/2007

Type: LETTER Submitted:

Submitted By: RALPH LAMBERT (REGULATOR)

Title: CASE CLOSURE

Title Link: https://geotracker.waterboards.ca.gov/site_documents/5737232804/21%2D0143%20case%20closure%2Epdf

 $\frac{44}{2}$ 2 of 3 SW 0.12 / 6.15 / VIACOM CABLEVISION HHSS

SAN RAFAEL CA 94901

County: Marin

Tank Details Microfiche: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002944b.pdf

44 3 of 3 SW 0.12/ 6.15/ VIACOM CABLEVISION HIST TANK 631.17 2 60 GOLDEN GATE DRIVE

SAN RAFAEL CA

 Owner Name:
 VIACOM CABLEVISION
 No of Containers:
 1

 Owner Street:
 60 GOLDEN GATE DRIVE
 County:
 MARIN

 Owner City:
 SAN RAFAEL
 Facility State:
 CA

 Owner State:
 CA
 Facility Zip:
 94901

Owner Zip: 94901

45 1 of 2 W 0.12 / 12.13 / AutoZone #5647 CERS HAZ 645.77 8 28 BELLAM BLVD

Order No: 24072600476

SAN RAFAEL CA 94901
Site ID: 705983

 Site ib.
 703303

 Latitude:
 37.958940

 Longitude:
 -122.506370

Regulated Programs

El ID: 10940080 El Description: Chemical Storage Facilities

EI ID: 10940080 EI Description: Hazardous Waste Generator

Affiliations

Affil Type Desc: Legal Owner Entity Name: Legal Owner AutoZone Inc

Entity Title:

 Address:
 123 S. Front St.

 City:
 Memphis

 State:
 TN

 Country:
 United States

 Zip Code:
 38103

 Phone:
 (901) 495-6500

Affil Type Desc: Document Preparer Entity Name: Deborah Williams

Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Facility Mailing Address

Entity Title:

Address: 123 South Front Street, Dept. 8190

City: Memphis State: TN

Country:

Zip Code: 38103

Phone:

Affil Type Desc: Identification Signer
Entity Name: Deborah Williams

Entity Title: Environmental Coordinator

Address: City: State: Country: Zip Code: Phone:

Affil Type Desc: Environmental Contact Entity Name: Andrew Beaven

Entity Name: Andrew Beaver Entity Title:

Address: 123 South Front Street, Dept. 8190
City: Memphis

State: Memp

Country:

Zip Code: 38103

Phone:

Affil Type Desc: CUPA District
Entity Name: Marin County CUPA

Entity Title:
Address: 1600 Los GamosSuite 210

City: San Rafael

State: CA

Country: 94903

Phone: (415) 473-6647

Affil Type Desc: Operator Entity Name: Autozone

Entity Title: Address:

Order No: 24072600476

City: State: Country: Zip Code:

Phone: (901) 495-6500

Affil Type Desc: Parent Corporation Entity Name: Auto Zone

Entity Name.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Property Owner

Entity Name: Chelsea Pacific Holdings, LP

Entity Title:

Address: 1100 Mar West Street, Suite D

 City:
 Tiburon

 State:
 CA

 Country:
 United States

 Zip Code:
 94920

 Phone:
 (415) 937-5370

45 2 of2 W 0.12 / 12.13 / AUTOZONE #5647 645.77 8 28 BELLAM BLVD

SAN RAFAEL CA 94901

RCRA

Order No: 24072600476

NON GEN

EPA Handler ID: CAL000481200
Gen Status Universe: No Report

Contact Name: DEBORAH WILLIAMS

Contact Address: 123 S FRONT ST DEPT 8190, , MEMPHIS, TN, 38103,

Contact Phone No and Ext: 901-495-7129

Contact Email: DEBORAH.J.WILLIAMS@AUTOZONE.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Receive Date: 20231013

Location Latitude: Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: Nο Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: No

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20231013 AUTOZONE #5647 Handler Name: Source Type: Implementer

Federal Waste Generator Code:

1 of1

Not a Generator, Verified Generator Code Description:

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

123 S FRONT ST Type: Other Street 1:

Name: **AUTOZONE INC** Street 2:

Date Became Current: City: **MEMPHIS** Date Ended Current: State: ΤN

901-495-6500 Phone: Country:

38103 Source Type: Implementer Zip Code:

Owner/Operator Ind: **Current Operator** Street No:

SW

123 S FRONT ST DEPT 8190 Type: Other Street 1: Name: **DEBORAH WILLIAMS** Street 2:

MEMPHIS Date Became Current: City:

Date Ended Current: State: TN

901-495-7129 Country: Phone:

Implementer Zip Code: 38103 Source Type:

0.12/

5.37/ Galaxy Dessert 46 **CUPA MARIN** 651.96 40 Golden Gate Drive, San Rafael

UFC: No Permit No: 30-0491 Type of Permit: **HWG Tons:** 0.0

Cross Ref: HWG Recycle: No

Status: Inactive HWG Type Gen: US Tanks: Tiered: No AG Tanks: PBR HHW: 0 No

HMBP: 0 Green: No Cal ARP: No Facility Phone No: (415) 459-3537

1 of1 NNW 0.13/ 4.04/ URBAN PAINTING INC. 47 **RCRA** 675.89 -1 40 LISBON ST **NON GEN**

SAN RAFAEL CA 94901-0000

Order No: 24072600476

EPA Handler ID: CAL000205541 Gen Status Universe: No Report

Contact Name: PATRICK COURTNEY

Contact Address: 40 LISBON ST,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-609-9481

Contact Email: PAT.COURTNEY@URBANCO.COM

Contact Country:

County Name: MARIN EPA Region:

Land Type:

Receive Date: 20010118 Location Latitude: 37.961552 Location Longitude: -122.504102

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: Nο **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer:

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20010118

URBAN PAINTING INC. Handler Name:

Implementer Source Type:

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Operator** Street No:

40 LISBON ST Type: Street 1:

PATRICK COURTNEY Name: Street 2:

Date Became Current: SAN RAFAEL City:

Date Ended Current: State: CA

415-609-9481 Phone: Country:

Source Type: Implementer Zip Code: 94901

Current Owner Owner/Operator Ind: Street No:

40 LISBON ST Type: Other Street 1:

Name: URBAN PAINTING INC. Street 2:

Date Became Current: City: SAN RAFAEL CA

Date Ended Current: State: 415-485-1130 Phone: Country:

94901-0000 Source Type: Implementer Zip Code:

0.14/ 48 1 of6 N 4.68/ F. Lofrano & Son, Inc. **CUPA MARIN** 763.30 21 Belvedere Street, San Rafael

CA

Permit No: 30-0293 UFC:

No Type of Permit: **HWG Tons:** 0.0 Cross Ref: HWG Recycle: No

CESQG Status: Active HWG Type Gen: US Tanks: Tiered: No AG Tanks: PBR HHW: 0 No HMBP: 15 Green: No

(415) 453-1318 Cal ARP: No Facility Phone No:

N 0.14/ 4.68/ L LOFRANO AND SON INC 48 2 of6 **EMISSIONS** 763.30 0 21 BELVEDERE STREET

SAN RAFAEL CA 94901

Order No: 24072600476

1996 Criteria Data

3758 CERR Code: Facility ID:

Facility SIC Code: 7532 TOGT: .3368 CO: ROGT: 21 Air Basin: SF COT:

District: ВА NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT:

CHAPIS: PM10T:

1996 Toxic Data

Facility ID: 3758 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: BA TS.

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

1997 Criteria Data

Facility ID: 3758 **CERR Code:**

Facility SIC Code: 7532 TOGT: .4 CO: 21 ROGT: .3368

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT: PMT:

BAY AREA AQMD DISN: CHAPIS:

1997 Toxic Data

3758 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

PM10T:

Order No: 24072600476

CO: 21 CHAPIS: Air Basin: SF CERR Code:

District: ВА

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind:

Non-Cancer Acute Haz Ind:

1998 Criteria Data

Facility ID: 3758 **CERR Code:**

Facility SIC Code: 7532 TOGT: .3 .2736 CO: 21 ROGT:

Air Basin: SF COT: District: BA NOXT: SOXT: MRN COID: DISN: **BAY AREA AQMD** PMT: PM10T:

CHAPIS:

1998 Toxic Data

Facility ID: 3758 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
CO: Air Basin: District: TS: Health Risk				CHAPIS: CERR Co			
	Chronic Haz Ind: Acute Haz Ind:						
1999 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID:	3758 7532 21 SF BA MRN			CERR Co TOGT: ROGT: COT: NOXT: SOXT:	ode:	.343 .298349	
DISN: CHAPIS:		REA AQMD		PMT: PM10T:			
<u>1999 Toxic L</u>	<u>Data</u>						
	21 SF BA			COID: DISN: CHAPIS: CERR Co	ode:	MRN BAY AREA AQMD	
2000 Criteria	<u>n Data</u>						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	REA AQMD		CERR Co TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.343 .3	
2000 Toxic L	<u>Data</u>						
	21 SF BA			COID: DISN: CHAPIS: CERR Co	ode:	MRN BAY AREA AQMD	
2001 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN:	21 SF BA MRN	REA AQMD		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT:	ode:	.56 .45	

Order No: 24072600476

Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

CHAPIS: PM10T:

2001 Toxic Data

Facility ID: 3758 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

 District:
 BA

TS.

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2002 Criteria Data

Facility ID: 3758 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .644

 CO:
 21
 ROGT:
 .5191342

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

 CHAPIS:
 PM10T:

2002 Toxic Data

Facility ID: 3758 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

BA

2003 Criteria Data

Facility ID: 3758 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .644

 CO:
 21
 ROGT:
 .52

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

2003 Toxic Data

CHAPIS:

Facility ID: 3758 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

PM10T:

Order No: 24072600476

CO: 21 CHAPIS:
Air Basin: SF CERR Code:

District:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2004 Criteria Data

Map Key	Numbe Record		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	3758 7532 21 SF BA MRN BAY ARE	ea aqmd		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.644 .5191342	
2004 Toxic D	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk A Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co		MRN BAY AREA AQMD	
2005 Criteria	Data							
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	3758 7532 21 SF BA MRN BAY ARE	ea aqmd		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.414 .3635748	
2005 Toxic D	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk A Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co		MRN BAY AREA AQMD	
2006 Criteria	Data							
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	3758 7532 21 SF BA MRN BAY ARE	ea aqmd		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.414 .3635748	
2006 Toxic D	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS:	Code:	3758 7532 21 SF BA			COID: DISN: CHAPIS: CERR Co		MRN BAY AREA AQMD	

Order No: 24072600476

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2007 Criteria Data

CERR Code: Facility ID: 3758

Facility SIC Code: 7532 TOGT: .414 .3635748 CO: 21

ROGT: Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT:

CHAPIS: PM10T:

2007 Toxic Data

3758 COID: MRN Facility ID:

Facility SIC Code: DISN: **BAY AREA AQMD** 7532

CO: 21 CHAPIS: Air Basin: SF **CERR Code:**

District: BA TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2008 Criteria Data

Facility ID: 3758 **CERR Code:**

Facility SIC Code: 7532 TOGT: .414 CO: 21 ROGT: .3635748 Air Basin: SF COT:

District: ВΑ NOXT: COID: MRN SOXT:

DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

2008 Toxic Data

3758 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: 21 CHAPIS: SF Air Basin: **CERR Code:**

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

ВА

BA

2010 Toxic Data

Facility ID: 3758 COID: MRN

Facility SIC Code: DISN: **BAY AREA AQMD** 7532

Order No: 24072600476

CHAPIS: CO: 21 Air Basin: SF **CERR Code:** District:

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

Map Key	Numbe Recore		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
2011 Toxic D	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin:	Code:	3758 7532 21 SF			COID: DISN: CHAPIS: CERR C		MRN BAY AREA AQMD	
District: TS: Health Risk A Non-Cancer	Chronic F							
Non-Cancer		z ina:						
<u> 2012 Toxic D</u>	<u>vala</u>							
Facility ID:	0-4	3758			COID:		MRN	
Facility SIC (CO:	Coae:	7532 21			DISN: CHAPIS:	•	BAY AREA AQMD	
CO: Air Basin:		SF			CERR C			
District: TS:		BA			CERN C	oue.		
Health Risk A Non-Cancer Non-Cancer	Chronic F							
<u> 2013 Toxic D</u>	<u>Data</u>							
Facility ID:		3758			COID:		MRN	
Facility SIC (Code:	7532			DISN:		BAY AREA AQMD	
CO:		21			CHAPIS:	•		
Air Basin:		SF			CERR C	ode:		
District:		BA						
TS:								
Health Risk A								
Non-Cancer Non-Cancer .								
<u>48</u>	3 of6		N	0.14 / 763.30	4.68 / 0	21 BELVE	ITO BODY DERE STREET AEL CA 94901	EMISSIÓN
1990 Criteria	Data							
Facility ID:		3758			CERR C	ode:		
Facility SIC (Code:	7532			TOGT:		1.3	
co:		21			ROGT:		1.124	
Air Basin:		SF			COT:			
District:		BA			NOXT:			
COID:		MRN	REA AQMD		SOXT:			
DISN: CHAPIS:		DATAF	NEA AQIVID		PMT: PM10T:			
<u>1990 Toxic D</u>	<u>Data</u>							
Facility ID:	Codo	3758			COID:		MRN BAY ABEA AOMD	
Facility SIC (CO:	coae:	7532 21			DISN: CHAPIS:		BAY AREA AQMD	
CO: Air Basin:		SF			CHAPIS:			
Air basin: District: TS:		BA			CENN C	Jue.		
15: Health Risk A Non-Cancer		łaz Ind·						
Non-Cancer Non-Cancer								

Order No: 24072600476

Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

1993 Criteria Data

Facility ID: 3758 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .7

 CO:
 21
 ROGT:
 .644

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

 CHAPIS:
 PM10T:

1993 Toxic Data

Facility ID: 3758 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District:

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

 48
 4 of6
 N
 0.14/
 4.68/
 F LOFRANO & SON INC
 RCRA

 763.30
 0
 21 BELVEDERE ST
 NON GEN

 SAN RAFAEL CA 94901
 NON GEN

EPA Handler ID:CAL000135851Gen Status Universe:No ReportContact Name:GREG KOHS

BA

Contact Address: 21 BELVEDERE ST,, SAN RAFAEL, CA, 94901, US

Contact Phone No and Ext: 415-415-6800

 Contact Email:
 US

 Contact Country:
 US

 County Name:
 MARIN

 EPA Region:
 09

 Land Type:
 Other

 Receive Date:
 20230613

 Location Latitude:
 37.961915

 Location Longitude:
 -122.503175

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

Order No: 24072600476

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No

Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

19970617 Receive Date:

F LOFRANO & SON INC Handler Name:

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20230613

Handler Name: F LOFRANO & SON INC

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

Street 1: 3355 17TH ST Type:

F LOFRANO & SON INC Street 2: Name: Date Became Current: City:

SAN FRANCISCO Date Ended Current: State: CA

415-865-8400 US Phone: Country: Implementer Zip Code: 94110 Source Type:

Owner/Operator Ind: **Current Operator** Street No:

1745 DIVISADERO ST Type: Street 1:

JAMES LOFRANO Name: Street 2:

Date Became Current: SAN FRANCISCO City:

Date Ended Current: State: CA

415-865-8414 Phone: Country: Implementer Zip Code: 94115 Source Type:

Current Operator Owner/Operator Ind: Street No:

Type: Street 1: 3355 17TH ST

Name: F LOFRANO & SON INC Street 2:

Date Became Current: City: SAN FRANCISCO

Date Ended Current: State: CA 415-865-8400 US Phone: Country:

Implementer Source Type: Zip Code: 94110

Owner/Operator Ind: **Current Owner** Street No:

3355 17TH ST Type: Other Street 1: F. LOFRANO & SON INC Name: Street 2:

SAN FRANCISCO Date Became Current: City:

Date Ended Current: State:

415-865-8400 Country: Phone:

Implementer 94110-0000 Source Type: Zip Code:

Historical Handler Details

Receive Dt: 19970617

Generator Code Description: Not a Generator, Verified F LOFRANO & SON INC Handler Name:

0.14/ N F. LOFRANO & SON INC. 48 5 of6 4.68/ **EMISSIONS** 763.30 21 BELVEDERE ST

Order No: 24072600476

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

2017 Toxic Data

COID: MRN Facility ID: 3758

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

21 CHAPIS: CO: Air Basin: SF **CERR Code:** BA

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Toxic Data

Co: 21 DISN: **BAY AREA AQMD**

SF Air Basin: CHAPIS: Cerr Code: Facility ID: 3758 District: BA TS:

Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Criteria Data

Co: 21 CHAPIS:

Air Basin: SF Cerr Code: Facility ID: 3758 ROGT: .1516525339395

District: BA COT: Facility SIC Code: 7532 NOXT: CO ID: MRN SOXT:

DISN: **BAY AREA AQMD** TOGT: .153510005

PMT: PM10T:

0.14/ F. LOFRANO AND SON INC 6 of6 Ν 4.68/ 48

EMISSIONS 763.30 21 BELVEDERE ST SAN RAFAEL CA 94901

PM10T:

2018 Criteria Data

Facility ID: 3758 CERR Code:

Facility SIC Code: 7532 TOGT: .104400004 CO: .1031367639516 21 ROGT:

Air Basin: SF COT: District: BA NOXT: MRN COID: SOXT: DISN: **BAY AREA AQMD** PMT:

2018 Toxic Data

CHAPIS:

Facility ID: 3758 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

CO: CHAPIS: 21 Air Basin:

SF **CERR Code:** ВА District:

TS:

Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2019 Criteria Data

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

Facility ID: 3758 **ROGT:** .1031367639516

 District:
 BA
 COT:

 Facility SIC Code:
 7532
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD

PM10T:

TOGT: .104400004

РМТ:

2019 Toxic Data

CO: 21 DISN: BAY AREA AQMD

Air Basin:SFCHAPIS:Faccility ID:3758CERR Code:

District: BA TS:
Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2020 Criteria Data

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

Facility ID: 3758 **ROGT:** .1031367639516

 District:
 BA
 COT:

 Facility SIC Code:
 7532
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD TOGT: .104400004

PMT: PM10T:

2020 Toxic Data

CO: 21 DISN: BAY AREA AQMD

Air Basin:SFCHAPIS:Facility ID:3758CHERR Code:

District: BA TS:

Facility SIC Code: 7532 Health Risk Asmt: COID: MRN

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

49 1 of 10 NNW 0.15 / 4.11 / VACATED TENANT SPACE 794.44 0 OWNED BY CAZADOR

INVESTMENT CO 50 LISBON ST UNIT 6 SAN RAFAEL CA 94901 **RCRA**

Order No: 24072600476

NON GEN

EPA Handler ID: CAP000190124
Gen Status Universe: No Report
Contact Name: MECH CAROLEE

Contact Address: 70 MITCHELL BLVD , CAZADOR INVESTMENT CO NO 102 , SAN RAFAEL , CA, 94903 , US

Contact Phone No and Ext: 415-479-9890

Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

Contact Email: CAROLEE@HOEYCOMPANY.COM

Contact Country:
County Name:
MARIN
EPA Region:
U9
Land Type:
Receive Date:
US
MARIN
Private
20080519

Location Latitude: Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: Nο Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: Nο **Underground Injection Activity:** Nο Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: Nο Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: Nο Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20080211

Handler Name: VACATED TENANT SPACE OWNED BY CAZADOR INVESTMENT CO

Source Type: Temporary

Federal Waste Generator Code:

Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D00

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F00

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE,

TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F00

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

Order No: 24072600476

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003

Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL

BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004. AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

F004 Hazardous Waste Code:

Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND

NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVÉ NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT

SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code:

Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON

DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT

SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20080519

Handler Name: VACATED TENANT SPACE OWNED BY CAZADOR INVESTMENT CO

Source Type: Notification

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Operator** Street No: Type: Private Street 1: Name: CAZADOR INVESTMENT CO Street 2: Date Became Current: 20071206 City: Date Ended Current: State:

F005

Phone: Country: Source Type: Temporary Zip Code:

Owner/Operator Ind: **Current Operator** Street No: Private Street 1: Type: CAZADOR INVESTMENT CO Name: Street 2:

Date Became Current: 20071206 City: Date Ended Current: State: Country: Phone:

Source Type: Notification

Owner/Operator Ind: **Current Owner** Street No:

Private Street 1: 70 MITCHELL BLVD Type:

Zip Code:

Order No: 24072600476

Name: CAZADOR INVESTMENT CO Street 2: **STE 102** SAN RAFAEL 20040615 Date Became Current: City: Date Ended Current:

State: CA Country: US Source Type: Notification 94903 Zip Code:

Owner/Operator Ind: **Current Owner** Street No:

70 MITCHELL BLVD Type: Private Street 1:

CAZADOR INVESTMENT CO Name: Street 2: STE 102 SAN RAFAEL Date Became Current: 20040615 City:

Date Ended Current: State: CA Phone: Country: US

Phone:

Historical Handler Details

20080211 Receive Dt:

Generator Code Description: Small Quantity Generator

Handler Name: VACATED TENANT SPACE OWNED BY CAZADOR INVESTMENT CO

49 2 of 10 NNW 0.15/ 4.11/ Berry GT Enterprises **CUPA MARIN** 50 Lisbon Street, Suite 3, San 794.44 n

UFC:

Rafael CA

No

Order No: 24072600476

30-0352 Permit No:

Type of Permit:

Status: US Tanks: AG Tanks: 0 HMBP: 0

HWG Tons: 0.0 Cross Ref: HWG Recycle: No **CESQG** Active HWG Type Gen:

Tiered: No PBR HHW: No Green: No

Cal ARP: Facility Phone No: (415) 457-9262 No

NNW 49 3 of 10 0.15/ 4.11/ Parker Automotive **CUPA MARIN** 794.44 50 Lisbon Street, Suite 1, San

Rafael CA

Permit No: 30-0161 UFC: No Type of Permit: **HWG Tons:** 0.0 Cross Ref: HWG Recycle: No

Status: HWG Type Gen: **CESQG** Active US Tanks: Tiered: 0 No AG Tanks: 0 PBR HHW: No HMBP: 0 Green: Nο

Cal ARP: No Facility Phone No: (415) 453-6603

4 of 10 NNW 0.15/ **GOOD BODY** 49 4.11/ **EMISSIONS** 794.44 50 LISBON # 5 0

SAN RAFAEL CA 94901

1996 Criteria Data

Facility ID: 6926 **CERR Code:**

Facility SIC Code: 7532 TOGT: .2 .1968 CO: 21 ROGT:

Air Basin: SF COT: District: BA NOXT: MRN SOXT: COID: DISN: **BAY AREA AQMD** PMT: PM10T: CHAPIS:

BA

1996 Toxic Data

Facility ID: 6926 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

1997 Criteria Data

6926 CERR Code: Facility ID:

Facility SIC Code: 7532 TOGT: .2 .1968 ROGT: CO: 21

Air Basin: SF COT: District: ВА NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

1997 Toxic Data

6926 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: BA TS.

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

1998 Toxic Data

Facility ID: 6926 COID: MRN

DISN: **BAY AREA AQMD** Facility SIC Code: 7532

CO: CHAPIS: 21 Air Basin: SF CERR Code: District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

GOOD BODY NNW 0.15/ 4.11/ 49 5 of 10 **EMISSIONS** 50 LISBON, #5 794.44 0

SAN RAFAEL CA 94901

Order No: 24072600476

1999 Toxic Data

Facility ID: 6926 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

2000 Toxic Data

Facility ID: 6926 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: SF **CERR Code:** District:

Health Risk Asmt:

Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

Non-Cancer Chronic Haz Ind:

Non-Cancer Acute Haz Ind:

2001 Toxic Data

Facility ID: 6926 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: BA

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind:

Non-Cancer Acute Haz Ind:

2003 Criteria Data

Facility ID: 6926 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .199

 CO:
 21
 ROGT:
 .17

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DIGN:
 BAY AREA AGAID
 BMT:

DISN: BAY AREA AQMD PMT: CHAPIS: PM10T:

2003 Toxic Data

Facility ID: 6926 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

 District:
 BA

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2004 Criteria Data

Facility ID: 6926 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .199

 CO:
 21
 ROGT:
 .173419

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

COID: MRN SOXT:
DISN: BAY AREA AQMD PMT:
CHAPIS: PM10T:

2004 Toxic Data

Facility ID: 6926 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

Order No: 24072600476

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2005 Criteria Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	2		CERR COT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.199 .173419	
2005 Toxic I	<u>Data</u>						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co		MRN BAY AREA AQMD	
2006 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	2		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.267 .2265276	
2006 Toxic I	<u>Data</u>						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co		MRN BAY AREA AQMD	
2007 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	2		CERR COTOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.267 .2265276	
2007 Toxic I	<u>Data</u>						
Facility ID: Facility SIC CO: Air Basin: District:	6926 Code: 7532 21 SF BA			COID: DISN: CHAPIS: CERR Co		MRN BAY AREA AQMD	

Order No: 24072600476

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

> 49 6 of 10 NNW 0.15/ 4.11/ **GOOD BODY EMISSIONS** 50 LISBON, 794.44

> > CHAPIS:

CERR Code:

SAN RAFAEL CA 94901

2002 Toxic Data

Facility ID: 6926 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: 21 Air Basin: SF District: BA

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

49 7 of 10 NNW 0.15/ 4.11/ Good Body **CUPA MARIN** 794.44 0 50 Lisbon Street, Suite 5, San

Rafael CA

Permit No: 30-0578 UFC: No Type of Permit: **HWG Tons:** 0.0 HWG Recycle: Cross Ref: No

Status: HWG Type Gen: **RCRA SQG** Inactive US Tanks: 0 Tiered: No AG Tanks: 0 PBR HHW: Nο HMBP: 0 Green: No

Cal ARP: Facility Phone No: (415) 459-1102 Nο

NNW 0.15/ 4.11/ **BERRY GT ENTERPRISES** 49 8 of 10 RCRA TSD 50 LISBON ST STE 3 794.44 0 SAN RAFAEL CA 94901-4789

CAL000419323 EPA Handler ID: Gen Status Universe: No Report Contact Name: **ERIC LONG**

50 LISBON ST STE 3,, SAN RAFAEL, CA, 94901, US Contact Address:

Contact Phone No and Ext: 415-457-9262

Contact Email:

US Contact Country:

Land Type:

County Name: MARIN EPA Region: 09 Receive Date: 20240318 Location Latitude: 37.961729 -122.504417 Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

Order No: 24072600476

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No

Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Smelting, Melting and Refining: No **Underground Injection Control:** Nο Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20160803

Handler Name: BERRY GT ENTERPRISES

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Source Type: Implementer

TSD Activity:

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20240318

Handler Name: **BERRY GT ENTERPRISES**

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Implementer Source Type:

TSD Activity:

Owner/Operator Details

Current Operator Street No: Owner/Operator Ind:

50 LISBON ST STE 3 Type: Other Street 1:

ERIC LONG Name: Street 2:

Date Became Current: SAN RAFAEL City:

Date Ended Current: State: CA

415-459-9262 Country: Phone: Implementer

94901 Source Type: Zip Code:

Current Operator Owner/Operator Ind: Street No:

Other Street 1: 49 BAYVIEW TERRACE Type: Name: **ERIC LONG** Street 2:

MILL VALLEY Date Became Current: City:

Date Ended Current: State:

415-888-8119 US Phone: Country: Source Type: Implementer Zip Code: 94941

Current Owner Owner/Operator Ind: Street No:

49 BAYVIEW TER Type: Other Street 1:

ERIC LONG Name: Street 2:

Date Became Current: City: MILL VALLEY

Date Ended Current: State: CA 415-888-8119

Country: Source Type: Implementer Zip Code: 94941-2497

Owner/Operator Ind: **Current Owner** Street No:

49 BAYVIEW TER Type: Other Street 1:

Order No: 24072600476

Name: **ERIC LONG** Street 2:

Date Became Current: City: MILL VALLEY

Phone:

Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

 Date Ended Current:
 State:
 CA

 Phone:
 415-888-8119
 Country:
 US

Source Type: Implementer Zip Code: 94941-2497

Historical Handler Details

Receive Dt: 20160803

Generator Code Description: Not a Generator, Verified Handler Name: Not a Generator, Verified BERRY GT ENTERPRISES

49 9 of 10 NNW 0.15 / 4.11 / BERRY GT ENTERPRISES 794.44 0 50 LISBON ST STE 3 SAN RAFAEL CA 94901-4789

RCRA

Order No: 24072600476

NON GEN

EPA Handler ID:CAL000419323Gen Status Universe:No ReportContact Name:ERIC LONG

Contact Address: 50 LISBON ST STE 3 , , SAN RAFAEL , CA, 94901 , US

Contact Phone No and Ext: 415-457-9262

Contact Email:

Contact Country: US
County Name: MARIN
EPA Region: 09

Land Type:

 Receive Date:
 20240318

 Location Latitude:
 37.961729

 Location Longitude:
 -122.504417

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: Nο Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20160803

Handler Name: BERRY GT ENTERPRISES

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Distance Number of Direction Elev/Diff Site DB Map Key Records (mi/ft) (ft)

94941-2497

RCRA

Order No: 24072600476

NON GEN

Sequence No: 2

Receive Date: 20240318

BERRY GT ENTERPRISES Handler Name:

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Current Owner Owner/Operator Ind: Street No:

49 BAYVIEW TER Type: Other Street 1:

Name: **ERIC LONG** Street 2:

Date Became Current: City: MILL VALLEY

Date Ended Current: State: CA 415-888-8119 Phone: Country:

Source Type: Implementer Zip Code:

Owner/Operator Ind: **Current Owner** Street No: 49 BAYVIEW TER Other Street 1: Type:

Name: **ERIC LONG** Street 2:

Date Became Current: City: MILL VALLEY

Date Ended Current: State: CA

415-888-8119 Country: US Phone:

Source Type: Implementer Zip Code: 94941-2497

Owner/Operator Ind: **Current Operator** Street No:

Other Street 1: 50 LISBON ST STE 3 Type:

Name: **ERIC LONG** Street 2:

SAN RAFAEL Date Became Current: City:

Date Ended Current: State:

Phone: 415-459-9262 Country: 94901 Source Type: Implementer Zip Code:

Owner/Operator Ind: **Current Operator** Street No: Type: Other Street 1: 49 BAYVIEW TERRACE

Name: **ERIC LONG** Street 2:

Date Became Current: MILL VALLEY City: Date Ended Current: State: CA

415-888-8119 US Phone: Country: Implementer Zip Code: 94941 Source Type:

Historical Handler Details

Receive Dt: 20160803

Generator Code Description: Not a Generator, Verified Handler Name: **BERRY GT ENTERPRISES**

PARKER AUTOMOTIVE 49 10 of 10 NNW 0.15/ 4.11/ 794.44 **50 LISBON ST**

SAN RAFAEL CA 94901-0000

EPA Handler ID: CAL000130519 Gen Status Universe: No Report

DONALD PARKER OWNER Contact Name:

Contact Address: 50 LISBON ST STE 1,, SAN RAFAEL, CA, 94901-0000,

Contact Phone No and Ext: 415-453-6603 Contact Email: JEEPFIXR1@AOL.COM

Contact Country: County Name: MARIN

EPA Region: 09 Land Type:

Receive Date: 19950315 Location Latitude: 37.961729 Location Longitude: -122.504417

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: Nο

Hazardous Waste Handler Details

Sequence No:

Receive Date: 19950315

PARKER AUTOMOTIVE Handler Name:

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

Type: Other Street 1: 50 LISBON ST STE 1

Name: PARKER AUTOMOTIVE Street 2: Date Became Current: City:

SAN RAFAEL

Date Ended Current: State: CA

415-453-6603 Phone: Country:

Source Type: Implementer Zip Code: 94901-4709

Owner/Operator Ind: **Current Operator** Street No:

50 LISBON ST STE 1 Type: Other Street 1:

DONALD PARKER OWNER Name: Street 2:

SAN RAFAEL Date Became Current: City:

Date Ended Current: State: CA

Phone: 415-453-6603 Country:

94901-0000 Source Type: Implementer Zip Code:

50 1 of1 WSW 0.15/ 6.94/ Tom Duffy Company **CUPA MARIN** 807.97 31 Simms Street, San Rafael

Order No: 24072600476

CA

Permit No: 30-0269 UFC: No **HWG Tons:** Type of Permit: 0.0 HWG Recycle: Cross Ref: No

Status: Inactive HWG Type Gen: No US Tanks: 0 Tiered: AG Tanks: 0 PBR HHW: No HMBP: 0 Green: No

Cal ARP: No Facility Phone No: (707) 863-8300

Distance Number of Direction Elev/Diff Site DB Map Key Records (mi/ft) (ft) NNW 4.00/ MOTHER NATURE'S CLEANING 51 1 of1 0.15/**RCRA** 812.92 41 BELVEDERE ST, STE 5 AND 6 **NON GEN** SAN RAFAEL CA 94901

EPA Handler ID:CAC003066338Gen Status Universe:No ReportContact Name:DAVID VARNAI

Contact Address: 41 BELVEDERE ST, STE 5 AND 6,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-991-0500

Contact Email: INFO@MOTHERNATURESCLEANING.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Receive Date: 20200511

Location Latitude: Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: Nο Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No No Commercial TSD: Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: Nο Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20200511

Handler Name: MOTHER NATURE'S CLEANING

Source Type: Implementer

Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

Type: Other Street 1: 41 BELVEDERE ST, STE 5 AND 6

Name: DAVID VARNAI Street 2:

Date Became Current: City: SAN RAFAEL

Date Ended Current: State: CA

 Phone:
 415-991-0500
 Country:

 Source Type:
 Implementer
 Zip Code:
 94901

Owner/Operator Ind: Current Operator Street No:

Type: Other Street 1: 41 BELVEDERE ST, STE 5 AND 6

Order No: 24072600476

Name: DAVID VARNAI Street 2:

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft) Date Became Current: City: SAN RAFAEL Date Ended Current: State: 415-991-0500 Phone: Country: 94901 Source Type: Implementer Zip Code:

52 1 of 14 NNW 0.16 / 4.23 / DON'S AUTO BODY RCRA SQG 821.26 0 41 BELVEDERE SAN RAFAEL CA 94901

EPA Handler ID: CAD078759420

Gen Status Universe: Small Quantity Generator

Contact Name:

Contact Address: US

Contact Phone No and Ext:

Contact Email:

Contact Country:USCounty Name:MARINEPA Region:09

Land Type:

 Receive Date:
 19960901

 Location Latitude:
 37.96322

 Location Longitude:
 -122.505465

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: Nο Furnace Exemption: No Underground Injection Activity: No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 19960901

Handler Name: DON'S AUTO BODY

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

Type:PrivateStreet 1:NOT REQUIREDName:NOT REQUIREDStreet 2:

Date Became Current: City: NOT REQUIRED

Order No: 24072600476

Date Ended Current: State: ME

Phone: 415-555-1212 Country:

Map Key	Number Records		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Source Type	e:	Impleme	nter		Zip Code:	,	99999	
Owner/Oper Type: Name: Date Becam	e Current:	Current (Private NOT RE			Street No. Street 1: Street 2: City:	:	NOT REQUIRED	
Date Ended Phone: Source Type		415-555 Impleme			State: Country: Zip Code:	,	ME 99999	
<u>52</u>	2 of14		NNW	0.16 / 821.26	4.23 / 0	TC Auto R 41 Belvede Rafael CA	epair ere Street, Suite 3, San	CUPA MARI
Permit No: Type of Peri Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	nit:	Active 0 0 0 No			UFC: HWG Ton HWG Rec HWG Typ Tiered: PBR HHW Green: Facility Pl	ycle: e Gen: /:	No 0.0 No CESQG No No No (415) 455-8333	
<u>52</u>	3 of14		NNW	0.16 / 821.26	4.23 / 0		rger Yacht Service ere Street, Suite 4 & 5,	DELISTED COUNTY
Delisted Col Original Sol Original Sol Record Dt: Record Date	ırce Facility ırce Name:		30-0543 Marin County (13-JUN-2017 13-JUN-2017	CUPA List				
<u>52</u>	4 of14		NNW	0.16 / 821.26	4.23 / 0	41 BELVE	UTO BODY DERE STREET NEL CA 94901	EMISSIONS
<u> 2002 Toxic I</u>	<u>Data</u>							
Facility ID: Facility SIC CO: Air Basin: District: TS: Health Risk Non-Cancer Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Cou	de:	MRN BAY AREA AQMD	
<u>52</u>	5 of14		NNW	0.16 / 821.26	4.23 / 0	41 BELVE	UTO BODY DERE ST #1 NEL CA 94901	EMISSIONS

Order No: 24072600476

Мар Кеу	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
<u>1997 Toxic D</u>	<u>ata</u>						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
1998 Criteria	<u>Data</u>						
Facility ID: Facility SIC C CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	2		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	.1 .08	
1998 Toxic D	<u>ata</u>						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
<u>1999 Toxic D</u>	ata						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2000 Toxic D	ata						
Facility ID: Facility SIC C CO: Air Basin:	9914 Code: 7532 21 SF			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	

Order No: 24072600476

District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

NNW 0.16/ N & L AUTO BODY **52** 6 of 14 4.23/

821.26 41 BELVEDERE STREET, #1 0

SAN RAFAEL CA 94901

EMISSIONS

Order No: 24072600476

2006 Criteria Data

Facility ID: 17585 **CERR Code:**

Facility SIC Code: 7532 TOGT: .92 21 ROGT: .805085

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT:

DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

2006 Toxic Data

Facility ID: 17585 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: 21 CHAPIS: Air Basin: SF **CERR Code:**

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

ВА

2007 Criteria Data

Facility ID: 17585 CERR Code:

Facility SIC Code: 7532 TOGT: .92 .805085 CO: 21 ROGT:

Air Basin: SF COT: BA District: NOXT: COID: MRN SOXT: BAY AREA AQMD DISN: PMT:

2007 Toxic Data

CHAPIS:

Facility ID: 17585 COID: MRN

Facility SIC Code: DISN: 7532 **BAY AREA AQMD**

PM10T:

CHAPIS: CO: 21 Air Basin: SF CERR Code:

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2008 Criteria Data

CERR Code: Facility ID: 17585

Facility SIC Code: 7532 TOGT: .92

CO: .805085 21 ROGT:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Air Basin: District: COID: DISN: CHAPIS:	SF BA MRN BAY	AREA AQMD		COT: NOXT: SOXT: PMT: PM10T:			
2008 Toxic L	<u>Data</u>						
	21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2009 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN			CERR Co TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	.92 .805085	
2009 Toxic L	<u>Data</u>						
	21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2010 Toxic L	<u>Data</u>						
	21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2011 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN			CERR Co TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	.92 .805085	

Order No: 24072600476

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft)

2011 Toxic Data

17585 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: CERR Code: SF ВА

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

> NNW JOHN'S AUTO BODY **52** 7 of14 0.16/ 4.23/ **EMISSIONS** 821.26 0 41 BELVEDERE STREET, #1

SAN RAFAEL CA 94901

2001 Criteria Data

Facility ID: 9914 CERR Code:

Facility SIC Code: 7532 .07 TOGT: CO: 21 ROGT: .05

Air Basin: SF COT: ВА District: NOXT: COID: MRN SOXT:

DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

2001 Toxic Data

Facility ID: 9914 COID: MRN

BAY AREA AQMD Facility SIC Code: 7532 DISN:

CO: 21 CHAPIS: Air Basin: SF **CERR Code:** BA

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2003 Criteria Data

Facility ID: 9914 CERR Code:

Facility SIC Code: 7532 TOGT: .119 CO: 21 ROGT: .09

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT:

BAY AREA AQMD DISN: PMT: CHAPIS: PM10T:

2003 Toxic Data

Facility ID: 9914 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

Order No: 24072600476

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: ВА

Health Risk Asmt:

Non-Cancer Chronic Haz Ind:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Non-Cancer Acute Haz Ind:

2004 Criteria Data

Facility ID: 9914 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .119

 CO:
 21
 ROGT:
 .0958912

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

 CHAPIS:
 PM10T:

2004 Toxic Data

Facility ID: 9914 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: BA

Health Risk Asmt:

Non-Cancer Chronic Haz Ind:

Non-Cancer Acute Haz Ind:

52 8 of 14 NNW 0.16 / 4.23 / Enzensperger Yacht Service CUPA MARIN
821.26 0 41 Belvedere Street, Suite 4 & 5,
San Rafael
CA

 Permit No:
 30-0543
 UFC:
 No

 Type of Permit:
 HWG Tons:
 0.0

HWG Recycle: Cross Ref: Nο Status: Inactive HWG Type Gen: US Tanks: Tiered: 0 No AG Tanks: 0 PBR HHW: No HMBP: 0 Green: No

Cal ARP: No **Facility Phone No:** (415) 453-3112

52 9 of 14 NNW 0.16 / 4.23 / N & L Auto Body
831.36 0 41 Belyindaya Street Suite 1 Sep

821.26 0 41 Belvedere Street, Suite 1, San Rafael CA

Permit No: 60-0731 **UFC:** No

 Type of Permit:
 HWG Tons:
 0.0

 Cross Ref:
 HWG Recycle:
 No

 Status:
 Inactive
 HWG Type Gen:
 4

 US Tanks:
 0
 Tiered:
 No

 AG Tanks:
 0
 PBR HHW:
 No

 HMBP:
 0
 Green:
 No

Cal ARP: No *Facility Phone No:* (415) 457-4010

52 10 of14 NNW 0.16 / 4.23 / Michael's Auto Repair CUPA MARIN 821.26 0 41 Belvedere Street, Suite 3, San

Order No: 24072600476

Rafael CA

 Permit No:
 30-0296
 UFC:
 No

 Type of Permit:
 HWG Tons:
 0.0

Cross Ref: HWG Recycle: No Status: Inactive HWG Type Gen:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
US Tanks: AG Tanks: HMBP: Cal ARP:	0 0 0 No			Tiered: PBR HI Green: Facility	łW: Phone No:	No No No (415) 455-8333	
<u>52</u>	11 of14	NNW	0.16 / 821.26	4.23 / 0	T & C Aut 41 Belved Rafael CA	o Repair lere Street, Suite 3, San	CUPA MARII
Permit No: Type of Pen Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	30-0 mit: Inact 0 0 0 No			Tiered: PBR HI Green:	ecycle: ype Gen:	No 0.0 No 4 No No No (415) 455-8333	
<u>52</u>	12 of14	NNW	0.16 / 821.26	4.23 / 0	John's Au 41 Belved Rafael CA	ito Body lere Street, Suite 1, San	CUPA MARII
Permit No: Type of Per Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	30-0 mit: Inact 0 0 0 0 No			Tiered: PBR HI Green:	ecycle: ype Gen:	No 0.0 No No No No (415) 457-4010	
<u>52</u>	13 of14	NNW	0.16 / 821.26	4.23 / 0	T C AUTO 41 BELVE SAN RAF		RCRA TSD

EPA Handler ID:CAL000253609Gen Status Universe:No ReportContact Name:CHAU LUONG

Contact Address: 41 BELVEDERE ST,, SAN RAFAEL, CA, 94901-0000,

Contact Phone No and Ext: 415-453-3578

Contact Email: BALY203@YAHOO.COM

Contact Country:

Land Type:

 County Name:
 MARIN

 EPA Region:
 09

 Receive Date:
 20020611

 Location Latitude:
 37.962169

 Location Longitude:
 -122.503643

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

Order No: 24072600476

associated with this facility (EPA ID).

Handler Summary

Importer Activity:NoMixed Waste Generator:NoTransporter Activity:No

Transfer Facility: No Onsite Burner Exemption: No Smelting, Melting and Refining: No **Underground Injection Control:** No Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20020611

Handler Name: T C AUTO REPAIR

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Source Type: Implementer

TSD Activity:

Owner/Operator Details

Owner/Operator Ind: **Current Operator** Street No:

41 BELVEDERE ST Type: Other Street 1:

CHAU LUONG Name: Street 2:

Date Became Current: City: SAN RAFAEL

State: Date Ended Current: Country:

Phone: 415-453-3578

Implementer 94901-0000 Source Type: Zip Code:

Owner/Operator Ind: **Current Owner** Street No:

41 BELVEDERE ST Type: Other Street 1: Name: **DINH PHAM** Street 2:

SAN RAFAEL Date Became Current: City:

Date Ended Current: State: CA

Phone: 415-453-3578 Country:

94901-0000 Source Type: Implementer Zip Code:

14 of14 NNW T C AUTO REPAIR 0.16/ **52** 4.23/ 821.26 41 BELVEDERE ST

RCRA

Order No: 24072600476

NON GEN

SAN RAFAEL CA 94901-0000

EPA Handler ID: CAL000253609 Gen Status Universe: No Report **CHAU LUONG** Contact Name:

41 BELVEDERE ST,, SAN RAFAEL, CA, 94901-0000, Contact Address:

Contact Phone No and Ext: 415-453-3578

BALY203@YAHOO.COM Contact Email:

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

20020611 Receive Date: Location Latitude: 37.962169 -122.503643 Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: Nο Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: Nο

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20020611

T C AUTO REPAIR Handler Name: Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

Type: 41 BELVEDERE ST Other Street 1:

Name: **DINH PHAM** Street 2:

Date Became Current: City: SAN RAFAEL Date Ended Current: State:

Phone: 415-453-3578 Country:

Implementer Zip Code: 94901-0000 Source Type:

Owner/Operator Ind: **Current Operator** Street No:

Type: Other Street 1: 41 BELVEDERE ST

CHAU LUONG Name: Street 2: Date Became Current: City:

SAN RAFAEL Date Ended Current: State: CA

415-453-3578 Country: Phone:

Source Type: Implementer Zip Code: 94901-0000

Ε 0.16/ PACIFIC GAS & ELECTRIC CO. (R-**53** 1 of1 6.87/

833.82

104 WINDWARD WAY

SAN RAFAEL CA 94901

RCRA

Order No: 24072600476

NON GEN

CAC002980820 EPA Handler ID: No Report Gen Status Universe: **COLT HAWKINS** Contact Name:

6111 BOLLINGER CANYON ROAD, SUITE 3130C, SAN RAMON, CA, 94583, Contact Address:

Contact Phone No and Ext: 925-404-4884 C2H8@PGE.COM Contact Email:

Contact Country:

MARIN County Name: EPA Region: 09

Land Type: Receive Date: 20180918 37.959456 Location Latitude: Location Longitude: -122.499009

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: Nο

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20180918

PACIFIC GAS & ELECTRIC CO. (R-506) Handler Name:

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

Other Street 1: PO BOX 7640 Type:

Name: PG&E-EPA IDS Street 2:

SAN FRANCISCO Date Became Current: City:

Date Ended Current: State: CA

925-404-4884 Phone: Country: Source Type: Implementer Zip Code: 94120

Owner/Operator Ind: **Current Operator** Street No:

6111 BOLLINGER CANYON ROAD Type: Other Street 1:

COLT HAWKINS Name: Street 2: **SUITE 3130C**

SAN RAMON Date Became Current: City:

Date Ended Current: State: CA

925-404-4884 Phone: Country:

Source Type: Implementer Zip Code: 94583

54 1 of4 NW 0.16/ 4.83/ LUCAS DIGITAL LTD L L C RCRA SQG 836.09 155 MARKET ST

SAN RAFAEL CA 94901

Order No: 24072600476

EPA Handler ID: CAD983642554 Gen Status Universe: Small Quantity Generator

Contact Name: AL MOUNTAIN

Contact Address: P O BOX 2459, , SAN RAFAEL, CA, 94912, US

Contact Phone No and Ext: 415-448-2132

Contact Email: Contact Country: US MARIN County Name: EPA Region: 09 Private Land Type:

Map Key Number of Direction Distance Elev/Diff Site DB
Records (mi/ft) (ft)

 Receive Date:
 20010416

 Location Latitude:
 37.961726

 Location Longitude:
 -122.505426

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: Nο Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: Nο **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No **Used Oil Transfer Facility:** No Used Oil Processor: Nο Used Oil Refiner: Nο Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20010416

Handler Name: LUCAS DIGITAL LTD L L C

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code:D007Waste Code Description:CHROMIUM

Hazardous Waste Code: D035

Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003

Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL

BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND STILL BOTTOMS EDOM THE BECOVERY OF THESE SPENT SOLVENTS AND SPENT

Order No: 24072600476

AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT

SOLVENT MIXTURES.

Distance Number of Direction Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Hazardous Waste Code: F005

THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON Waste Code Description:

DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT

SAN RAFAEL CA 94901

SAN RAFAEL CA 94901

Order No: 24072600476

SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Street No: Owner/Operator Ind: **Current Owner**

Private Street 1: P O BOX 2459 Type:

LUCAS DIGITAL LTD L L C Name: Street 2:

Date Became Current: City: SAN RAFAEL Date Ended Current: State: CA

Phone: 415-448-9000 Country:

Notification 94912 Source Type: Zip Code:

NW 0.16/ 4.83/ MARIN DODGE ISUZU **54** 2 of4 **EMISSIONS** 836.09 0 155 MARKET STREET

1990 Criteria Data

6510 Facility ID: CERR Code:

Facility SIC Code: 7532 TOGT: 1.2 ROGT: 1.1936 21

CO: Air Basin: SF COT: District: BA NOXT: SOXT: COID: MRN

BAY AREA AQMD DISN: PMT: PM10T: CHAPIS:

1990 Toxic Data

6510 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: CHAPIS: 21 Air Basin: SF **CERR Code:**

District: BA

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

3 of4 NW 0.16/ 4.83/ LUCAS DIGITAL LTD LLC 54 **EMISSIONS** 836.09 0 155 MARKET STREET

2001 Criteria Data

Facility ID: 12804 **CERR Code:**

Facility SIC Code: 7800 TOGT: .43 21 ROGT: .41

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT: PMT:

BAY AREA AQMD DISN: CHAPIS: PM10T:

PM10T:

Order No: 24072600476

2001 Toxic Data

12804 COID: MRN Facility ID:

7800 DISN: BAY AREA AQMD Facility SIC Code:

CO: 21 CHAPIS: Air Basin: SF **CERR Code:**

District:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

2002 Criteria Data

12804 CERR Code: Facility ID:

Facility SIC Code: 7812 TOGT: .45 .4337226 CO: ROGT: 21 Air Basin: SF COT:

District: ВА NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT: CHAPIS:

2002 Toxic Data

Facility ID: 12804 COID: MRN

Facility SIC Code: 7812 DISN: **BAY AREA AQMD**

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2003 Criteria Data

12804 Facility ID: CERR Code:

Facility SIC Code: 7812 .233 TOGT: CO: 21 ROGT: .22 SF

Air Basin: COT: District: ВА NOXT: COID: MRN SOXT: **BAY AREA AQMD** DISN: PMT: CHAPIS: PM10T:

2003 Toxic Data

Facility ID: 12804 COID: MRN

Facility SIC Code: 7812 DISN: **BAY AREA AQMD**

CO: 21 CHAPIS: Air Basin: **CERR Code:** SF

District: ВΑ

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2004 Criteria Data

Facility ID: 12804 **CERR Code:**

Facility SIC Code: 7812 TOGT: .233

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN BAY	AREA AQMD		ROGT: COT: NOXT: SOXT: PMT: PM10T:	.2194872	
2004 Toxic D	<u>Pata</u>					
	21 SF BA			COID: DISN: CHAPIS: CERR Cod	MRN BAY AREA AQMD	
<u>54</u>	4 of4	NW	0.16 / 836.09	4.83 / 0	LUCASFILM ENTERTAINMENT CO LTD 155 MARKET STREET	EMISSIONS

SAN RAFAEL CA 94901

Order No: 24072600476

Facility ID:	12804	CERR Code:	
Facility SIC Code:	7812	TOGT:	.233
CO:	21	ROGT:	.2194872
Air Basin:	SF	COT:	
District:	BA	NOXT:	
COID:	MRN	SOXT:	

DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

2005 Toxic Data

Facility ID:	12804	COID:	MRN

BAY AREA AQMD Facility SIC Code: 7812 DISN:

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: ВА TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2006 Criteria Data

Facility ID: 12804 CERR Code:

Facility SIC Code: .233 7812 TOGT: CO: 21 ROGT: .2194872

Air Basin: SF COT: District: ВА NOXT: COID: MRN SOXT:

BAY AREA AQMD DISN: PMT: CHAPIS: PM10T:

2006 Toxic Data

12804 COID: MRN Facility ID:

CHAPIS:

CERR Code:

Oil Field Oper (SRCH): Census Tract (SRCH):

RWQCB Region (DL):

Latitude (DL):

Longitude (DL):

6041112202

-122 506354

SAN FRANCISCO BAY RWQCB (REGION 2)

Order No: 24072600476

37.95854

Facility SIC Code: 7812 DISN: **BAY AREA AQMD**

CO: 21 Air Basin: SF District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

> W 10.91/ **55** 1 of1 0.16/ **BELLAM MINI STORAGE** LUST 838.52 6 24 BELLAM BLVD SAN RAFAEL CA 94901

LUST Cleanup Site Global ID: T0604100317 Case Type (DL): Oil Field (SRCH):

Site Facility Type: LUST CLEANUP SITE Site Fac Type (SRCH): LUST CLEANUP SITE

Status:

Status (SRCH): **COMPLETED - CASE CLOSED**

Status (DL): Completed - Case Closed

Status Date (DL): 8/5/1998

COMPLETED - CASE CLOSED Cleanup Status: Site Facility Name (SRCH): **BELLAM MINI STORAGE** Address (SRCH): 24 BELLAM BLVD City (SRCH): SAN RAFAEL

Zip (SRCH): 94901 County (SRCH): MARIN Street No (DL): 24

BELLAM BLVD Street Name (DL): City (DL): SAN RAFAEL Zip (DL): 94901 County (DL): Marin State (DL): CA

Business Name (DL): **BELLAM MINI STORAGE BELLAM MINI STORAGE** Site Facility Name: Address : 24 BELLAM BLVD SAN RAFAEL

City: 94901 Zip: County: **MARIN**

GeoTracker Search Results (SRCH);GeoTracker Sites Data Download (DL);GeoTracker Search Results Report Report Source:

GeoTracker Sites Data Download - Site Details

CUF Case:

SAN FRANCISCO BAY RWQCB (REGION 2) Lead Agency:

Case Worker: Local Agency:

RB Case No: 21-0335

Local Case No:

File Location:

Potential COC: Gasoline

Potential Media of Concern: Other Groundwater (uses other than drinking water)

Begin Date: 8/9/1993 How Discovered: Tank Closure

How Discovered Description:

Stop Method:

Stop Description:

Calwater Watershed Name: Bay Bridges - San Rafael (203.20)

DWR GW Subbasin Name: Disadvantaged Community: CalEnvScreen Score:

Google Geocode Coordinate Source:

Overfill Discharge Cause: Discharge Source: Other

EPA Region:

Leak Reported Dt: 1993-08-09 00:00:00

Military DoD Site: No

1998-08-05 00:00:00 No Further Action Dt:

Qty Risd Gallons:

Facility Project Sub Type:

Calenviroscreen 3 Score: 56-60% Calenviroscreen 4 Score: 70-75%

Site History:

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type:
Contact Name:
BRADLEY R. MARK
Organization Name:
Address:
City:

Local Agency Caseworker
BRADLEY R. MARK
SAN RAFAEL, CITY OF
1039 C STREET
SAN RAFAEL

Email: brad.mark@ci.san-rafael.ca.us

Phone No:

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed

Status Date: 8/5/1998

Status: Open - Case Begin Date

Status Date: 8/9/1993

GeoTracker Search - Regulatory Profile (as of June 5, 2024)

Site Facility Name:BELLAM MINI STORAGESite Facility Type:LUST CLEANUP SITE

Cleanup Status: COMPLETED - CASE CLOSED

 Address:
 24 BELLAM BLVD

 City:
 SAN RAFAEL

 Zip:
 94901

 County:
 MARIN

Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0604100317

Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 8/5/1998

Project Status:

Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0604100317&tabname=regulatoryhistory

Order No: 24072600476

Potential COC: GASOLINE

Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)

File Location:

User Defined Beneficial Use: Designated Beneficial Use: DWR GW Sub Basin:

Calwater Watershed Name: Bay Bridges - San Rafael (203.20)

Post Closure Site Management:

Future Land Use:

Cleanup Oversight Agencies: SAN FRANCISCO BAY RWQCB (REGION 2) (LEAD) - CASE #: 21-0335

CUF Claim No: CUF Priority Assig: CUF Amount Paid: WDR Place Type: WDR File No: WDR Order No:

Project Oversight Agencies:

Facility Type:

Composting Method:

Grndwtr Monitoring Frequency: Designated Beneficial Use

Desc: Site History:

No site history available

GeoTracker Search - Cleanup Status History (as of June 5, 2024)

Status: Completed - Case Closed

Date: 8/5/1998

Status: Open - Case Begin Date

Date: 8/9/1993

GeoTracker Search - Regulatory Activities (as of June 5, 2024)

Action Type:Leak ActionAction:Leak ReportedAction Date:8/9/1993

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak StoppedAction Date:8/9/1993

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak DiscoveryAction Date:8/9/1993

Received Issue Date:

Doc Link:

Title Description Comments:

 56
 1 of10
 NW
 0.16 / 839.24
 4.66 / 0RLANDI'S BODY & FENDER INC RCRA SQG

SAN RAFAEL CA 94901

Order No: 24072600476

EPA Handler ID: CAD045031739

Gen Status Universe: Small Quantity Generator
Contact Name: ENVIRONMENTAL MANAGER

Contact Address: 25 VERDI STREET,, SAN RAFAEL, CA, 94901, US

Contact Phone No and Ext: 415-456-3110

Contact Email: Contact Country: US

Contact Country: US
County Name: MARIN
EPA Region: 09

Land Type:

 Receive Date:
 19860603

 Location Latitude:
 37.962039

 Location Longitude:
 -122.504746

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS;

Compliance Monitoring and Enforcement table dated Apr, 2024.

Evaluation Details

Evaluation Start Date: 19990819

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION

Violation Short Description: Return to Compliance Date:

Evaluation Agency: State Contractor/Grantee

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** Nο Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

19860603 Receive Date:

Handler Name: ORLANDI'S BODY & FENDER INC

Federal Waste Generator Code:

Generator Code Description: Small Quantity Generator

Notification Source Type:

Owner/Operator Details

Current Owner Street No: Owner/Operator Ind: Private Street 1:

Type: D ORLANDI Name: Street 2:

Date Became Current: City:

Date Ended Current: State:

Phone: 415-555-1212 Country: Source Type: Notification Zip Code: 99999

Current Operator Street No: Owner/Operator Ind:

Type: Street 1: **NOT REQUIRED** Private

NOT REQUIRED Name: Street 2: Date Became Current: City:

NOT REQUIRED Date Ended Current: State: ΜE

415-555-1212 Country: Phone:

Notification 99999 Source Type: Zip Code:

2 of 10 NW 0.16/ 4.66/ **Kovacs Motors 56 CUPA MARIN**

839.24 0

Permit No: 60-1080 UFC: No 0.0 Type of Permit: **HWG Tons:**

HWG Recycle: Cross Ref: No Status: Active HWG Type Gen: SQG US Tanks: Tiered: 0 Nο AG Tanks: 0 PBR HHW: No HMBP: 6 Green: No

Cal ARP: No Facility Phone No: (415) 459-7000

NW ORLANDI'S BODY & FENDER INC 56 3 of 10 0.16/ 4.66/ **EMISSIONS**

839.24 25 VERDI STREET n SAN RAFAEL CA 94901

CA

NOT REQUIRED

NOT REQUIRED

Order No: 24072600476

ME

25 Verdi Street, San Rafael

Map Key Number of Direction Distance Elev/Diff Site DB Records (mi/ft) (ft) 1990 Criteria Data 4176 Facility ID: **CERR Code:** 7532 Facility SIC Code: TOGT: 3.9 CO: 21 ROGT: 3.5904 Air Basin: SF COT: District: ВА NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T: 1990 Toxic Data 4176 COID: MRN Facility ID: Facility SIC Code: 7532 DISN: **BAY AREA AQMD** CO: 21 CHAPIS: Air Basin: **CERR Code:** SF District: ВА TS: Health Risk Asmt: Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind: 1993 Criteria Data Facility ID: 4176 CERR Code: Facility SIC Code: 7532 TOGT: 1.9 1.82244 ROGT: CO: 21 Air Basin: SF COT: NOXT: District: BA COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T: 1993 Toxic Data Facility ID: 4176 COID: MRN DISN: **BAY AREA AQMD** Facility SIC Code: 7532 CHAPIS: CO: 21 Air Basin: SF CERR Code: District: BA TS: Health Risk Asmt: Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind: 1995 Criteria Data Facility ID: 4176 **CERR Code:** Facility SIC Code: 7532 TOGT: 1.6 21 ROGT: 1.47906 Air Basin: SF COT: District: NOXT: BA MRN COID: SOXT:

BAY AREA AQMD PMT: DISN: PM10T:

CHAPIS:

1995 Toxic Data

4176 MRN Facility ID: COID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

Order No: 24072600476

CO: 21 CHAPIS:

Air Basin: CERR Code: SF District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

1996 Criteria Data

Facility ID: 4176 **CERR Code:**

Facility SIC Code: 1.6 7532 TOGT: 1.47906 CO: 21 ROGT: Air Basin: SF COT:

District: NOXT: BA COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

1996 Toxic Data

Facility ID: 4176 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

CO: 21 CHAPIS: Air Basin: SF CERR Code:

District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

1997 Criteria Data

CERR Code: Facility ID: 4176

Facility SIC Code: 7532 TOGT: 1.5 CO: 21 ROGT: 1.3846

Air Basin: SF COT: District: BA NOXT: MRN COID: SOXT:

BAY AREA AQMD DISN: PMT: CHAPIS: PM10T:

1997 Toxic Data

4176 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: 21 CHAPIS: Air Basin: SF **CERR Code:**

District: BA

TS:

Health Risk Asmt: Non-Cancer Chronic Haz Ind:

Non-Cancer Acute Haz Ind:

1998 Criteria Data

Facility ID: 4176 **CERR Code:**

Facility SIC Code: 7532 TOGT: 1.5

Order No: 24072600476

ROGT: 1.22598 CO: 21 Air Basin: SF COT: ВА District: NOXT:

COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

PM10T:

Order No: 24072600476

1998 Toxic Data

Facility ID: 4176 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

1999 Criteria Data

Facility ID: 4176 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 1.456

 CO:
 21
 ROGT:
 1.1890062

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

1999 Toxic Data

CHAPIS:

Facility ID: 4176 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

 District:
 BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2000 Criteria Data

Facility ID: 4176 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 1.456

 CO:
 21
 ROGT:
 1.19

 Air Basins
 SF
 00T:
 00T:

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

DISN: BAY AREA AQMD PMT: CHAPIS: PM10T:

2000 Toxic Data

Facility ID: 4176 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

2001 Criteria Data

Facility ID: 4176 CERR Code:

Мар Кеу	Number Records		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	7532 21 SF BA MRN BAY ARI	ea aqmd		TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:		1.75 1.31	
2001 Toxic L	<u>Data</u>							
Facility ID: Facility SIC CO: Air Basin: District: TS: Health Risk Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2002 Criteria	a Data							
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	4176 7532 21 SF BA MRN BAY ARI	EA AQMD		CERR Co TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	1.743 1.3072396	
2002 Toxic L	<u>Data</u>							
Facility ID: Facility SIC CO: Air Basin: District: TS: Health Risk Non-Cancer Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2003 Criteria	a Data							
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	4176 7532 21 SF BA MRN BAY ARI	EA AQMD		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	1.143 .9	
2003 Toxic L	<u>Data</u>							
Facility ID: Facility SIC CO: Air Basin: District: TS: Health Risk		4176 7532 21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	

CERR Code:

1.143

.903021

Order No: 24072600476

TOGT:

ROGT:

COT:

NOXT:

SOXT:

PM10T:

PM10T:

PMT:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2004 Criteria Data

Facility ID: 4176 Facility SIC Code: 7532

21 Air Basin: SF District: BA

COID: MRN **BAY AREA AQMD** DISN: CHAPIS:

2004 Toxic Data

4176 COID: Facility ID: MRN

Facility SIC Code: DISN: **BAY AREA AQMD** 7532

CHAPIS: CO: 21 Air Basin: SF **CERR Code:** District: BA

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2005 Criteria Data

Facility ID: 4176 **CERR Code:**

Facility SIC Code: 1.143 7532 TOGT: .903021 CO: 21 ROGT:

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT:

ВА

CHAPIS:

2005 Toxic Data

Facility ID: 4176 COID: MRN

Facility SIC Code: DISN: **BAY AREA AQMD** 7532

CO: 21 CHAPIS: Air Basin: SF CERR Code:

District: TS:

Health Risk Asmt: Non-Cancer Chronic Haz Ind:

Non-Cancer Acute Haz Ind:

2006 Criteria Data

Facility ID: 4176 CERR Code:

Facility SIC Code: 7532 TOGT: 1.143 .903021 CO: 21 ROGT:

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT: **BAY AREA AQMD** DISN: PMT:

CHAPIS: PM10T:

2006 Toxic Data

Map Key	Number Record		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk (Non-Cancer Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2007 Criteria	a Data							
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	4176 7532 21 SF BA MRN BAY AF	BEA AQMD		CERR Co TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	.258 .2081082	
2007 Toxic L	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk (Non-Cancer Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2008 Criteria	a Data							
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	4176 7532 21 SF BA MRN BAY AF	BEA AQMD		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	.258 .2081082	
2008 Toxic L	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk (Non-Cancer)	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2009 Criteria	a Data							
Facility ID: Facility SIC (CO: Air Basin: District:	Code:	4176 7532 21 SF BA			CERR Co TOGT: ROGT: COT: NOXT:	de:	.258 .2081082	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
COID: DISN: CHAPIS:	MRN BAY	I AREA AQMD		SOXT: PMT: PM10T:			
2009 Toxic L	<u>Data</u>						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co	ode:	MRN BAY AREA AQMD	
2010 Toxic L	<u>Data</u>						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2011 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	2		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.55 .4297474	
2011 Toxic L	<u>Data</u>						
	21 SF BA	2		COID: DISN: CHAPIS: CERR Co	ode:	MRN BAY AREA AQMD	
2012 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	2		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	.55 .4297474	

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft) 2012 Toxic Data Facility ID: 4176 COID: MRN Facility SIC Code: 7532 DISN: **BAY AREA AQMD** CO: 21 CHAPIS: Air Basin: SF **CERR Code:** District: BA TS: Health Risk Asmt: Non-Cancer Chronic Haz Ind:

 56
 4 of 10
 NW
 0.16 / 839.24
 4.66 / 600 / 4.66 / 600 / 4.66 / 600

2013 Criteria Data

Non-Cancer Acute Haz Ind:

Facility ID: 22315 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .55

 CO:
 21
 ROGT:
 .4297474

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

DISN: BAY AREA AQMD PMT: Chapis: PM10T:

2013 Toxic Data

Facility ID: 22315 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: BA

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2014 Criteria Data

Facility ID: 22315 CERR Code:

Facility SIC Code: 7532 **TOGT:** .219365776

 CO:
 21
 ROGT:

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISM:
 BAY AREA AOMD
 BMT:

DISN: BAY AREA AQMD PMT: CHAPIS: PM10T:

2014 Toxic Data

Facility ID: 22315 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

Order No: 24072600476

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: BA

TS:

Health Risk Asmt: Non-Cancer Chronic Haz Ind:

Non-Cancer Acute Haz Ind:

Map Key	Numbe Record		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
<u> 2015 Criteri</u>	ia Data							
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	22315 7532 21 SF BA MRN BAY ARI	EA AQMD		CERR (TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T		.21936581 .21936571	
2015 Toxic	Data							
Facility ID: Facility SIC CO: Air Basin: District: TS:		22315 7532 21 SF BA			COID: DISN: CHAPI: CERR (MRN BAY AREA AQMD	
Health Risk Non-Cancel Non-Cancel	r Chronic H							
<u>56</u>	5 of10		NW	0.16 / 839.24	4.66 / 0		Body & Fender treet, San Rafael	CUPA MARII
Permit No: Type of Per Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	rmit:	60-0937 Inactive 0 0 0 No			HWG T Tiered: PBR HI Green:	Recycle: Type Gen: HW:	No 0.0 No 4 No No No (415) 456-3110	
<u>56</u>	6 of10		NW	0.16 / 839.24	4.66 / 0		Body and Fender treet, San Rafael	CUPA MARIN
Permit No: Type of Per Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	rmit:	30-0057 Inactive 0 0 0 No			HWG T Tiered: PBR HI Green:	Recycle: Type Gen: HW:	No 0.0 No No No No (415) 456-3110	
<u>56</u>	7 of10		NW	0.16 / 839.24	4.66 / 0		Body & Fender treet, San Rafael	CUPA MARIN
Permit No: Type of Per Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	mit:	30-0660 5445 Inactive 0 0 0 No			HWG T Tiered: PBR HI Green:	Tons: Recycle: Type Gen: HW:	No 0.0 No CESQG No No No (415) 456-3110	

56 8 of 10 NW 0.16/ 4.66/ **KOVACS MOTORS INC** 25 VERDI ST 839.24

SAN RAFAEL CA 94901

RCRA NON GEN

Order No: 24072600476

CAL000410515 EPA Handler ID: No Report Gen Status Universe:

MICHAEL QUIGLEY MANAGER Contact Name:

2320 LANCASTER DR APT 4,, RICHMOND, CA, 94901, Contact Address:

Contact Phone No and Ext: 209-597-9455

MICHAEL@KOVACSAUTOBODY.COM Contact Email:

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Receive Date: 20150918 Location Latitude: 37.961653 Location Longitude: -122.505303

Violation/Evaluation Summary

NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records Note:

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: Nο Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** Nο Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: Nο Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20150918

Handler Name: KOVACS MOTORS INC

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Operator** Street No:

Type: Street 1: 2320 LANCASTER DR APT 4 MICHAEL QUIGLEY MANAGER Street 2:

Country:

Name: Date Became Current:

RICHMOND City: CA

Date Ended Current: State: 209-597-9455

Implementer Zip Code: 94901 Source Type:

Owner/Operator Ind: **Current Owner** Street No:

Type: Other Street 1: 701 AVE DEL ORO

Phone:

Map Key	Number o Records	of Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Name:		ADAMS KOVACS		Street 2:		
Date Becam	e Current:			City:	SONOMA	
Date Ended	Date Ended Current:			State:	CA	
Phone:		415-720-6807		Country:		
Source Type:		Implementer		Zip Code:	95476	
56	9 of10	NW	0.16/	4.66 /	KOVACS MOTORS	FMISSIONS

839.24 0 25 VERDI ST SAN RAFAEL CA 94901

PM10T:

Order No: 24072600476

2017 Toxic Data

 Facility ID:
 22315
 COID:
 MRN

 Facility SIC Code:
 7532
 DISN:
 BAY A

Facility SIC Code:7532DISN:BAY AREA AQMDCO:21CHAPIS:

Air Basin: SF CERR Code: District: BA

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2018 Criteria Data

Facility ID: 22315 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .055200002

 CO:
 21
 ROGT:
 .0545320819758

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

2018 Toxic Data

CHAPIS:

Facility ID: 22315 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: BA

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2020 Criteria Data

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

Facility ID: 22315 **ROGT:** .0545320819758

 District:
 BA
 COT:

 Facility SIC Code:
 7532
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD
TOGT: .055200002

PMT: PM10T:

2020 Toxic Data

CO: 21 DISN: BAY AREA AQMD

CHAPIS: Air Basin: SF Facility ID: 22315 CHERR Code: District: BA TS:

Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Toxic Data

DISN: **BAY AREA AQMD** Co: 21

Air Basin: SF CHAPIS: Facility ID: 22315 Cerr Code: District: BA TS:

Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Criteria Data

21 CHAPIS: Co: Air Basin: SF Cerr Code:

Facility ID: 22315 ROGT: .2148682519758

District: BA COT: Facility SIC Code: 7532 NOXT: CO ID: MRN SOXT:

BAY AREA AQMD DISN: .217500002

TOGT: РМТ:

PM10T:

10 of 10 NW 0.16/ 4.66/ **AUTO CENTER MARIN 56** 839.24 0 25 VERDI ST

SAN RAFAEL CA 94901

RCRA

Order No: 24072600476

NON GEN

EPA Handler ID: CAL000467659 No Report Gen Status Universe: Contact Name: SIMON JIZRAWI

25 VERDI ST,, SAN RAFAEL, CA, 94901, Contact Address:

Contact Phone No and Ext: 415-459-7000

Contact Email: SIMON@AUTOCENTERMARIN.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Location Latitude: Location Longitude:

Receive Date: 20211230

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft) Underground Injection Activity: No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: Nο Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: No Hazardous Waste Handler Details Sequence No: Receive Date: 20211230 Handler Name: **AUTO CENTER MARIN** Source Type: Implementer Federal Waste Generator Code: Generator Code Description: Not a Generator, Verified Owner/Operator Details Owner/Operator Ind: **Current Owner** Street No: Type: Other Street 1: 333 LIBERTY ST UNIT C SIMON JUZRAWI Name: Street 2: Date Became Current: **PETALUMA** City: Date Ended Current: State: CA 415-686-1639 Phone: Country: 94952 Implementer Zip Code: Source Type: Owner/Operator Ind: **Current Operator** Street No: Type: Street 1: 25 VERDI ST SIMON JIZRAWI Name: Street 2: Date Became Current: City: SAN RAFAEL Date Ended Current: State: CA 415-459-7000 Country: Phone: Source Type: Implementer Zip Code: 94901 **ESE** 0.16/ 5.95/ Design Line Cabinetry **57** 1 of 5 **CUPA MARIN** 846.11 3100 Kerner Boulevard, Suite D, San Rafael CA UFC: Permit No: 30-0624 No Type of Permit: **HWG Tons:** 0.0 Cross Ref: 5440 HWG Recycle: No Status: Inactive HWG Type Gen: US Tanks: Tiered: No AG Tanks: PBR HHW: 0 Nο HMBP: 0 Green: No Facility Phone No: (415) 456-4166 Cal ARP: No 2 of 5 **ESE** 0.16/ 5.95/ MARIN MECHANICAL II. INC. **57** RCRA TSD 846.11 3100 KERNER BLVD. SUITE B1 1 SAN RAFAEL CA 94901 EPA Handler ID: CAC003012204 Gen Status Universe: No Report Contact Name: **BRYAN DUNBAR**

Order No: 24072600476

Contact Address: 3100 KERNER BLVD. SUITE B1,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-485-4472

Contact Email: BRYAN.DUNBAR@MARINMECHANICAL.COM

Contact Country: Land Type:

County Name: MARIN

EPA Region: 09

 Receive Date:
 20190426

 Location Latitude:
 37.957094

 Location Longitude:
 -122.499563

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: Nο Smelting, Melting and Refining: No **Underground Injection Control:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No **Used Oil Refiner:** No Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: Nο

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20190426

Handler Name: MARIN MECHANICAL II, INC.

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Source Type: Implementer

TSD Activity:

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

Type: Other Street 1: 3100 KERNER BLVD. SUITE B1

Name: MARIN MECHANICAL II. INC. Street 2:

Date Became Current: City: SAN RAFAEL

Date Ended Current: State: CA

Phone: 415-485-4472 **Country:**

Source Type: Implementer Zip Code: 94901

Owner/Operator Ind: Current Operator Street No:

Type: Other Street 1: 3100 KERNER BLVD. SUITE B1

Name: BRYAN DUNBAR Street 2:

Date Became Current: City: SAN RAFAEL

 Date Ended Current:
 State:

 Phone:
 415-485-4472

 Country:

Source Type: Implementer Zip Code: 94901

 57
 3 of 5
 ESE
 0.16 /
 5.95 /
 MARIN MECHANICAL II, INC.
 RCRA

 846.11
 1
 3100 KERNER BLVD. SUITE B1
 NON GEN

 SAN RAFAEL CA 94901
 NON GEN

CA

Order No: 24072600476

EPA Handler ID: CAC003012204
Gen Status Universe: No Report
Contact Name: BRYAN DUNBAR

Contact Address: 3100 KERNER BLVD. SUITE B1,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-485-4472

Contact Email: BRYAN.DUNBAR@MARINMECHANICAL.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

 Receive Date:
 20190426

 Location Latitude:
 37.957094

 Location Longitude:
 -122.499563

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: Nο Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: No Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: Nο Used Oil Spec Marketer:

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20190426

Handler Name: MARIN MECHANICAL II, INC.

Source Type: Implementer

Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator Street No:

Type: Other Street 1: 3100 KERNER BLVD. SUITE B1

Name: BRYAN DUNBAR Street 2:

Date Became Current: City: SAN RAFAEL

Date Ended Current: State:

Phone: 415-485-4472 **Country:**

Source Type: Implementer Zip Code: 94901

Owner/Operator Ind: Current Owner Street No:

Type: Other Street 1: 3100 KERNER BLVD. SUITE B1

Name: MARIN MECHANICAL II. INC. Street 2:

Date Became Current:City:SAN RAFAELDate Ended Current:State:CA

 Date Ended Current:
 State:
 Cr

 Phone:
 415-485-4472
 Country:

Source Type: Implementer Zip Code: 94901

 57
 4 of5
 ESE
 0.16/
 5.95/
 MARIN MECHANICAL II INC.
 RCRA

 846.11
 1
 3100 KERNER BLVD. SUITE B1
 NON GEN

Number of Direction Distance Elev/Diff Site DB Map Key

Records

(mi/ft) (ft)

SAN RAFAEL CA 94901

EPA Handler ID: CAC003091540 Gen Status Universe: No Report Contact Name: **BRYAN DUNBAR**

3100 KERNER BLVD. SUITE B1,, SAN RAFAEL, CA, 94901, Contact Address:

Contact Phone No and Ext: 415-485-4472

Contact Email: BRYAN.DUNBAR@MARINMECHANICAL.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Receive Date: 20201105

Location Latitude: Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: Nο Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: Nο Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: Nο

Hazardous Waste Handler Details

Seauence No:

Receive Date: 20201105

Handler Name: MARIN MECHANICAL II INC.

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

3100 KERNER BLVD. SUITE B1 Street 1: Type: Other

Name: MARIN MECHANICAL II, INC. Street 2: Date Became Current:

City: SAN RAFAEL

CA

Order No: 24072600476

Date Ended Current: State:

Phone: 415-485-4472 Country: 94901 Source Type: Implementer Zip Code:

Current Operator Owner/Operator Ind: Street No:

3100 KERNER BLVD. SUITE B1 Type: Other Street 1:

Name: **BRYAN DUNBAR** Street 2:

Date Became Current: SAN RAFAEL City:

Date Ended Current: State: CA

415-485-4472 Phone: Country:

3100 KERNER BLVD SUITE B1

SAN RAFAEL CA 94901

RCRA

Order No: 24072600476

NON GEN

Source Type: Implementer Zip Code: 94901

846.11

57 5 of 5 ESE 0.16 / 5.95 / MARIN MECHANICAL II, INC.

EPA Handler ID:CAC003117409Gen Status Universe:No ReportContact Name:JOHN WISE

Contact Address: 3100 KERNER BLVD, SUITE B1, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-485-4472

Contact Email: BRYAN.DUNBAR@MARINMECHANICAL.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Receive Date: 20210429

Location Latitude: Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: Nο Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: No Commercial TSD: Nο Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: Nο Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20210429

Handler Name: MARIN MECHANICAL II, INC.

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

Type: Other Street 1: 3100 KERNER BLVD

Name: JOHN WISE Street 2: SUITE B1

Date Became Current: City: SAN RAFAEL

Date Ended Current: State: CA

Date Ended Current:State:Phone:415-485-4472Country:

Source Type: Implementer Zip Code: 94901

Owner/Operator Ind: Current Operator Street No:

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft) Other 3100 KERNER BLVD Type: Street 1: JOHN WISE Name: Street 2: SUITE B1 SAN RAFAEL Date Became Current: City: State: Date Ended Current: CA Phone: 415-485-4472 Country: Implementer 94901 Zip Code: Source Type: NNE 0.16/ 4.27/ KERNER CANAL, L.P. **58** 1 of1

— 861.90 0 3301 KERI SAN RAFA

3301 KERNER BLVD.
SAN RAFAEL CA 94901
RCRA
NON GEN

Order No: 24072600476

EPA Handler ID:CAC003251699Gen Status Universe:No ReportContact Name:CORY HIRAGA

Contact Address: 22645 GRAND STREET,, HAYWARD, CA, 94541,

Contact Phone No and Ext: 510-247-8110

Contact Email: CORY.HIRAGA@EDENHOUSING.ORG

Contact Country:

County Name: MARIN EPA Region: 09
Land Type:

Receive Date: 20230914

Location Latitude: Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: Nο Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: Nο Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20230914

Handler Name: KERNER CANAL, L.P.

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

Type: Other Street 1: 22645 GRAND STREET

Name: CORY HIRAGA Street 2:

Date Became Current: City: HAYWARD

Map Key	Number Record		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Date Ended	Current:				State:		CA	
Phone:		510-247-			Country:		04544	
Source Type	9:	Impleme	nter		Zip Code:		94541	
Owner/Oper	ator Ind:	Current 0	Operator		Street No:			
Туре: Name:		Other CORY H	IRAGA		Street 1: Street 2:		22645 GRAND STREET	
vame. Date Becam	e Current:	0011111	II I/ CG/ C		City:		HAYWARD	
Date Ended	Current:	540 04 7	0440		State:		CA	
Phone: Source Type	9:	510-247- Impleme			Country: Zip Code:		94541	
59	1 of7		NNW	0.17/	4.46 /	JK Motors		CUDA MADU
_				872.80	0	51 Belvedere Rafael CA	Street, Suite B, San	CUPA MARII
Permit No:		60-1147			UFC:		No	
Type of Peri	mit:				HWG Tons		0.0	
Cross Ref:		Active			HWG Recy		No	
Status: US Tanks:		Active 0			HWG Type Tiered:	e Gen:	CESQG No	
AG Tanks:		Ö			PBR HHW	•	No	
НМВР:		0			Green:		No	
Cal ARP:		No			Facility Ph	one No:	(415) 453-7939	
<u>59</u>	2 of7		NNW	0.17/ 872.80	4.46 / 0	Aladdins Aut 51 BELVEDE SAN RAFAE	RE STREET	DELISTED HAZ
						SAN NAFALI	- OA 34301	
Latitude: Longitude: Original Sou			379407 37.962245 -122.504020 CHAZ 30-MAY-2017			JAN NAFALI	- OA 34301	
Latitude: Longitude: Original Sou			37.962245 -122.504020 CHAZ	0.17/	4.46/	Aladdins Au	romotive	CUPA MARII
Latitude: Longitude: Original Sou Record Date	e: 		37.962245 -122.504020 CHAZ 30-MAY-2017	0.17/ 872.80	4.46 / 0	Aladdins Au		CUPA MARII
Latitude: Longitude: Original Sou Record Date	e: 	30-0508	37.962245 -122.504020 CHAZ 30-MAY-2017			Aladdins Aut 51 Belvedere Rafael	romotive	CUPA MARII
Latitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri	3 of7	30-0508	37.962245 -122.504020 CHAZ 30-MAY-2017		0 UFC: HWG Tons	Aladdins Aur 51 Belvedere Rafael CA	comotive e Street, Suite B, San No 0.0	CUPA MARII
Latitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri	3 of7		37.962245 -122.504020 CHAZ 30-MAY-2017		0 UFC: HWG Tons HWG Recy	Aladdins Aut 51 Belvedere Rafael CA s: vcle:	comotive c Street, Suite B, San No 0.0 No	CUPA MARII
Latitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status:	3 of7	Inactive	37.962245 -122.504020 CHAZ 30-MAY-2017		0 UFC: HWG Tons HWG Recy HWG Type	Aladdins Aut 51 Belvedere Rafael CA s: vcle:	Pomotive Postreet, Suite B, San No 0.0 No CESQG	CUPA MARII
Latitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks:	3 of7		37.962245 -122.504020 CHAZ 30-MAY-2017		0 UFC: HWG Tons HWG Recy	Aladdins Aut 51 Belvedere Rafael CA s: vcle:	comotive c Street, Suite B, San No 0.0 No	CUPA MARII
Latitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP:	3 of7	Inactive 0 0 0	37.962245 -122.504020 CHAZ 30-MAY-2017		UFC: HWG Tons HWG Recy HWG Type Tiered: PBR HHW. Green:	Aladdins Aut 51 Belvedere Rafael CA s: vcle: e Gen:	No 0.0 No CESQG No No	CUPA MARII
Siteid: Latitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: AG Tanks: HMBP: Cal ARP:	3 of7	Inactive 0 0	37.962245 -122.504020 CHAZ 30-MAY-2017		UFC: HWG Tons HWG Recy HWG Type Tiered: PBR HHW	Aladdins Aut 51 Belvedere Rafael CA s: vcle: e Gen:	No 0.0 No CESQG No No	CUPA MARII
Latitude: Longitude: Congitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP:	3 of7	Inactive 0 0 0	37.962245 -122.504020 CHAZ 30-MAY-2017		UFC: HWG Tons HWG Recy HWG Type Tiered: PBR HHW. Green:	Aladdins Aut 51 Belvedere Rafael CA s: vcle: e Gen: :	No 0.0 No CESQG No No No (415) 453-7939	CUPA MARII
Latitude: Longitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP: Cal ARP:	3 of7	Inactive 0 0 0 No	37.962245 -122.504020 CHAZ 30-MAY-2017	0.17/	UFC: HWG Tons HWG Recy HWG Type Tiered: PBR HHW! Green: Facility Ph	Aladdins Aut 51 Belvedere Rafael CA s: vcle: e Gen: : none No: North Bay Au 51 Belvedere Rafael	No 0.0 No CESQG No No (415) 453-7939	
Latitude: Longitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP: Cal ARP: 59 Permit No:	9: 3 of7 mit: 4 of7	Inactive 0 0 0	37.962245 -122.504020 CHAZ 30-MAY-2017	0.17/	UFC: HWG Tons HWG Type Tiered: PBR HHW. Green: Facility Ph	Aladdins Aut 51 Belvedere Rafael CA s: vole: e Gen: : none No: North Bay Au 51 Belvedere Rafael CA	Pomotive Street, Suite B, San No 0.0 No CESQG No No No (415) 453-7939	
Latitude: Longitude: Longitude: Original Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP: Cal ARP: 59 Permit No: Type of Peri Cross Ref:	9: 3 of7 mit: 4 of7	Inactive 0 0 0 No	37.962245 -122.504020 CHAZ 30-MAY-2017	0.17/	UFC: HWG Tons HWG Recy HWG Tiered: PBR HHW. Green: Facility Ph 4.46 / 0 UFC: HWG Tons HWG Recy	Aladdins Aut 51 Belvedere Rafael CA s: vcle: Gen: Tone No: North Bay Aut 51 Belvedere Rafael CA s:	No 0.0 No CESQG No No (415) 453-7939 Itomotive Street, Suite A, San	
Latitude: Longitude: Longitude: Criginal Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP: Cal ARP: 59 Permit No: Type of Peri Cross Ref: Status: Cross Ref: Status:	9: 3 of7 mit: 4 of7	Inactive 0 0 No 60-1039	37.962245 -122.504020 CHAZ 30-MAY-2017	0.17/	UFC: HWG Tons HWG Recy HWG Type Tiered: PBR HHW. Green: Facility Ph 4.46 / 0 UFC: HWG Tons HWG Recy	Aladdins Aut 51 Belvedere Rafael CA s: vcle: Gen: Tone No: North Bay Aut 51 Belvedere Rafael CA s:	No 0.0 No CESQG No No (415) 453-7939 utomotive • Street, Suite A, San No 0.0 No SQG	
Latitude: Longitude: Longitude: Criginal Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP: Cal ARP: Cross Ref: Status: US Tanks: US Tanks:	9: 3 of7 mit: 4 of7	Inactive 0 0 No No Inactive 0	37.962245 -122.504020 CHAZ 30-MAY-2017	0.17/	UFC: HWG Tons HWG Recy HWG Tiered: PBR HHW. Green: Facility Ph 4.46 / 0 UFC: HWG Tons HWG Recy HWG Type	Aladdins Autority St. Belvedere Rafael CA St. Cole: Gen: Toone No: North Bay Autority Belvedere Rafael CA St. Cole: Gen: Gen: Gen:	No 0.0 No CESQG No No (415) 453-7939 utomotive Street, Suite A, San No 0.0 No SQG No	
Latitude: Longitude: Longitude: Criginal Sou Record Date 59 Permit No: Type of Peri Cross Ref: Status: US Tanks: HMBP: Cal ARP: 59 Permit No: Type of Peri Cross Ref: Status: Cross Ref: Status:	9: 3 of7 mit: 4 of7	Inactive 0 0 No 60-1039	37.962245 -122.504020 CHAZ 30-MAY-2017	0.17/	UFC: HWG Tons HWG Recy HWG Type Tiered: PBR HHW. Green: Facility Ph 4.46 / 0 UFC: HWG Tons HWG Recy	Aladdins Autority St. Belvedere Rafael CA St. Cole: Gen: Toone No: North Bay Autority Belvedere Rafael CA St. Cole: Gen: Gen: Gen:	No 0.0 No CESQG No No (415) 453-7939 utomotive • Street, Suite A, San No 0.0 No SQG	

59 5 of 7 NNW 0.17/ 4.46/ J K Motors

872.80 0 51 Belvedere Street, Suite B, San

Rafael CA

SAN RAFAEL CA 94901

CUPA MARIN

Order No: 24072600476

 Permit No:
 30-0557
 UFC:
 No

 Type of Permit:
 HWG Tons:
 0.0

Type of Permit: HWG Tons:
Cross Ref: HWG Recycle:

No HWG Type Gen: Status: Inactive US Tanks: 0 Tiered: No AG Tanks: 0 PBR HHW: No HMBP: n Green: Nο

Cal ARP: No Facility Phone No: (415) 717-2091

59 6 of7 NNW 0.17/ 4.46/ JK MOTORS RCRA TSD 872.80 0 51 BELVEDERE ST STE B

EPA Handler ID:CAL000410428Gen Status Universe:No ReportContact Name:OWEN MAINA

Contact Address: 51 BELVEDERE ST STE B,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-453-7939

Contact Email: MOWEN10464@ATT.NET

Contact Country: Land Type:

County Name: MARIN
EPA Region: 09
Receive Date: 20150916

 Location Latitude:
 20150916

 Location Longitude:
 37.962345

 -122.503953

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: Nο Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Smelting, Melting and Refining: No **Underground Injection Control:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: Nο Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20150916
Handler Name: JK MOTORS

Federal Waste Generator Code:

Generator Code Description:

Not a Generator, Verified

Source Type: Implementer

TSD Activity:

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

51 BELVEDERE ST STE B Type: Other Street 1:

Name: OWEN MAINA Street 2:

Date Became Current: SAN RAFAEL City: CA

Date Ended Current: State: 415-453-7939 Country:

Phone: Source Type: Implementer Zip Code: 94901

Current Operator Owner/Operator Ind: Street No:

Type: Other Street 1: 51 BELVEDERE ST STE B

Name: **OWEN MAINA** Street 2:

Date Became Current: City: SAN RAFAEL

Date Ended Current: State: 415-453-7939

Phone: Country:

94901 Source Type: Implementer Zip Code:

7 of7 NNW 0.17/ 4.46/ JK MOTORS 59 **RCRA** 872.80 51 BELVEDERE ST STE B **NON GEN**

SAN RAFAEL CA 94901

Order No: 24072600476

EPA Handler ID: CAL000410428 Gen Status Universe: No Report Contact Name: **OWEN MAINA**

51 BELVEDERE ST STE B,, SAN RAFAEL, CA, 94901, Contact Address:

Contact Phone No and Ext: 415-453-7939

MOWEN10464@ATT.NET Contact Email:

Contact Country: County Name: MARIN EPA Region: 09

Land Type:

20150916 Receive Date: 37.962345 Location Latitude:

Location Longitude: -122.503953

Violation/Evaluation Summary

NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records Note:

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: Nο Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No **Used Oil Market Burner:** Nο Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20150916 Handler Name: JK MOTORS Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Current Operator Owner/Operator Ind: Street No:

Type: Other Street 1: 51 BELVEDERE ST STE B

OWEN MAINA Name: Street 2: Date Became Current:

SAN RAFAEL City: Date Ended Current: State: CA

Phone: 415-453-7939 Country: Source Type: Implementer Zip Code: 94901

Current Owner Street No: Owner/Operator Ind:

Other Street 1: 51 BELVEDERE ST STE B Type:

Name: **OWEN MAINA** Street 2:

SAN RAFAEL Date Became Current: City: CA

Date Ended Current: State: 415-453-7939 Country: Phone:

Source Type: Implementer Zip Code: 94901

60 1 of1 Ε 0.17/ 7.81/ Bellam Blvd LF AKA San Rafael LF 885.44 3 31 Windward Way

SWF/LF

Order No: 24072600476

San Rafael CA 94901

21-AA-0048 SWIS No: ARB District: Bay Area Site ID: 1734 SWRCB Region:

San Francisco Bay EPA Fed Regist ID: Site Point of Cont: Dawn Liang

Site Op Status: Site ZIP: 94901 Closed Regulatory Status: County: Marin Unpermitted Latitude: 37.95359 Site is Archived: No

Absorbed on: -122.49025 Longitude: Absorbed by:

No Closed Illegal Aband: Yes Closed Illegal Aband Cat: D Finance Assuran Responsible: No

Incorporated City: San Rafael Local Government: San Rafael Reporting Agency Legal Name: County of Marin

Reporting Agency Department: **Environmental Health Services**

Enforcing Agency Legal Name: County of Marin

Enforcing Agency Department: Environmental Health Services

Site Owners

Site Inert Debris Eng Fill:

Site Type: Disposal Only Started On:

Contact Name: David Bernardi

Contact First Name: David Contact Last Name: Bernardi

Director Of Public Works Contact Title:

Contact Email:

Contact Phone: (415) 485-3085 Owner Name: City Of San Rafael PO Box 151560 Owner Address: Owner City: San Rafael Owner State: CA

Owner Zip Code: 94915-1560

Owner Phone:

Site Activities (Search Result)

Activity Category: Disposal Act Regulat Stat: Unpermitted

Act Opl Status: Closed

Site Name:

Bellam Blvd LF AKA San Rafael LF

Activity:

Solid Waste Disposal Site

Site Operators

Site Type: Disposal Only
Started on:
Contact Name: David Bernardi
Contact First Name: David
Contact Last Name: Bernardi

Contact Title: Director Of Public Works

Contact Email:

Contact Phone: (415) 485-3085 Operator Name: City Of San Rafael

Operator Address: 1400 Fifth Ave., P.O. Box 151560

Operator City:San RafaelOperator State:CAOperator Zip:94915-1560

Operator Phone:

61 1 of1 WSW 0.17/ 7.24/ CAL STEAM A WOLSELEY 887.75 3 COMPANY #2506

25 DODIE ST SAN RAFAEL CA 94901

NON GEN

RCRA

Order No: 24072600476

EPA Handler ID: CAL000421975
Gen Status Universe: No Report
Contact Name: CLAYTON WEST

Contact Address: 25 DODIE ST,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-469-2009

Contact Email: KEN.DURHAM@FERGUSON.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Receive Date: 20161115

Location Latitude: Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** Nο Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No

Used Oil Refiner:NoUsed Oil Burner:NoUsed Oil Market Burner:NoUsed Oil Spec Marketer:No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20161115

Handler Name: CAL STEAM A WOLSELEY COMPANY #2506

Source Type: Implementer

Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator Street No:

Type: Other Street 1: 25 DODIE ST

Name: CLAYTON WEST Street 2:

Date Became Current: City: SAN RAFAEL

 Date Ended Current:
 State:
 CA

 Phone:
 415-469-2009
 Country:

 Phone:
 415-469-2009
 Country:

 Source Type:
 Implementer
 Zip Code:
 94901

Owner/Operator Ind: Current Owner Street No:

Type: Other Street 1: 12500 JEFFERSON AVE

Name: FERGUSON ENTERPRISES LLC Street 2:

Date Became Current: City: NEWPORT NEWS

Date Ended Current: State:

 Phone:
 757-874-7795
 Country:

 Source Type:
 Implementer
 Zip Code:
 23602

Source Type.

999 ANDERSEN DR STE 100 SAN RAFAEL CA 94901

Order No: 24072600476

EPA Handler ID:CAR000004382Gen Status Universe:Small Quantity Generator

Contact Name: DENNIS THOMPSON
Contact Address: DENNIS THOMPSON
999 ANDERSEN DR STE 100 , , SAN RAFAEL , CA, 94901 , US

Contact Address: 999 ANDERSI Contact Phone No and Ext: 415-454-1500

Contact Email:

Contact Country: US
County Name: MARIN
EPA Region: 09
Land Type: Private
Receive Date: 19950718
Location Latitude: 37.954548
Location Longitude: -122.503141

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS;

Compliance Monitoring and Enforcement table dated Apr, 2024.

Evaluation Details

Evaluation Start Date: 20020117

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION

Violation Short Description: Return to Compliance Date:

Evaluation Agency: State Contractor/Grantee

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: Nο **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer:

Hazardous Waste Handler Details

Sequence No:

Receive Date: 19950718

Handler Name: JERRY THOMPSON AND SONS PAINTING

Federal Waste Generator Code:

Generator Code Description: Small Quantity Generator

Source Type: Notification

Owner/Operator Details

Owner/Operator Ind: Current Owner Street No:

Type: Private Street 1: 999 ANDERSEN DR STE 100

Name: JERRY THOMPSON AND SONS MGMT Street 2:

Date Became Current: City: SAN RAFAEL

Date Ended Current: State: CA

 Phone:
 415-454-1500
 Country:

 Source Type:
 Notification
 Zip Code:
 94901

63 1 of 1 WSW 0.17/ 7.87/ Simms Street Pump Station 901.19 3 40 Simms Street, San Rafael CA

ermit No: 30-0650 UFC: No

Permit No: 30-0650 No Type of Permit: **HWG Tons:** 0.0 Cross Ref: HWG Recycle: No Status: Active HWG Type Gen: US Tanks: Tiered: 0 No PBR HHW: AG Tanks: 0 No HMBP: Green: Nο

Cal ARP: No **Facility Phone No:** (415) 454-4001

 64
 1 of 2
 NNW
 0.17/
 3.75/
 Rodcar Auto Repair
 CUPA MARIN

 901.26
 -1
 121 Verdi Street, San Rafael
 CUPA MARIN

CA

 Permit No:
 30-0519
 UFC:
 No

 Type of Permit:
 HWG Tons:
 0.0

 Cross Ref:
 HWG Recycle:
 No

 Status:
 Inactive
 HWG Type Gen:

 Status:
 Inactive
 HWG Type Gen:

 US Tanks:
 0
 Tiered:
 No

 AG Tanks:
 0
 PBR HHW:
 No

 HMBP:
 0
 Green:
 No

Cal ARP: No *Facility Phone No:* (415) 455-9272

NNW 0.17/ 3.75/ PERUVA AUTO REPAIR 2 of2 64

901.26 -1 121 VERDI ST **RCRA**

NON GEN SAN RAFAEL CA 94901-4714

CAL000344677 EPA Handler ID: Gen Status Universe: No Report Contact Name: LUIS ARCOS

Contact Address: 61 DRAKEWOOD LN,, NOVATO, CA, 94901-3841,

Contact Phone No and Ext: 415-261-0707

LUISARCOS2010@ATT.NET Contact Email:

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

20090708 Receive Date: Location Latitude: 37.962021 -122.504799 Location Longitude:

Violation/Evaluation Summary

NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records Note:

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: Nο Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: No Commercial TSD: Nο Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: Nο Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20090708

PERUVA AUTO REPAIR Handler Name:

Source Type: Implementer

Federal Waste Generator Code:

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Operator** Street No:

61 DRAKEWOOD LN Type: Other Street 1:

CA

Order No: 24072600476

LUIS ARCOS Name: Street 2: **NOVATO** Date Became Current: City:

Date Ended Current: State: 415-261-0707 Phone: Country:

Source Type: 94901-3841 Implementer Zip Code:

Owner/Operator Ind: **Current Owner** Street No:

Map Key	Number Record		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Туре:		Other			Street 1:		61 DRAKEWOOD LN	
Name:		LUIS AR	cos		Street 2:		NOVATO	
Date Becam Date Ended					City: State:		NOVATO CA	
Phone:	Current.	415-261-	0707		Country:		CA	
Source Type	e:	Implemer			Zip Code:		94901-3841	
<u>65</u>	1 of5		wsw	0.17/ 917.16	10.43 / 6	Bellam Au 22 Bellam San Rafae CA	uto Repair Boulevard, Suite B2, el	CUPA MARII
Permit No:		30-0309			UFC:		No	
Type of Perr	nit:				HWG Tons	s <i>:</i>	0.0	
Cross Ref:					HWG Recy	/cle:	No	
Status:		Active			HWG Type	Gen:	SQG	
US Tanks:		0			Tiered:		No	
AG Tanks:		0			PBR HHW	<i>:</i>	No	
HMBP:		2			Green:		No (445) 450 0000	
Cal ARP:		No			Facility Ph	ione No:	(415) 459-9283	
<u>65</u>	2 of5		WSW	0.17/ 917.16	10.43 / 6		Auto Body Boulevard, Suite D, San	CUPA MARII
Permit No:		30-0248			UFC:		No	
Type of Perr	mit:	00 02 10			HWG Tons	s:	0.0	
Cross Ref:					HWG Recy		No	
Status:		Active			HWG Type		4	
US Tanks:		0			Tiered:		No	
AG Tanks:		0			PBR HHW	:	No	
НМВР:		0			Green:		No	
Cal ARP:		No			Facility Ph	one No:	(415) 456-6324	
<u>65</u>	3 of5		wsw	0.17/ 917.16	10.43 / 6	22 BELLA	AUTO BODY M BLVD STE D AEL CA 94901	EMISSIONS
2008 Criteria	a Data							
Facility ID:		18998			CERR Cod	le:		
Facility SIC	Code:	7532			TOGT:		1.503	
CO:		21			ROGT:		1.27895	
Air Basin:		SF			COT:			
District:		BA			NOXT:			
COID:		MRN			SOXT:			
DISN: CHAPIS:		BAY ARE	ea aqmd		PMT: PM10T:			
2008 Toxic L	<u>Data</u>							
Facility ID:		18998			COID:		MRN	
Facility SIC	Code:	7532			DISN:		BAY AREA AQMD	
CO:		21			CHAPIS:			
Air Basin:		SF BA			CERR Cod	ie:		
District: TS:		DA						
15: Health Risk Non-Cancer		az Ind:						

2009 Criteria Data

Facility ID: 18998 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 1.503

 CO:
 21
 ROGT:
 1.27895

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

 CHAPIS:
 PM10T:

2009 Toxic Data

Facility ID: 18998 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

TS: Health Risk Asmt:

District:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

2010 Toxic Data

Facility ID: 18998 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

 District:
 BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2011 Criteria Data

Facility ID: 18998 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 .094

 CO:
 21
 ROGT:
 .0877778

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

 CHAPIS:
 PM10T:

2011 Toxic Data

Facility ID: 18998 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

Order No: 24072600476

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

2012 Criteria Data

Facility ID: 18998 CERR Code:

Мар Кеу	Number Records		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	7532 21 SF BA MRN BAY ARE	ea aqmd		TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:		.094 .0877778	
2012 Toxic L	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk . Non-Cancer Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2013 Criteria	a Data							
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	18998 7532 21 SF BA MRN BAY ARE	ea aqmd		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	.094 .0877778	
2013 Toxic L	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk (Non-Cancer Non-Cancer	Asmt: Chronic Ha				COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
2014 Criteria	a Data							
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	18998 7532 21 SF BA MRN BAY ARE	ea aqmd		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	.093908168	
2014 Toxic L	<u>Data</u>							
Facility ID: Facility SIC (CO: Air Basin: District: TS: Health Risk (18998 7532 21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	

CERR Code:

TOGT:

ROGT:

COT:

NOXT:

SOXT:

PM10T:

COID:

DISN:

CHAPIS:

PM10T:

AH Index:

CERR Code:

PMT:

.093908171

.093908171

MRN

BAY AREA AQMD

Order No: 24072600476

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2015 Criteria Data

Facility ID: 18998 Facility SIC Code: 7532

21 Air Basin: SF

District: BA COID: MRN

BAY AREA AQMD DISN:

CHAPIS:

2015 Toxic Data

Facility ID: 18998

BA

Facility SIC Code: 7532 21 Air Basin: SF

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2016 Criteria Data

Facility ID: 18998 **CERR CODE:**

Facility SIC Code: 7532 .093908168 TOGT: CO: 21 ROGT: .087591814174

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT:

CHAPIS:

2016 Toxic Data

Facility ID: 18998 TS: Facility SIC Code: 7532 HRA: CH Index:

CERR CODE:

MRN COID: 21

SF CO: Air Basin: DISN: **BAY AREA AQMD** District: ВА

CHAPIS:

2017 Criteria Data

Facility ID: 18998 **CERR Code:**

Facility SIC Code: 7532 TOGT: .09246166 .086214378782 CO: 21 ROGT:

Air Basin: SF COT: District: BA NOXT: COID: MRN SOXT:

DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T:

2017 Toxic Data

Facility ID: 18998 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft) CHAPIS: CO: 21 Air Basin: SF **CERR Code:** District: BA TS: Health Risk Asmt: Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind: 2018 Criteria Data Facility ID: 18998 **CERR Code:** Facility SIC Code: .092523014 7532 TOGT: CO: 21 ROGT: .0862715872136 Air Basin: SF COT: District: ВА NOXT: COID: MRN SOXT: DISN: **BAY AREA AQMD** PMT: CHAPIS: PM10T: 2018 Toxic Data Facility ID: 18998 COID: MRN Facility SIC Code: 7532 DISN: **BAY AREA AQMD** CO: 21 CHAPIS: Air Basin: SF **CERR Code:** District: ВА TS: Health Risk Asmt: Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind: 2019 Criteria Data CO: CHAPIS: 21 Air Basin: SF **CERR Code:** Facility ID: 18998 ROGT: .0862715872136

 District:
 BA
 COT:

 Facility SIC Code:
 7532
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD

PM10T:

TOGT: .092523014

PMT:

2019 Toxic Data

CO: 21 DISN: BAY AREA AQMD

 Air Basin:
 SF
 CHAPIS:

 Faccility ID:
 18998
 CERR Code:

 District:
 BA
 TS:

Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Toxic Data

Co: 21 DISN: BAY AREA AQMD

Order No: 24072600476

 Air Basin:
 SF
 CHAPIS:

 Facility ID:
 18998
 Cerr Code:

 District:
 BA
 TS:

Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Criteria Data

 Co:
 21
 CHAPIS:

 Air Basin:
 SF
 Cerr Code:

Facility ID: 18998 **ROGT:** .091041580239

 District:
 BA
 COT:

 Facility SIC Code:
 7532
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD **TOGT:** .09246166

PMT: PM10T:

65 4 of5 WSW 0.17/ 10.43/ BELLAM AUTO REPAIR 917.16 6 22 BELLAM

917.16 6 22 BELLAM SAN RAFAEL CA 94901-0000 **RCRA**

Order No: 24072600476

NON GEN

EPA Handler ID:CAL000158952Gen Status Universe:No ReportContact Name:BINH NGUYEN

Contact Address: 22 BELLAM BLVD,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-459-9283

Contact Email: BINHHNGUYEN@SBCGLOBAL.NET

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

 Receive Date:
 19950303

 Location Latitude:
 37.958382

 Location Longitude:
 -122.506749

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: Nο Furnace Exemption: No Underground Injection Activity: No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No **Used Oil Market Burner:** No No Used Oil Spec Marketer:

Hazardous Waste Handler Details

Sequence No: 1

Receive Date: 19950303

Handler Name: BELLAM AUTO REPAIR

Source Type: Implementer

Number of Direction Elev/Diff Site DB Map Key Distance Records (mi/ft) (ft)

Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Date Ended Current:

Current Owner Street No: Owner/Operator Ind:

Type: Other Street 1: 22 BELLAM BLVD

BINH NGUYEN Name: Street 2: Date Became Current:

SAN RAFAEL City:

State:

415-459-9283 Phone: Country: Source Type: Implementer Zip Code: 94901-5312

Owner/Operator Ind: **Current Operator** Street No:

22 BELLAM BLVD Type: Other Street 1:

BINH NGUYEN Name: Street 2:

Date Became Current: SAN RAFAEL City:

Date Ended Current: State: CA 415-459-9283 Country: Phone:

Source Type: Implementer Zip Code: 94901

WSW GEORGE'S AUTO BODY 65 5 of 5 0.17/ 10.43/

RCRA 22 D BELLAM BLVD 917.16 6 **NON GEN** SAN RAFAEL CA 94901

EPA Handler ID: CAL000311572 Gen Status Universe: No Report Contact Name: JENNÝ QUIROZ

Contact Address: 22 D BELLAM BLVD,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-456-6324

Contact Email: Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

Receive Date: 20060915 Location Latitude: 37.958382 -122.506749 Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

Order No: 24072600476

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: Nο Furnace Exemption: No **Underground Injection Activity:** No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: Nο Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Sequence No:

20060915 Receive Date:

GEORGE'S AUTO BODY Handler Name:

Source Type: Implementer

Federal Waste Generator Code: Ν

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: **Current Operator** Street No:

Type: Other Street 1: 22 D BELLAM BLVD

Name: JENNY QUIROZ Street 2:

SAN RAFAEL Date Became Current: City: Date Ended Current: State: CA

Phone: 415-456-6324 Country:

Zip Code: 94901 Source Type: Implementer

Current Owner Owner/Operator Ind: Street No:

Type: Other Street 1: CANDIDO J QUIROZ

CANDIDO J QUIROZ Name: Street 2: Date Became Current: City:

SAN RAFAEL Date Ended Current: State: CA

415-456-6324 Country: Phone: 94901-0000 Source Type: Implementer Zip Code:

NNW 0.18/ 3.86/ 66 1 of2 Anthonys Auto Craft

CUPA MARIN 924.49 -1 100 Lisbon Street, San Rafael CA

No

SAN RAFAEL CA 94901-4761

Order No: 24072600476

Permit No: 60-0896 UFC:

HWG Tons: 0.0 Type of Permit: HWG Recycle: Cross Ref: No

Status: Active HWG Type Gen: 4 No US Tanks: Tiered: 0 AG Tanks: 0 PBR HHW: No HMBP: Green: 5 No

Cal ARP: No Facility Phone No: (415) 456-7591

NNW 0.18/ ANTHONYS AUTO CRAFT INC 66 2 of2 3.86/ **RCRA** 924.49 100 LISBON ST -1 **NON GEN**

CAL000350426 EPA Handler ID: Gen Status Universe: No Report

Contact Name: **TODD BALLENGER**

103 VERDI ST,, SAN RAFAEL, CA, 94901, Contact Address:

Contact Phone No and Ext: 415-456-7591

AACRAFT@SBCGLOBAL.NET Contact Email:

Contact Country:

County Name: MARIN EPA Region: 09

Land Type: 20100225 Receive Date: Location Latitude: 37.961982 Location Longitude: -122.504598

Violation/Evaluation Summary

NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records Note:

associated with this facility (EPA ID).

Handler Summary

Мар Кеу	Number o Records	of	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Importer Active Mixed Waste Transporter Active Transfer Facili Onsite Burner Furnace Exemunder Grand Commercial Toused Oil Tranused Oil Prodused Oil Refit Used Oil Mark Used Oil Special Special Mixed Oil Special Transport	Generator: Activity: Ity: r Exemption: Injection Ac rSD: ssporter: ssfer Facility: tessor: ner: tes: tes:	tivity:	No N					
Hazardous W. Sequence No Receive Date: Handler Name Source Type: Federal Waste Generator Co	: : e: e Generator (Code:	1 20100225 ANTHONYS AU Implementer N Not a Generator	JTO CRAFT INC r, Verified				
Owner/Opera	tor Details							
Owner/Operat Type: Name: Date Became Date Ended C Phone: Source Type:	Current: Current:	Current C Other FODD BA 115-456- mplemer	ALLENGER 7591		Street No. Street 1: Street 2: City: State: Country: Zip Code:		103 VERDI ST SAN RAFAEL CA 94901	
Owner/Operat Type: Name: Date Became Date Ended C Phone: Source Type:	Current:	Current C Other ROY CAF 415-456- mplemer	RNEVALE		Street No. Street 1: Street 2: City: State: Country: Zip Code:		103 VERDI ST SAN RAFAEL CA 94901-4714	
<u>67</u>	1 of1		wsw	0.18/	7.78/	The Darki	room	CUPA MARIN

CUPA MARIN 937.55 41 Simms Street, San Rafael 3 CA

Permit No: 30-0214 UFC: No Type of Permit: **HWG Tons:** 0.0 Cross Ref: HWG Recycle: No Inactive Status: HWG Type Gen: US Tanks: Tiered: 0 No AG Tanks: 0 PBR HHW: No

HMBP: 0 Green: No Cal ARP: No Facility Phone No: (415) 457-2770

1 of4 NW 0.18/ Anthony's Auto Craft, Inc. **68** 4.64/ **CUPA MARIN** 946.14 0 103 Verdi Street, San Rafael CA

> 30-0070 UFC: No

Permit No: Type of Permit: **HWG Tons:** 0.0 Cross Ref: HWG Recycle: No

Мар Кеу	Numbe Record		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB	
Status: US Tanks: AG Tanks: HMBP: Cal ARP:	Active 0 0 4 No				HWG Type Gen: SQG Tiered: No PBR HHW: No Green: No Facility Phone No: (415) 456-7591		No No No		
68	2 of4		NW	0.18 / 946.14	4.64 / 0	103 VERD	''S AUTO CRAFT INC I STREET AEL CA 94901	EMISSIONS	
1990 Criteria	n Data								
Facility ID: Facility SIC of CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	4816 7532 21 SF BA MRN BAY AF	REA AQMD		CERR C TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	1 .96676		
<u>1990 Toxic L</u>	<u>Data</u>								
Facility ID: Facility SIC (CO: Air Basin: District: TS:	Code:	4816 7532 21 SF BA			COID: DISN: CHAPIS CERR C		MRN BAY AREA AQMD		
Health Risk Non-Cancer Non-Cancer	Chronic Ha								
1995 Criteria	n Data								
Facility ID: Facility SIC of CO: Air Basin: District: COID: DISN: CHAPIS:	Code:	4816 7532 21 SF BA MRN BAY AF	REA AQMD		CERR C TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	ode:	1.4 1.3446		
<u>1995 Toxic L</u>	<u>Data</u>								
Facility ID: Facility SIC CO: Air Basin: District: TS: Health Risk	Asmt:	4816 7532 21 SF BA			COID: DISN: CHAPIS CERR C		MRN BAY AREA AQMD		
Non-Cancer Non-Cancer									
1996 Criteria	<u>Data</u>								
Facility ID: Facility SIC	Code:	4816 7532			CERR C TOGT:	ode:	1.4		

Order No: 24072600476

Мар Кеу	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN BAY	AREA AQMD		ROGT: COT: NOXT: SOXT: PMT: PM10T:		1.3446	
<u>1996 Toxic I</u>	<u>Data</u>						
	21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
Non-Cancer	Acute naz ma:						
1997 Criteria Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	4816 Code: 7532 21 SF BA MRN	AREA AQMD		CERR Co TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	1.6 1.53352	
<u>1997 Toxic I</u>	<u>Data</u>						
	21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	
1998 Criteria	a Data						
Facility ID: Facility SIC CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	AREA AQMD		CERR CO TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	2.8 2.73352	
<u>1998 Toxic I</u>	<u>Data</u>						
Facility ID: Facility SIC CO: Air Basin: District: TS: Health Risk Non-Cancer	21 SF BA			COID: DISN: CHAPIS: CERR Co	de:	MRN BAY AREA AQMD	

Order No: 24072600476

Non-Cancer Acute Haz Ind:

1999 Criteria Data

Facility ID: 4816 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 2.896

 CO:
 21
 ROGT:
 2.4482338

 CO:
 21
 ROGT:
 2.4482

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

DISN: BAY AREA AQMD PMT: CHAPIS: PM10T:

1999 Toxic Data

Facility ID: 4816 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: BA

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2000 Criteria Data

Facility ID: 4816 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 2.896

 CO:
 21
 ROGT:
 2.44

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

DISN: BAY AREA AQMD PMT: Chapis: PM10T:

2000 Toxic Data

Facility ID: 4816 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

BA

2001 Criteria Data

Facility ID: 4816 CERR Code:

 Facility SIC Code:
 7532
 TOGT:
 2.86

 CO:
 21
 ROGT:
 2.42

 CO:
 21
 ROGT:

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AOMD
 PMT:

DISN: BAY AREA AQMD PMT:
CHAPIS: PM10T:

2001 Toxic Data

Facility ID: 4816 COID: MRN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff Sit	e e	DB
Facility SIC Co CO: Air Basin: District: TS: Health Risk A: Non-Cancer C Non-Cancer A	21 SF BA smt: Chronic Haz Ind:			DISN: CHAPIS: CERR Code:	BAY AREA AQMD	
2002 Criteria I	<u>Data</u>					
Facility ID: Facility SIC Co CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	AREA AQMD		CERR Code: TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	2.866 2.4275396 .014 .054 0 .001	
2002 Toxic Da	n <u>ta</u>					
Facility ID: Facility SIC CO CO: Air Basin: District: TS: Health Risk A Non-Cancer C Non-Cancer A	21 SF BA smt: Chronic Haz Ind:			COID: DISN: CHAPIS: CERR Code:	MRN BAY AREA AQMD	
2003 Criteria I	<u>Data</u>					
Facility ID: Facility SIC Co CO: Air Basin: District: COID: DISN: CHAPIS:	21 SF BA MRN	AREA AQMD		CERR Code: TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	1.425 1.22 .016 .068 0 .002	
2003 Toxic Da	nta					
Facility ID: Facility SIC CC CO: Air Basin: District: TS: Health Risk A: Non-Cancer A	21 SF BA smt: Chronic Haz Ind:			COID: DISN: CHAPIS: CERR Code:	MRN BAY AREA AQMD	
2004 Criteria I	<u>Data</u>					
Facility ID: Facility SIC Co CO: Air Basin: District: COID:	4816 7532 21 SF BA MRN			CERR Code: TOGT: ROGT: COT: NOXT: SOXT:	3.908 3.5076986 .016 .066 0	

Order No: 24072600476

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

DISN: **BAY AREA AQMD** PMT: .002 CHAPIS: PM10T: .001148

2004 Toxic Data

Facility ID: 4816 COID: MRN

Facility SIC Code: DISN: **BAY AREA AQMD** 7532

21 CHAPIS: Air Basin: SF **CERR Code:**

District: ВА

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2005 Criteria Data

4816 Facility ID: **CERR Code:**

Facility SIC Code: 7532 1.566 TOGT: CO: 21 ROGT: 1.3813792 Air Basin: SF COT: .016 District: BA NOXT: .064 COID: MRN SOXT: 0 DISN:

BAY AREA AQMD PMT: .002 CHAPIS: .001148 PM10T:

2005 Toxic Data

Facility ID: 4816 COID: MRN

Facility SIC Code: 7532 DISN: BAY AREA AQMD

CHAPIS: CO: 21 Air Basin: SF **CERR Code:** District: BA

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2006 Criteria Data

4816 Facility ID: CERR Code:

Facility SIC Code: 7532 TOGT: 1.322 1.1762605 CO: 21 ROGT: SF COT: Air Basin: .017 District: ВА NOXT: .066 COID: MRN SOXT: O

BAY AREA AQMD .002 DISN: PMT: CHAPIS: PM10T: .001148

2006 Toxic Data

Facility ID: 4816 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

Order No: 24072600476

CHAPIS: CO: 21 Air Basin: SF **CERR Code:**

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

ВА

2007 Criteria Data

Мар Кеу	Number of Records	f Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code: 75 2' S B M			CERR Coc TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	2.25 2.0651784 .011 .044 0 .001	
2007 Toxic L	<u>Data</u>						
	Code: 75 2 S B	F A <i>nd:</i>		COID: DISN: CHAPIS: CERR Cod	de:	MRN BAY AREA AQMD	
2008 Criteria	a Data						
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code: 75 2' S B M			CERR Cod TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	1.238 1.1453174 .012 .046 0 0	
2008 Toxic L	<u>Data</u>						
	Code: 75 2' S B	F A <i>nd:</i>		COID: DISN: CHAPIS: CERR Coo	de:	MRN BAY AREA AQMD	
2009 Criteria	a Data						
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code: 79 2' S B M	F		CERR Coo TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	de:	1.303 .9718134 .01 .042 0	
2009 Toxic L	<u>Data</u>						
Facility ID: Facility SIC (CO: Air Basin: District:		F		COID: DISN: CHAPIS: CERR Coo	de:	MRN BAY AREA AQMD	

Order No: 24072600476

PMT:

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2010 Toxic Data

Facility ID: 4816 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: CHAPIS: 21 Air Basin: SF **CERR Code:**

District: BA

TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2011 Criteria Data

CERR Code: Facility ID: 4816

Facility SIC Code: 7532 TOGT: .558 .4986194 CO: 21 ROGT: Air Basin: SF COT: .016 District: BA NOXT: .06 MRN 0 COID: SOXT:

DISN: **BAY AREA AQMD**

00348432055749128919860627177700348432

0558

CHAPIS: PM10T: .002

2011 Toxic Data

4816 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

co: CHAPIS: 21 Air Basin: SF **CERR Code:** ВА

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2012 Criteria Data

Facility ID: 4816 **CERR Code:**

Facility SIC Code: 7532 TOGT: .558 CO: 21 ROGT: .4986194 Air Basin: SF COT: .016 District: BA NOXT: .06 COID: MRN SOXT: 0

DISN: **BAY AREA AQMD** PMT:

00348432055749128919860627177700348432

0558

CHAPIS: PM10T: .002

2012 Toxic Data

Facility ID: 4816 COID: MRN

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: 21 CHAPIS: Air Basin: SF CERR Code:

District: ВА

TS:

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2013 Criteria Data

CERR Code: Facility ID: 4816

Facility SIC Code: 7532 TOGT: .932 .7993666 CO: 21 ROGT: Air Basin: SF COT: .018 District: BA NOXT: .072 COID: MRN SOXT: 0 **BAY AREA AQMD** PMT: .002

DISN: CHAPIS: PM10T: .002

2013 Toxic Data

4816 COID: Facility ID: MRN

Facility SIC Code: DISN: 7532 **BAY AREA AQMD**

CO: 21 CHAPIS: Air Basin: SF **CERR Code:**

District: BA TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2014 Criteria Data

Facility ID: 4816 **CERR Code:**

Facility SIC Code: 7532 TOGT: 1.020115542

CO: 21 ROGT: Air Basin: SF COT:

.01518 District: ВА NOXT: .060820168 COID: MRN SOXT: .000246458

DISN: **BAY AREA AQMD** .001301142 PMT: CHAPIS: PM10T: .001301142

2014 Toxic Data

4816 COID: MRN Facility ID:

Facility SIC Code: 7532 DISN: **BAY AREA AQMD**

CO: 21 CHAPIS: SF Air Basin: **CERR Code:**

District: TS:

Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

ВА

2015 Criteria Data

Facility ID: 4816 CERR Code:

Facility SIC Code: 1.020115492 7532 TOGT: ROGT: 1.019291246 CO: 21 Air Basin: SF COT: .01518 District: BΑ NOXT: .06082016 SOXT: .000246458 COID: MRN

.001301142 DISN: **BAY AREA AQMD** PMT: .001301142 CHAPIS: PM10T:

2015 Toxic Data

Мар Кеу	Number of Records	Direction	Distance (mi/ft)	Elev/Diff Site (ft)		DB
	Code: 79 21 S B	F A <i>nd:</i>		COID: DISN: CHAPIS: CERR Code:	MRN BAY AREA AQMD	
2016 Criteria	<u>Data</u>					
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code: 79 2' S B M	F		CERR CODE: TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	.599167162 .4830750893218 .035759994 .143275972 .000580586 .003065142	
2016 Toxic D	<u> Pata</u>					
Facility ID: Facility SIC (CERR CODE COID: CO: DISN: CHAPIS:	Code: 75 i: M 2	816 532 IRN 1 AY AREA AQMD		TS: HRA: CH Index: AH Index: Air Basin: District:	SF BA	
2018 Criteria	Data					
Facility ID: Facility SIC (CO: Air Basin: District: COID: DISN: CHAPIS:	Code: 79 2' S B M	F		CERR Code: TOGT: ROGT: COT: NOXT: SOXT: PMT: PM10T:	.616608091 .4852287841582 .04497649 .180202813 .000730222 .003855128	
2018 Toxic D	<u> Data</u>					
	Code: 79 2° S B	F A <i>nd:</i>		COID: DISN: CHAPIS: CERR Code:	MRN BAY AREA AQMD	
2019 Criteria	<u>Data</u>					
CO: Air Basin: Facility ID: District: Facility SIC (CO ID:	B. Code: 75	F 816		CHAPIS: CERR Code: ROGT: COT: NOXT: SOXT:	.6449011456854	

Order No: 24072600476

DISN: BAY AREA AQMD

PM10T:

TOGT: .652800026

PMT:

2019 Toxic Data

CO: 21 DISN: BAY AREA AQMD

Air Basin:SFCHAPIS:Faccility ID:4816CERR Code:

District: BA TS:
Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2020 Criteria Data

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

Facility ID: 4816 **ROGT:** .6449011456854

 District:
 BA
 COT:

 Facility SIC Code:
 7532
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD

TOGT: .652800026 **PMT:**

PM10T:

2020 Toxic Data

CO: 21 DISN: BAY AREA AQMD

 Air Basin:
 SF
 CHAPIS:

 Facility ID:
 4816
 CHERR Code:

District: BA TS:

Facility SIC Code: 7532 Health Risk Asmt: COID: MRN

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Toxic Data

Co: 21 DISN: BAY AREA AQMD

 Air Basin:
 SF
 CHAPIS:

 Facility ID:
 4816
 Cerr Code:

 District:
 BA
 TS:

Facility SIC Code: 7532 Health Risk Asmt:

COID: MRN
Non-Cancer Chronic Haz Ind:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

2021 Criteria Data

 Co:
 21
 CHAPIS:

 Air Basin:
 SF
 Cerr Code:

Facility ID: 4816 **ROGT:** 1.4661424314918

Order No: 24072600476

 District:
 BA
 COT:

 Facility SIC Code:
 7532
 NOXT:

 CO ID:
 MRN
 SOXT:

DISN: BAY AREA AQMD **TOGT:** 1.484100042

PMT: PM10T:

 68
 3 of 4
 NW
 0.18 /
 4.64 /
 ANTHONY'S AUTO CRAFT
 RCRA SQG

 946.14
 0
 103 VERDI ST
 RCRA SQG

SAN RAFAEL CA 94901

EPA Handler ID: CAD981416647

Gen Status Universe: Small Quantity Generator
Contact Name: ENVIRONMENTAL MANAGER

Contact Address: 103 VERDI ST,, SAN RAFAEL, CA, 94901, US

Contact Phone No and Ext: 415-456-7591

Contact Email:

Contact Country:USCounty Name:MARINEPA Region:09Land Type:OtherReceive Date:19860603Location Latitude:37.961734Location Longitude:-122.505092

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: Nο Onsite Burner Exemption: No Furnace Exemption: No **Underground Injection Activity:** Nο Commercial TSD: No Used Oil Transporter: Nο Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: Nο Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 19860603

Handler Name: ANTHONY'S AUTO CRAFT

Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Source Type: Notification

Owner/Operator Details

Owner/Operator Ind: Current Operator Street No:

Type:PrivateStreet 1:NOT REQUIREDName:NOT REQUIREDStreet 2:Date Became Current:City:NOT REQUIRED

Date Became Current:City:NODate Ended Current:State:ME

Phone: 415-555-1212 Country:

Source Type: Notification Zip Code: 99999

Owner/Operator Ind: Current Owner Street No:

Type: Private Street 1: NOT REQUIRED

Order No: 24072600476

Мар Кеу	Number Records		Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
Name: Date Became Date Ended (R CARN			Street 2: City: State:		NOT REQUIRED ME	
Phone: Source Type:	:	415-555 Notificati			Country Zip Code		99999	
<u>68</u>	4 of4		NW	0.18 / 946.14	4.64 / 0	103 VERD	''S AUTO CRAFT I ST AEL CA 949010000	HAZ TSD
EPA ID:		CAD981	416647		Facility	County:	21	
Facility Stree Details DTSC Handler Profi	: HWTS:		Code, its describttps://hwts.dts		County: ances Control (DT al amounts in its H	SC) makes av	Marin railable a Waste Code Matrix sho ste Tracking System:	owing each Waste
<u>69</u>	1 of2		WSW	0.18 / 946.60	10.35 / 6		pa Boulevard, San Rafael	CUPA MARIN
Permit No: Type of Perm	nit:	30-0510			UFC: HWG To		No 0.0	
Cross Ref: Status:		Inactive			HWG Re HWG Ty	•	No	
US Tanks:		0			Tiered:	be den.	No	
AG Tanks: HMBP:		0 0			PBR HH Green:	W:	No No	
Cal ARP:		No				Phone No:	NO	
<u>69</u>	2 of2		WSW	0.18 / 946.60	10.35 / 6	Transmiss	inc. dba Cottman sions Boulevard, San Rafael	CUPA MARIN
Permit No:		30-0374			UFC:		No	
Type of Perm	nit:	30-0374			HWG To	ns:	0.0	
Cross Ref:		la a ationa			HWG Re		No	
Status: US Tanks:		Inactive 0			HWG Ty Tiered:	pe Gen:	No	
AG Tanks:		0			PBR HH	W:	No	
HMBP: Cal ARP:		0 No			Green: Facility	Phone No:	No (415) 460-6611	
<u>70</u>	1 of2		NW	0.18 / 955.78	4.36 / 0	111 VERD	AUTOMOTIVE I ST AEL CA 94901	RCRA SQG
EPA Handler Gen Status U Contact Nam Contact Phoi Contact Ema Contact Cour County Name EPA Region: Land Type: Receive Date Location Lati Location Lon	Iniverse: e: ress: ne No and l il: ntry: e:	Ext:	CAD98365117 Small Quantity STEVEN TRAI 59 LADDERM/ 415-457-5868 US MARIN 09 Other 19921022 37.961896 -122.504912	Generator	BRAE , CA, 9490			

Order No: 24072600476

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS;

Compliance Monitoring and Enforcement table dated Apr, 2024.

Evaluation Details

Evaluation Start Date: 19990923

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION

Violation Short Description: Return to Compliance Date:

Evaluation Agency: State Contractor/Grantee

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: Nο Furnace Exemption: No Underground Injection Activity: No Commercial TSD: No Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: No Used Oil Burner: No **Used Oil Market Burner:** No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Seauence No:

Receive Date: 19921022

Handler Name: IMPERIAL AUTOMOTIVE

Federal Waste Generator Code:

Small Quantity Generator Generator Code Description:

Notification Source Type:

Owner/Operator Details

Owner/Operator Ind: **Current Owner** Street No:

Private Street 1: 59 LADDERMAN LN Type:

Name: STEVEN H TRAIGER Street 2: Date Became Current: City:

Date Ended Current: State: CA

Phone: 415-461-2401 Country: Notification 94904 Zip Code:

Source Type:

70 2 of2 NW 0 18 / 4.36 / Imperial Automotive **CUPA MARIN** 955.78 111 Verdi Street, San Rafael 0

CA

GREENBRAE

Order No: 24072600476

UFC: Permit No: 30-0241 No Type of Permit: HWG Tons: 0.0

Cross Ref: HWG Recycle: Nο Status: Active HWG Type Gen: SQG US Tanks: 0 Tiered: No AG Tanks: 0 PBR HHW: No

HMBP: 5 Green: No

Cal ARP: (415) 457-5868 Facility Phone No:

Map Key	Numb Recor												Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
<u>71</u>	1 of1		WNW	0.18 / 956.56	4.46 / 0		et Properties isco Boulevard, San	CUPA MARIN										
Permit No:		30-0366			UFC:		No											
Type of Peri	mit:				HWG To	ns:	0.0											
Cross Ref:					HWG Re	cycle:	No											
Status:		Inactive			HWG Ty													
US Tanks:		0			Tiered:		No											
AG Tanks:		0			PBR HH	W:	No											
HMBP:		0			Green:		No											
Cal ARP:		No			Facility I	Phone No:												
72	1 of1		N	0.18/	5.07/	BILL'S SE	RVICE CO	RCRA SQG										

40 BELVEDERE SAN RAFAEL CA 94901 RCRA SQG

Order No: 24072600476

EPA Handler ID: CAD981386188

Gen Status Universe: Small Quantity Generator

Contact Name:

US Contact Address:

Contact Phone No and Ext:

Contact Email:

US Contact Country: County Name: MARIN EPA Region: 09 Land Type:

19960901 Receive Date: Location Latitude: 37.96322 Location Longitude: -122.505465

Violation/Evaluation Summary

NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records Note:

associated with this facility (EPA ID).

962.31

Handler Summary

Importer Activity: No Mixed Waste Generator: Nο Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: No Commercial TSD: No **Used Oil Transporter:** No Used Oil Transfer Facility: No Used Oil Processor: No Used Oil Refiner: Nο Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

19960901 Receive Date:

Handler Name: **BILL'S SERVICE CO**

Federal Waste Generator Code:

Generator Code Description: Small Quantity Generator

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft)

Source Type: Implementer

Owner/Operator Details

Date Ended Current:

Owner/Operator Ind: **Current Operator** Street No:

Private Type: Street 1: Name: NOT REQUIRED Street 2:

Date Became Current:

NOT REQUIRED City: ME

NOT REQUIRED

NOT REQUIRED

DELISTED

TNK

99999

State:

415-555-1212 Phone: Country: Implementer Source Type: Zip Code:

Owner/Operator Ind: **Current Owner** Street No:

NOT REQUIRED Private Type: Street 1:

Name: LEACHMAN WILLIAM Street 2: Date Became Current: City:

Date Ended Current: State: ME

Phone: 415-555-1212 Country:

Source Type: 99999 Implementer Zip Code:

WNW 0.18/ 4.60/ **VERDI STREET PROPERTIES** 73 1 of1 963.47 933 FRANCISCO BLVD.

San Rafael CA 94901

Delisted Underground Storage Tanks

Facility ID: 300366 Marin County: CERS ID: Latitude: 37.96182

Original Source: UST Longitude: -122.50793

Record Date: 17-OCT-2021

CalEnviroScrn 4 Pct :

Permitting Agency: SAN RAFAEL, CITY OF

Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)

Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca. Note:

gov/search

Source:

74 1 of2 NNW 0.19/ 4.58/ DELISTED

127 VERDI STREET 977.27 0 **TNK** San Rafael CA 94901

Delisted Storage Tanks

300338 Facility ID: County: Marin Latitude: 37.9636797 Original Source: UST

30-JAN-2017 Longitude: -122.5032807 Record Date:

Permitting Agency: SAN RAFAEL, CITY OF

NNW **74** 2 of2 0.19/ 4.58/ Auto Milano **CUPA MARIN** 977.27 0

127 Verdi Street, San Rafael CA

Permit No: 30-0338 UFC: No Type of Permit: **HWG Tons:** 0.0 Cross Ref: No

HWG Recycle: Status: Inactive HWG Type Gen: US Tanks: Tiered: Nο 0 AG Tanks: 0 PBR HHW: No

HMBP: 0 Green: No Cal ARP: No Facility Phone No: (415) 453-3644

Number of Direction Distance Elev/Diff Site DB Map Key Records (mi/ft) (ft) 75 1 of5 W 0.19/ 9.94/ R. JENNINGS, GROUSE CK DELISTED 1,001.12 RANCH **TNK** 20 BELLAM BLVD. San Rafael CA 94901

Delisted Storage Tanks

Facility ID:300355County:MarinLatitude:37.959857Original Source:UST

Longitude: -122.50573 **Record Date:** 30-JAN-2017

Permitting Agency: SAN RAFAEL, CITY OF

75 2 of 5 W 0.19 / 9.94 / RLJ INCORPORATION LUST 1,001.12 5 20 BELLAM BLVD SAN RAFAEL CA 94901

Oil Field Oper (SRCH):

Census Tract (SRCH):

RWQCB Region (DL):

Latitude (DL):

Longitude (DL):

6041112202

-122.506033

SAN FRANCISCO BAY RWQCB (REGION 2)

Order No: 24072600476

37.95821

Global ID:T0604100112Case Type (DL):LUST Cleanup SiteSite Facility Type:LUST CLEANUP SITEOil Field (SRCH):

Site Facility Type: LUST CLEANUP SITE
Site Fac Type (SRCH): LUST CLEANUP SITE

Status:

Status (SRCH):COMPLETED - CASE CLOSEDStatus (DL):Completed - Case Closed

Status Date (DL): 12/17/1998

Cleanup Status: COMPLETED - CASE CLOSED
Site Facility Name (SRCH): RLJ INCORPORATION
Address (SRCH): 20 BELLAM BLVD
City (SRCH): SAN RAFAEL
2ip (SRCH): 94901
County (SRCH): MARIN

 Street No (DL):
 20

 Street Name (DL):
 BELLAM BLVD

 City (DL):
 SAN RAFAEL

 Zip (DL):
 94901

 County (DL):
 Marin

State (DL):

Business Name (DL):
Site Facility Name:
Address:
City:
SAN RAFAEL
2ip:
94901
County:
RLJ INCORPORATION
RLJ INCORPORATION
RLJ INCORPORATION
RAJ INCORPORATION

Report Source: GeoTracker Search Results (SRCH);GeoTracker Sites Data Download (DL);GeoTracker Search Results Report

GeoTracker Sites Data Download - Site Details

CUF Case: YES

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Worker: Local Agency:

RB Case No: 21-0119

Local Case No: File Location:

Potential COC: Waste Oil / Motor / Hydraulic / Lubricating

Potential Media of Concern:

Begin Date:

How Discovered:

Soil

11/17/1986

Tank Closure

How Discovered Description:

Stop Method: Stop Description:

Calwater Watershed Name: Bay Bridges - San Rafael (203.20)

DWR GW Subbasin Name: Disadvantaged Community: CalEnvScreen Score:

Coordinate Source: * Historical Geocode - Exact Address Match

Discharge Cause:UnknownDischarge Source:OtherEPA Region:9

Leak Reported Dt: 1986-12-24 00:00:00

Military DoD Site: No

No Further Action Dt: 1998-12-17 00:00:00

Qty Risd Gallons:

Facility Project Sub Type:

Calenviroscreen 3 Score: 56-60% Calenviroscreen 4 Score: 70-75%

Site History:

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: BRADLEY R. MARK
Organization Name: SAN RAFAEL, CITY OF
Address: 1039 C STREET

City: SAN RAFAEL
Email: brad.mark@ci.san-rafael.ca.us

Phone No:

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed

Status Date: 12/17/1998

Status: Open - Site Assessment

Status Date: 11/17/1986

Status: Open - Case Begin Date

Status Date: 11/17/1986

GeoTracker Search - Regulatory Profile (as of June 5, 2024)

Site Facility Name: RLJ INCORPORATION
Site Facility Type: LUST CLEANUP SITE

Cleanup Status: COMPLETED - CASE CLOSED

 Address:
 20 BELLAM BLVD

 City:
 SAN RAFAEL

 Zip:
 94901

 County:
 MARIN

Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0604100112

Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 12/17/1998

Project Status:

Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0604100112&tabname=regulatoryhistory

Order No: 24072600476

Potential COC: WASTE OIL / MOTOR / HYDRAULIC / LUBRICATING

Potential Media of Concern: SOIL

File Location:

User Defined Beneficial Use: Designated Beneficial Use: DWR GW Sub Basin:

Calwater Watershed Name: Bay Bridges - San Rafael (203.20)

Post Closure Site Management:

Future Land Use:

Cleanup Oversight Agencies: SAN FRANCISCO BAY RWQCB (REGION 2) (LEAD) - CASE #: 21-0119

CUF Claim No: 14310
CUF Priority Assig: B
CUF Amount Paid: \$0

WDR Place Type: WDR File No: WDR Order No:

Project Oversight Agencies:

Facility Type:

Composting Method:

Grndwtr Monitoring Frequency: Designated Beneficial Use

Desc: Site History:

No site history available

GeoTracker Search - Cleanup Status History (as of June 5, 2024)

Status: Completed - Case Closed

Date : 12/17/1998

Status: Open - Site Assessment

Date: 11/17/1986

Status: Open - Case Begin Date

Date: 11/17/1986

GeoTracker Search - Regulatory Activities (as of June 5, 2024)

Action Type:Other Regulatory ActionsAction:Clean Up Fund - Letter to RP

 Action Date:
 2/26/2001

 Received Issue Date:
 2/26/2001

Doc Link: https://geotracker.waterboards.ca.gov/view_documents?

global_id=T0604100112&enforcement_id=6319559&temptable=ENFORCEMENT

Title Description Comments:

UST Cleanup Fund Claim No. 014310

Action Type:Other Regulatory ActionsAction:Closure/No Further Action Letter

 Action Date:
 12/17/1998

 Received Issue Date:
 12/17/1998

Doc Link: https://geotracker.waterboards.ca.gov/view_documents?

global_id=T0604100112&enforcement_id=6313503&temptable=ENFORCEMENT

Order No: 24072600476

Title Description Comments:

Case Closure Letter and Site Summary

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 7/14/1998

 Received Issue Date:
 7/14/1998

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100112&doc_id=5919520

Title Description Comments:

Tank Closure Report

Action Type:Leak ActionAction:Leak ReportedAction Date:12/24/1986

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak StoppedAction Date:11/17/1986

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak DiscoveryAction Date:11/17/1986

Received Issue Date:

Doc Link:

Title Description Comments:

GeoTracker Search - Documents (as of June 5, 2024)

Document Type: Site Documents **Document Date:** 2/26/2001

Type: CLEAN UP FUND - LETTER TO RP Submitted:

Submitted By:SUNNY GRUNLOH (REGULATOR)Title:UST CLEANUP FUND CLAIM NO. 014310

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100112&enforcement_id=6319559

Document Type: Site Documents Document Date: 12/17/1998

Type: CLOSURE/NO FURTHER ACTION LETTER Submitted:

 Submitted By:
 SUNNY GRUNLOH (REGULATOR)

 Title:
 CASE CLOSURE LETTER AND SITE SUMMARY

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100112&enforcement_id=6313503

Document Type: Site Documents **Document Date:** 7/14/1998

Type: TANK REMOVAL REPORT / UST SAMPLING Submitted:

REPORT

Submitted By: SUNNY GRUNLOH (REGULATOR)

Title: TANK CLOSURE REPORT

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100112&document_id=5919520

75 3 of 5 W 0.19 / 9.94 / RLJ INC HHSS 1,001.12 5 20-A BELLAM BLVD.

1,001.12 5 20-A BELLAM BLVD. SAN RAFAEL CA 94901

County: Marin

Tank Details Microfiche: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/00029338.pdf

75 4 of 5 W 0.19 / 9.94 / R,L,J, INC.
HIST TANK

1,001.12 5 20-A BELLAM BLVD.

SAN RAFAEL CA

Owner Name:R,L,J, INC.No of Containers:7Owner Street:611 TANBARK TERRACECounty:MARINOwner City:SAN RAFAELFacility State:CA

Owner City:SAN RAFAELFacility State:CAOwner State:CAFacility Zip:94901

Owner Zip: 94903

75 5 of 5 W 0.19 / 9.94 / R. Jennings, Grouse CK Ranch
1.001.13 5 20 Pollom Royloverd, San Potagl

Order No: 24072600476

— 1,001.12 5 20 Bellam Boulevard, San Rafael CA

 Permit No:
 30-0355
 UFC:
 No

 Type of Permit:
 HWG Tons:
 0.0

 Cross Ref:
 HWG Recycle:
 No

 Status:
 Inactive
 HWG Type Gen:

 US Tanks:
 0
 Tiered:
 No

 AG Tanks:
 0
 PBR HHW:
 No

 HMBP:
 0
 Green:
 No

 Cal ARP:
 No
 Facility Phone No:
 (916) 233-4750

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>76</u>	1 of1	NE	0.19 / 1,001.72	5.99 / 1	CARDENAS MARKETS #216 330 BELLAN BLVD SAN RAFAEL CA 94901	RCRA NON GEN

EPA Handler ID:CAL000433907Gen Status Universe:No ReportContact Name:MARIN REYES

Contact Address: 330 BELLAN BLVD,, SAN RAFAEL, CA, 94901,

Contact Phone No and Ext: 415-578-3971

Contact Email: QUALITY@CMKTS.COM

Contact Country:

County Name: MARIN EPA Region: 09

Land Type:

 Receive Date:
 20180228

 Location Latitude:
 37.961781

 Location Longitude:
 -122.499977

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity: No Mixed Waste Generator: No Transporter Activity: No Transfer Facility: No Onsite Burner Exemption: No Furnace Exemption: No Underground Injection Activity: No Commercial TSD: Nο Used Oil Transporter: No Used Oil Transfer Facility: No Used Oil Processor: Nο Used Oil Refiner: No Used Oil Burner: No Used Oil Market Burner: No Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:

Receive Date: 20180228

Handler Name: CARDENAS MARKETS #216

Source Type: Implementer

Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator Street No:

Type: Other Street 1: 330 BELLAN BLVD

Name: MARIN REYES Street 2:

Date Became Current: City: SAN RAFAEL

Date Ended Current: State: CA

 Phone:
 415-578-3971
 Country:

 Source Type:
 Implementer
 Zip Code:
 94901

Owner/Operator Ind: Current Owner Street No:

Type: Other Street 1: 2501 E HUASTI RD

Order No: 24072600476

Name: CARDENAS MARKETS LLC Street 2:

Date Became Current: City: ONTARIO

Date Ended Current: State: CA

Phone: 909-923-7426 **Country:**

Source Type: Implementer Zip Code: 91761

77 1 of 16 SSW 0.19/ 6.51/ GOLDEN GATE TRANSIT 1,002.60 2 1011 ANDERSEN DRIVE

San Rafael CA 94901

6041112202

-122.503659

SAN FRANCISCO BAY RWQCB (REGION 2)

Order No: 24072600476

37.955869

DELISTED

TNK

Delisted Underground Storage Tanks

 Facility ID:
 300378
 County:
 Marin

 CERS ID:
 Latitude:
 37.9571761

Original Source: UST Longitude: -122.5018627

Record Date: 17-OCT-2021

CalEnviroScrn 4 Pct :

Permitting Agency: SAN RAFAEL, CITY OF

Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)

Note: Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.

gov/search

Source:

77 2 of 16 SSW 0.19 / 6.51 / GOLDEN GATE TRANSIT LUST 1,002.60 2 1011 ANDERSEN DR SAN RAFAEL CA 94901

Census Tract (SRCH):

RWQCB Region (DL):

Latitude (DL):

Longitude (DL):

Global ID: T0604100054 Case Type (DL): LUST Cleanup Site

Site Facility Type: LUST CLEANUP SITE Oil Field (SRCH):
Site Fac Type (SRCH): LUST CLEANUP SITE Oil Field Oper (SRCH):

Site Fac Type (SRCH): LUST CLEANUP SITE Status:

Status (SRCH): COMPLETED - CASE CLOSED
Status (DL): Completed - Case Closed

Status Date (DL): 12/12/2006

Cleanup Status: COMPLETED - CASE CLOSED
Site Facility Name (SRCH): GOLDEN GATE TRANSIT

Address (SRCH):
City (SRCH):

GOLDEN GATE THANSI

 Zip (SRCH):
 94901

 County (SRCH):
 MARIN

 Street No (DL):
 1011

 Street Name (DL):
 ANDERSEN DR

 City (DL):
 SAN RAFAEL

 Zip (DL):
 94901

 County (DL):
 Marin

 State (DL):
 CA

Business Name (DL):GOLDEN GATE TRANSITSite Facility Name:GOLDEN GATE TRANSITAddress :1011 ANDERSEN DR

 City:
 SAN RAFAEL

 Zip:
 94901

 County:
 MARIN

Report Source: GeoTracker Search Results (SRCH);GeoTracker Sites Data Download (DL);GeoTracker Search Results Report

GeoTracker Sites Data Download - Site Details

CUF Case: NO

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)

Case Worker: Local Agency:

RB Case No: 21-0056

Local Case No: File Location:

Potential COC: Diese

Potential Media of Concern: Other Groundwater (uses other than drinking water)

Begin Date: 10/11/1989

How Discovered:

Tank Closure

How Discovered Description:

Stop Method: Stop Description:

Calwater Watershed Name:Bay Bridges - San Rafael (203.20)DWR GW Subbasin Name:San Rafael Valley (2-029)

Disadvantaged Community: Severely Disadvantaged Community

CalEnvScreen Score:

Coordinate Source: Manual Entry on Screens

Discharge Cause: Unknown
Discharge Source: Other

EPA Region: 9

Leak Reported Dt: 1989-10-11 00:00:00

Military DoD Site: No

No Further Action Dt: 2006-12-12 00:00:00

Qty RIsd Gallons:

Facility Project Sub Type:

Calenviroscreen 3 Score:66-70%Calenviroscreen 4 Score:70-75%

Site History:

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type:Local Agency CaseworkerContact Name:BRADLEY R. MARKOrganization Name:SAN RAFAEL, CITY OFAddress:1039 C STREETCity:SAN RAFAEL

Email: brad.mark@ci.san-rafael.ca.us

Phone No:

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed

Status Date: 12/12/2006

Status: Open - Site Assessment

Status Date: 3/20/1996

Status: Open - Case Begin Date

Status Date: 10/11/1989

GeoTracker Search - Regulatory Profile (as of June 5, 2024)

Site Facility Name:GOLDEN GATE TRANSITSite Facility Type:LUST CLEANUP SITECleanup Status:COMPLETED - CASE CLOSED

Address: 1011 ANDERSEN DR

 City:
 SAN RAFAEL

 Zip:
 94901

 County:
 MARIN

Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0604100054

Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 12/12/2006

Project Status:

Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0604100054&tabname=regulatoryhistory

Order No: 24072600476

Potential COC: DIESEL

Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)

File Location:

User Defined Beneficial Use:

Designated Beneficial Use:MUN, AGR, IND, PROCDWR GW Sub Basin:San Rafael Valley (2-029)Calwater Watershed Name:Bay Bridges - San Rafael (203.20)

Post Closure Site Management:

Future Land Use:

Cleanup Oversight Agencies: SAN FRANCISCO BAY RWQCB (REGION 2) (LEAD) - CASE #: 21-0056

CUF Claim No: CUF Priority Assig: CUF Amount Paid: WDR Place Type: WDR File No: WDR Order No:

Project Oversight Agencies:

Facility Type:

Composting Method:

Grndwtr Monitoring Frequency:

Designated Beneficial Use

Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply

Desc: Site History:

No site history available

GeoTracker Search - Cleanup Status History (as of June 5, 2024)

Status: Completed - Case Closed

Date: 12/12/2006

Status: Open - Site Assessment

Date: 3/20/1996

Status: Open - Case Begin Date

Date: 10/11/1989

GeoTracker Search - Regulatory Activities (as of June 5, 2024)

Action Type:Referral to Other AgencyAction:Referral to Other State Agency

 Action Date:
 6/23/2010

 Received Issue Date:
 6/23/2010

Doc Link:

Title Description Comments:

Files Scheduled for Shipment to SRC 08/2010

Action Type:Other Regulatory ActionsAction:Closure/No Further Action Letter

 Action Date:
 12/12/2006

 Received Issue Date:
 12/12/2006

Doc Link:

Title Description Comments:

Closure letter

Action Type:Response Requested - ReportsAction:Soil and Water Investigation Report

 Action Date:
 12/3/2004

 Received Issue Date:
 12/3/2004

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5835086

Title Description Comments:

MEK Laboratory Results During UST Removal

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:11/30/2004Received Issue Date:11/30/2004

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5742849

Order No: 24072600476

Title Description Comments:

Correspondence - Letter of No Further Action

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:10/18/2004Received Issue Date:10/18/2004

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5742847

Title Description Comments:

Correspondence - Application for Closure

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 10/18/2004

 Received Issue Date:
 10/18/2004

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5744188

Title Description Comments:

Analytical Test Results Soil Sample Report Locations Map Excavation Backfill

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 12/18/2003

 Received Issue Date:
 12/18/2003

Doc Link: 12/18/2003 https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748500

Title Description Comments:

San Rafael Bus Facility (Underground) Gas Tank Replacement

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 4/2/2002

 Received Issue Date:
 4/2/2002

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5744192

Title Description Comments:

Permit Application

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:12/16/1996Received Issue Date:12/16/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5742845

Title Description Comments:

Correspondence - Lynford Edwards to Forrest Craig San Rafael Bus Facility Groundwater Monitoring

Action Type:Response Requested - ReportsAction:Monitoring Report - Quarterly

Action Date: 11/13/1996 **Received Issue Date:** 11/13/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834836

Title Description Comments:

Quarterly Groundwater Monitoring 8th Event/4th Quarter - December 1995

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 8/28/1996

 Received Issue Date:
 8/28/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748360

Order No: 24072600476

Title Description Comments:

Hazardous Materials Management Permit Inspection

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 5/31/1996

 Received Issue Date:
 5/31/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748434

Title Description Comments:

Underground Storage Tank Inspection

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 5/6/1996

 Received Issue Date:
 5/6/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748359

Title Description Comments:

Hazardous Materials Management Permit Inspection

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 5/6/1996

 Received Issue Date:
 5/6/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748431

Title Description Comments:

Underground Storage Tank Inspection

Action Type:Response Requested - OtherAction:Unauthorized Release Form

 Action Date:
 4/12/1996

 Received Issue Date:
 4/12/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834829

Title Description Comments:

Underground Storage Tank Permit Application - Form A

Action Type:Response Requested - ReportsAction:Monitoring Report - Quarterly

 Action Date:
 2/16/1996

 Received Issue Date:
 2/16/1996

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5742840

Title Description Comments:

Quarterly Groundwater Monitoring

Action Type:Response Requested - ReportsAction:Monitoring Report - Quarterly

 Action Date:
 9/25/1995

 Received Issue Date:
 9/25/1995

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834834

Title Description Comments:

Quarterly Groundwater Monitoring 6th Event/2nd Quarter - June 1995

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly

 Action Date:
 6/2/1995

 Received Issue Date:
 6/2/1995

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834828

Order No: 24072600476

Title Description Comments:

Quarterly Groundwater Monitoring 5th Event/ 1st Quarter - March 1995

Action Type:Response Requested - ReportsAction:Monitoring Report - Quarterly

 Action Date:
 3/2/1995

 Received Issue Date:
 3/2/1995

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834833

Title Description Comments:

Quarterly Groundwater Monitoring 4th Quarter - December 1994

Action Type:Response Requested - ReportsAction:CAP/RAP - Other Report

 Action Date:
 2/2/1995

 Received Issue Date:
 2/2/1995

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834827

Title Description Comments:

Ground Water Treatment System Quarterly Monitoring Report

Action Type:Response Requested - ReportsAction:Monitoring Report - Quarterly

 Action Date:
 12/15/1994

 Received Issue Date:
 12/15/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5742837

Title Description Comments:

Quarterly Groundwater Monitoring 3rd Quarter September 1994

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 11/16/1994

 Received Issue Date:
 11/16/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748495

Title Description Comments:

Regarding Status of Items Noted During the Inspection Conducted Sept.19 1994

Action Type: Response Requested - Other

Action: Correspondence
Action Date: 10/18/1994
Received Issue Date: 10/18/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748435

Title Description Comments:

Hazardous Material Management Plan Inspection

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:9/22/1994Received Issue Date:9/22/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748499

Title Description Comments:

San Rafael Bus Facility - Groundwater Monitoring Program

Action Type:Response Requested - ReportsAction:Monitoring Report - Other

 Action Date:
 8/30/1994

 Received Issue Date:
 8/30/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834823

Order No: 24072600476

Title Description Comments:

Groundwater Monitoring Report

Action Type:Response Requested - ReportsAction:Monitoring Report - Other

 Action Date:
 8/29/1994

 Received Issue Date:
 8/29/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748354

Title Description Comments:

Groundwater Monitoring

Action Type:Response Requested - ReportsAction:Monitoring Report - Other

 Action Date:
 6/21/1994

 Received Issue Date:
 6/21/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834822

Title Description Comments:

Groundwater Monitoring

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:5/6/1994

Received Issue Date: 5/6/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748439

Title Description Comments:

San Rafael Bus Facility - Tank Test Results

Action Type:Response Requested - WorkplansAction:Soil and Water Investigation Workplan

 Action Date:
 3/28/1994

 Received Issue Date:
 3/28/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5834825

Title Description Comments:

Work Plan Groundwater Monitoring

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:3/25/1994Received Issue Date:3/25/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748455

Title Description Comments:

San Rafael Bus Facility Groundwater Monitoring-Quarterly Groundwater Monitoring Program

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:3/23/1994Received Issue Date:3/23/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748425

Title Description Comments:

Quarterly Groundwater Monitoring Program

Action Type: Response Requested - Workplans

Action:Other WorkplanAction Date:3/16/1994Received Issue Date:3/16/1994

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5744189

Order No: 24072600476

Title Description Comments:

Hazardous Materials Business Plan

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 12/21/1993

 Received Issue Date:
 12/21/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748386

Title Description Comments:

Notice of Violations and Intent to File Suit Under the Federal Water Pollution Control Act

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:9/28/1993Received Issue Date:9/28/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748449

Title Description Comments:

San Rafael Bus Facility Fuel Tank Removals-Contract 91-BT-5

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 9/20/1993

 Received Issue Date:
 9/20/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748419

Title Description Comments:

San Rafael Bus Facility Fuel Tank Removals-Contract 91-BT-5

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:9/13/1993Received Issue Date:9/13/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748489

Title Description Comments:

EVAX Technologies Inc. Fuel Removal

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 9/7/1993

 Received Issue Date:
 9/7/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748417

Title Description Comments:

SAN RAFAEL BUS FACILITY FUEL TANK REMOVALS, CONTRACT 91-BT-5 - REPORT ON MONITORING WELL DATA

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

Action Date: 7/21/1993 **Received Issue Date:** 7/21/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748496

Title Description Comments:

Report of Laboratory Analyses for Samples Received July16 1993

Action Type: Response Requested - Other Action: Other Report / Document

 Action Date:
 7/8/1993

 Received Issue Date:
 7/8/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748421

Order No: 24072600476

Title Description Comments:

Permit Application Acknowledgement

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:6/23/1993Received Issue Date:6/23/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748367

Title Description Comments:

Golden Gate Bridge Highway and Transportation Department, San Rafael Bus Facility contaminated soil project

Action Type:Response Requested - ReportsAction:CAP/RAP - Other Report

 Action Date:
 6/16/1993

 Received Issue Date:
 6/16/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5835078

Title Description Comments:

Report Remedial Investigation

Action Type: Response Requested - Other

 Action:
 Correspondence

 Action Date:
 5/20/1993

 Received Issue Date:
 5/20/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5742850

Title Description Comments:

Correspondence - Remedial Investigation Report

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 4/29/1993

 Received Issue Date:
 4/29/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748448

Title Description Comments:

San Rafael Bus Facility Fuel Tank Removals-Contract 91-BT-5-Summary of Test Results

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

 Action Date:
 3/23/1993

 Received Issue Date:
 3/23/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748368

Title Description Comments:

HAZARDOUS MATERIALS PERMIT RENEWAL FORM

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 3/19/1993

 Received Issue Date:
 3/19/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748384

Title Description Comments:

Notice of Violation-Hazardous Material Permit Expired

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 3/4/1993

 Received Issue Date:
 3/4/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748427

Order No: 24072600476

Title Description Comments:

San Rafael Bus Facility - Tank Test Results

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 2/22/1993

 Received Issue Date:
 2/22/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748440

Title Description Comments:

San Rafael Bus Facility - Monitoring Wells

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 2/18/1993

 Received Issue Date:
 2/18/1993

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5744190

Title Description Comments:

Invoice for Analytical Services

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 12/28/1992

 Received Issue Date:
 12/28/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748418

Title Description Comments:

San Rafael Bus Facility Fuel Tank Removals

Action Type:Response Requested - OtherAction:Unauthorized Release Form

 Action Date:
 12/18/1992

 Received Issue Date:
 12/18/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748415

Title Description Comments:

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) I CONTAMINATION SITE REPORT

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

Action Date: 12/17/1992
Received Issue Date: 12/17/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748341

Title Description Comments:

Chain of Custody Record

Action Type: Other Regulatory Actions

Action: Closure/No Further Action Letter - #21-0056

 Action Date:
 8/18/1992

 Received Issue Date:
 8/18/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents?

global_id=T0604100054&enforcement_id=6239407&temptable=ENFORCEMENT

Order No: 24072600476

Title Description Comments:

Case Closure for Golden Gate Bridge District (GGBD), North End near Hwy 101 South/Vista Point, Marin County

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:8/12/1992Received Issue Date:8/12/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5835073

Title Description Comments:

Bridge Diesel Fuel Tank Removal, Contract 91-B-3

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 8/4/1992

 Received Issue Date:
 8/4/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748383

Title Description Comments:

Methanol tank cleaning at Golden Gate Transit

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:7/7/1992Received Issue Date:7/7/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748364

Title Description Comments:

Golden Gate Bridge District Letter of June 5, 1992

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 6/25/1992

 Received Issue Date:
 6/25/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5835069

Title Description Comments:

Bridge Diesel Fuel Tank Removal, Contract 91-B-3

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 6/23/1992

 Received Issue Date:
 6/23/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5744191

Title Description Comments:

MW-1 Client Name Golden Gate Bridge

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:6/5/1992

Received Issue Date: 6/5/1992
Doc Link: 6/5/1992
https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748502

Title Description Comments:

Soil and Groundwater Investigation

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

 Action Date:
 4/8/1992

 Received Issue Date:
 4/8/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748403

Order No: 24072600476

Title Description Comments:

Evaluation of Analytical Results from Soil Sampling

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:3/5/1992Received Issue Date:3/5/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748498

Title Description Comments:

Revised Monitoring Well and Soil Boring Program

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:2/25/1992Received Issue Date:2/25/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748406

Title Description Comments:

PROPOSED WORK PLAN - SOIL AND GROUNDWATER INVESTIGATION

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 2/12/1992

 Received Issue Date:
 2/12/1992

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748443

Title Description Comments:

Permit

Action Type: Response Requested - Other

Action: Correspondence
Action Date: 12/11/1991
Received Issue Date: 12/11/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748458

Title Description Comments:

Underground Storage Tank Permit - Expired

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:12/6/1991Received Issue Date:12/6/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748380

Title Description Comments:

Letter of December 2, 1991; Golden Gate Transportation and Highway District, UST Permit

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:11/14/1991Received Issue Date:11/14/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748424

Title Description Comments:

Proposed Work Plan - Soil & Groundwater Investigation

Action Type: Response Requested - Workplans

Action: Corrective Action Plan / Remedial Action Plan

 Action Date:
 9/26/1991

 Received Issue Date:
 9/26/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5835084

Title Description Comments:

Work Plan Remedial Investigation

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

 Action Date:
 8/28/1991

 Received Issue Date:
 8/28/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748442

Order No: 24072600476

Title Description Comments:

Permit

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 8/5/1991

 Received Issue Date:
 8/5/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748409

Title Description Comments:

Well Sampling Data

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 6/11/1991

 Received Issue Date:
 6/11/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748446

Title Description Comments:

Test Tank Results

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:5/23/1991Received Issue Date:5/23/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748492

Title Description Comments:

Preliminary Plan Review for Proposed Installation of Three 20000 Gallon USTs

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 5/15/1991

 Received Issue Date:
 5/15/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748497

Title Description Comments:

Report of SoilTest Leak Master Line Test

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

 Action Date:
 5/15/1991

 Received Issue Date:
 5/15/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748338

Title Description Comments:

AINLAY TANK TIGHTNESS TEST NO. 2

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:5/3/1991Received Issue Date:5/3/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748381

Title Description Comments:

Informative Letter to Cheif Marcucci

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:3/28/1991Received Issue Date:3/28/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748379

Order No: 24072600476

Title Description Comments:

Items that Require Attention Regarding the Underground Storage Tanks

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 3/25/1991

 Received Issue Date:
 3/25/1991

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748487

Title Description Comments:

Permit Application Acknowledgement

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 11/30/1990

 Received Issue Date:
 11/30/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5744194

Title Description Comments:

Underground Oil Tank Removals

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 11/19/1990

 Received Issue Date:
 11/19/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748339

Title Description Comments:

Annual Inspection Checklist for Existing Underground Storage Tanks

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 11/19/1990

 Received Issue Date:
 11/19/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748369

Title Description Comments:

Hazardous Materials Release - Underground Diesel Storage Tank Investigation, Clean-up and Abatement Order

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:10/30/1990Received Issue Date:10/30/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748343

Title Description Comments:

Evaluation of Analytical Results from Soil Sampling Park & Ride Site

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:10/29/1990Received Issue Date:10/29/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748346

Title Description Comments:

Deposition of Oil Laden Soil on Andersen Drive Site, Telephone Conversation of October 26, 1990

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

 Action Date:
 10/16/1990

 Received Issue Date:
 10/16/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748365

Order No: 24072600476

Title Description Comments:

Field Report

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 10/4/1990

 Received Issue Date:
 10/4/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748457

Title Description Comments:

San Rafael Fire Department Permit

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:8/3/1990Received Issue Date:8/3/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748376

Title Description Comments:

HAZARDOUS MATERIALS RELEASE CLEAN-UP AND ABATEMENT ORDER

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:7/10/1990Received Issue Date:7/10/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748375

Title Description Comments:

Hazardous Materials Release, Clean-up and Abatement Order

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:5/16/1990Received Issue Date:5/16/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748461

Title Description Comments:

UNDERGROUND STORAGE TANK - DIESEL TANK NO.1

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:4/27/1990Received Issue Date:4/27/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748430

Title Description Comments:

Leaking Underground Diesel Tank No.1

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:4/13/1990Received Issue Date:4/13/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5993877

Title Description Comments:

UST Facility - Diesel Tank No.1 Further Investigation

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 4/6/1990

 Received Issue Date:
 4/6/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748407

Order No: 24072600476

Title Description Comments:

UST Removal/Abandonment Inspection Checklist

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 4/4/1990

 Received Issue Date:
 4/4/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748460

Title Description Comments:

UNDERGROUND STORAGE TANK - DIESEL TANK NO.1

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 3/30/1990

 Received Issue Date:
 3/30/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748450

Title Description Comments:

Client Reference Information-Sample Analysis

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 3/29/1990

 Received Issue Date:
 3/29/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748459

Title Description Comments:

Underground Storage Tank Test Results

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 2/15/1990

 Received Issue Date:
 2/15/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748382

Title Description Comments:

Log of Exploratory Borings

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 1/17/1990

 Received Issue Date:
 1/17/1990

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748423

Title Description Comments:

Proposal - Subsurface Hydrogeologic Investigation

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 12/18/1989

 Received Issue Date:
 12/18/1989

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748490

Title Description Comments:

Metcalf & Eddy Meeting

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

 Action Date:
 12/5/1989

 Received Issue Date:
 12/5/1989

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748503

Order No: 24072600476

Title Description Comments:

Soil Movement from 1011 Andersen San Rafael

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:10/27/1989Received Issue Date:10/27/1989

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748452

Title Description Comments:

Information Requested by Forrest Craig

Action Type:Leak ActionAction:Leak ReportedAction Date:10/11/1989

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak DiscoveryAction Date:10/11/1989

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type:Leak ActionAction:Leak StoppedAction Date:10/11/1989

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:4/21/1989Received Issue Date:4/21/1989

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748451

Title Description Comments:

Detection of Water in 6000 Gallon Unleaded Fuel Tank

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 1/13/1989

 Received Issue Date:
 1/13/1989

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748420

Title Description Comments:Proposed Site Investigation

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 1/3/1989

 Received Issue Date:
 1/3/1989

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748398

Title Description Comments:

Photos of Exploratory Trenching. Shoring Installation. Emptying Waste & Drain Oil Tanks. Etc.

Action Type:Response Requested - OtherAction:Other Report / Document

Action Date: 11/10/1988
Received Issue Date: 11/10/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5993880

Title Description Comments:

Precision Tank Test Report

Action Type: Response Requested - Other Action: Other Report / Document

 Action Date:
 10/10/1988

 Received Issue Date:
 10/10/1988

Doc Link: https://geotracker.waterboards.ca.gov/view documents all?global id=T0604100054&doc id=5993879

Title Description Comments:

UST Unauthorized Release Contamination Site Report

Action Type:Response Requested - OtherAction:Unauthorized Release Form

 Action Date:
 10/10/1988

 Received Issue Date:
 10/10/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748414

Title Description Comments:

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) I CONTAMINATION SITE REPORT

Action Type:Response Requested - OtherAction:Unauthorized Release Form

 Action Date:
 10/4/1988

 Received Issue Date:
 10/4/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748413

Title Description Comments:

Underground Storage Tank Unauthorized Release (Leak)/Contaminated Site Report

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:9/14/1988Received Issue Date:9/14/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748378

Title Description Comments:

Information Discussed Sept.9 Regarding Underground Fuel Storage Tanks

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:9/9/1988Received Issue Date:9/9/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748363

Title Description Comments:

Follow-up to Previous Conversation

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 8/26/1988

 Received Issue Date:
 8/26/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748438

Title Description Comments:

Underground Tank Management Project-Authorization for Testing (Action)

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:4/29/1988Received Issue Date:4/29/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748454

Title Description Comments:

Sample Analyses Results

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:2/5/1988Received Issue Date:2/5/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748355

Title Description Comments:
Hazardous Material Disclosure

Action Type:

Action: Correspondence
Action Date: 1/6/1988
Received Issue Date: 1/6/1988

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748356

Title Description Comments:

Hazardous Material Disclosure

Action Type: Response Requested - Other

Action:CorrespondenceAction Date:12/31/1987Received Issue Date:12/31/1987

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748411

Title Description Comments:

Urgent Priority Analysis of Two Samples Identified as "1211-1 and -2" Received Dec.11 1987

Response Requested - Other

Action Type: Response Requested - Reports

Action: Tank Removal Report / UST Sampling Report

 Action Date:
 10/14/1987

 Received Issue Date:
 10/14/1987

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748422

Title Description Comments:

Permit to Remove Underground Storage Tank

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 3/9/1987

 Received Issue Date:
 3/9/1987

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748437

Title Description Comments:

Hazardous Waste Predisposal Evaluation

Action Type:Response Requested - OtherAction:Other Report / Document

 Action Date:
 7/1/1984

 Received Issue Date:
 7/1/1984

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748377

Title Description Comments:

Hazardous Substance Storage Statement

 Action Type:
 Response Requested - Other

 Action:
 Other Report / Document

Action Date: 10/27/1972
Received Issue Date: 10/27/1972

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0604100054&doc_id=5748488

Number of Direction Elev/Diff Site DΒ Map Key Distance Records (mi/ft) (ft)

Title Description Comments:

Boring Location Plan

GeoTracker Search - Site Maps (as of June 5, 2024)

Submitted: 9/7/2006

SUSAN GAHRY (AUTH_RP) Submitted By:

Title: GEO MAP

Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/3187304437/T0604100054.pdf

GeoTracker Search - Documents (as of June 5, 2024)

Document Type: Site Documents Document Date: 12/20/2006

LETTER Submitted: Type:

RALPH LAMBERT (REGULATOR) Submitted By:

CLOSURE LETTER Title:

Title Link: https://geotracker.waterboards.ca.gov/site_documents/6713505387/21%2D0056%20Closure%2Epdf

Submitted:

Document Type: Site Documents Document Date: 9/7/2006

REPORTS - CLOSURE RPT. Type: SUSAN GAHRY (AUTH RP)

Submitted By: Title:

2006MONITORINGREPORT&CLOSUREREQUEST

https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9676792740/T0604100054.PDF Title Link:

Document Type: Site Documents Document Date: 12/3/2004

SOIL AND WATER INVESTIGATION Type: Submitted:

REPORT

ASHA TURMAN (REGULATOR) Submitted By:

MEK LABORATORY RESULTS DURING UST REMOVAL Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5835086 Title Link:

Document Type: Site Documents Document Date: 11/30/2004

CORRESPONDENCE Submitted: Type:

Submitted By: (REGULATOR)

CORRESPONDENCE - LETTER OF NO FURTHER ACTION Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5742849

Document Type: Site Documents Document Date: 10/18/2004

Type: TANK REMOVAL REPORT / UST SAMPLING Submitted:

REPORT

KIMBERLY YEE (REGULATOR) Submitted By:

ANALYTICAL TEST RESULTS SOIL SAMPLE REPORT LOCATIONS MAP EXCAVATION BACKFILL Title: Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5744188

Site Documents 10/18/2004 Document Date: Document Type:

Type: CORRESPONDENCE Submitted:

Submitted By: (REGULATOR)

CORRESPONDENCE - APPLICATION FOR CLOSURE Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5742847

Document Type: Site Documents Document Date: 12/18/2003

OTHER REPORT / DOCUMENT Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

SAN RAFAEL BUS FACILITY (UNDERGROUND) GAS TANK REPLACEMENT Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748500 Title Link:

Document Type: Site Documents **Document Date:** 4/2/2002

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR) PERMIT APPLICATION Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5744192

Order No: 24072600476

Site Documents Document Date: 12/16/1996 Document Type:

Type: CORRESPONDENCE Submitted:

Submitted By: (REGULATOR)

Title: CORRESPONDENCE - LYNFORD EDWARDS TO FORREST CRAIG SAN RAFAEL BUS FACILITY

GROUNDWATER MONITORING

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5742845

Document Type: Monitoring Reports **Document Date:** 11/13/1996

Type: MONITORING REPORT - QUARTERLY Submitted:

Submitted By: ASHA TURMAN (REGULATOR)

Title:QUARTERLY GROUNDWATER MONITORING 8TH EVENT/4TH QUARTER - DECEMBER 1995 -Title Link:https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7775057733/4q95%2Epdf

Document Type: Monitoring Reports **Document Date:** 11/13/1996

Type: MONITORING REPORT - QUARTERLY Submitted:

Submitted By: MADELEINE LITTLE (REGULATOR)

Title: QUARTERLY GROUNDWATER MONITORING 8TH EVENT/4TH QUARTER - DECEMBER 1995 - 12-16-1996

COVER LETTER QUARTERLY GROUNDWATER MONITORING 8TH EVENT/4TH QUARTER - DECEMBER

1995

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7476668417/21%2D0056%2012%2D16%

2D1996%20gw%20monitoring%20report%20cover%20page%2Epdf

Document Type: Site Documents **Document Date:** 8/28/1996

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

Title: HAZARDOUS MATERIALS MANAGEMENT PERMIT INSPECTION

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748360

Document Type: Site Documents Document Date: 5/31/1996

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

Title: UNDERGROUND STORAGE TANK INSPECTION

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748434

Document Type: Site Documents Document Date: 5/6/1996

Type: OTHER REPORT / DOCUMENT

Submitted By: KIMBERLY YEE (REGULATOR)

Title: HAZARDOUS MATERIALS MANAGEMENT PERMIT INSPECTION

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748359

Submitted:

Document Type: Site Documents Document Date: 5/6/1996

Type: OTHER REPORT / DOCUMENT Submitted:
Submitted By: KIMBERLY YEE (REGULATOR)

Title: UNDERGROUND STORAGE TANK INSPECTION

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748431

Document Type: Site Documents Document Date: 4/12/1996

Type: UNAUTHORIZED RELEASE FORM Submitted:

Submitted By: ASHA TURMAN (REGULATOR)

Title: UNDERGROUND STORAGE TANK PERMIT APPLICATION - FORM A

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5834829

Document Type: Monitoring Reports **Document Date:** 2/16/1996

Type: MONITORING REPORT - QUARTERLY Submitted: Submitted By: (REGULATOR)

Title: QUARTERLY GROUNDWATER MONITORING -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/2541624307/Quarterly%20Groundwater%

Order No: 24072600476

20Monitoring%20%2D%2002%2E16%2E1996%2Epdf

Document Type: Monitoring Reports **Document Date:** 9/25/1995

Type: MONITORING REPORT - QUARTERLY Submitted:

Submitted By: ASHA TURMAN (REGULATOR)

Title: QUARTERLY GROUNDWATER MONITORING 6TH EVENT/2ND QUARTER - JUNE 1995 -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5238630533/4q956th%2Epdf

Document Type: Monitoring Reports **Document Date:** 6/2/1995

Type: MONITORING REPORT - QUARTERLY Submitted:

Śubmitted By:ASHA TURMAN (REGULATOR)Title:QUARTERLY GROUNDWATER MONITORING 5TH EVENT/ 1ST QUARTER - MARCH 1995 -

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3546461343/5ev4q95%2Epdf

Document Type: Monitoring Reports **Document Date:** 3/2/1995

Number of Direction Elev/Diff Site DΒ Map Key Distance Records (mi/ft) (ft)

MONITORING REPORT - QUARTERLY Submitted: Type:

ASHA TURMAN (REGULATOR) Submitted By:

QUARTERLY GROUNDWATER MONITORING 4TH QUARTER - DECEMBER 1994 -Title:

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4577486932/4q94mar95%2Epdf

Site Documents 2/2/1995 Document Type: Document Date: Submitted:

Type: CAP/RAP - OTHER REPORT

ASHA TURMAN (REGULATOR) Submitted By:

GROUND WATER TREATMENT SYSTEM QUARTERLY MONITORING REPORT

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5834827 Title Link:

Document Type: Monitoring Reports Document Date: 12/15/1994

MONITORING REPORT - QUARTERLY Type:

Submitted By: (REGULATOR)

Title:

QUARTERLY GROUNDWATER MONITORING 3RD QUARTER SEPTEMBER 1994 -Title:

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7775883316/Quarterly%20Groundwater% Title Link:

20Monitoring%203rd%20Quarter%20September%201994%20%2D%2012%2E15%2E1994%2Epdf

Submitted:

Submitted:

Submitted:

Document Type: Site Documents Document Date: 11/16/1994

OTHER REPORT / DOCUMENT Type:

KIMBERLY YEE (REGULATOR) Submitted By:

REGARDING STATUS OF ITEMS NOTED DURING THE INSPECTION CONDUCTED SEPT.19 1994 Title: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748495 Title Link:

Site Documents Document Date: 10/18/1994 Document Type:

CORRESPONDENCE Submitted: Type:

KIMBERLY YEE (REGULATOR) Submitted By:

HAZARDOUS MATERIAL MANAGEMENT PLAN INSPECTION Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748435 Title Link:

Site Documents Document Date: Document Type: 9/22/1994

CORRESPONDENCE Type:

Submitted By: KIMBERLY YEE (REGULATOR)

SAN RAFAEL BUS FACILITY - GROUNDWATER MONITORING PROGRAM Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748499

Document Type: Monitoring Reports Document Date: 8/30/1994

MONITORING REPORT - OTHER Type: Submitted:

Submitted By: ASHA TURMAN (REGULATOR)

GROUNDWATER MONITORING REPORT -Title:

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/2636871159/gwmpnaug94%2Epdf Title Link:

Monitoring Reports Document Type: **Document Date:** 8/29/1994 Submitted:

MONITORING REPORT - OTHER Type:

Submitted By: KIMBERLY YEE (REGULATOR) GROUNDWATER MONITORING -Title:

https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4390348672/Groundwater% Title Link:

20Monitoring%20%2D%2008%2E29%2E1994%2Epdf

Monitoring Reports Document Type: **Document Date:** 6/21/1994

MONITORING REPORT - OTHER Submitted: Type:

Submitted By: ASHA TURMAN (REGULATOR) GROUNDWATER MONITORING -Title:

Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/5725008904/gwmpnjun94%2Epdf

Document Type: Site Documents Document Date: 5/6/1994 Submitted:

CORRESPONDENCE Type:

Submitted By: KIMBERLY YEE (REGULATOR) Title:

SAN RAFAEL BUS FACILITY - TANK TEST RESULTS

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748439 Title Link:

Document Type: Site Documents Document Date: 3/28/1994

SOIL AND WATER INVESTIGATION Type: Submitted:

WORKPLAN

ASHA TURMAN (REGULATOR) Submitted By: Title:

WORK PLAN GROUNDWATER MONITORING

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5834825

Order No: 24072600476

Document Type: Site Documents **Document Date:** 3/25/1994

Number of Direction Elev/Diff Site DΒ Map Key Distance Records (mi/ft) (ft)

CORRESPONDENCE Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

SAN RAFAEL BUS FACILITY GROUNDWATER MONITORING-QUARTERLY GROUNDWATER MONITORING Title:

Submitted:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748455

Document Type: Site Documents Document Date: 3/23/1994

CORRESPONDENCE Type: Submitted By: KIMBERLY YEE (REGULATOR)

QUARTERLY GROUNDWATER MONITORING PROGRAM Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748425

Site Documents Document Date: 3/16/1994 Document Type:

OTHER WORKPLAN Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

HAZARDOUS MATERIALS BUSINESS PLAN Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5744189

Document Type: Site Documents Document Date: 12/21/1993

OTHER REPORT / DOCUMENT Submitted: Tvpe:

Submitted By: KIMBERLY YEE (REGULATOR)

NOTICE OF VIOLATIONS AND INTENT TO FILE SUIT UNDER THE FEDERAL WATER POLLUTION CONTROL Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748386

Document Type: Site Documents Document Date: 9/28/1993

CORRESPONDENCE Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

SAN RAFAEL BUS FACILITY FUEL TANK REMOVALS-CONTRACT 91-BT-5 Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748449 Title Link:

Document Type: Site Documents Document Date: 9/20/1993

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

KIMBERLY YEE (REGULATOR) Submitted By: Title:

SAN RAFAEL BUS FACILITY FUEL TANK REMOVALS-CONTRACT 91-BT-5

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748419

9/13/1993 Document Type: Site Documents **Document Date:**

CORRESPONDENCE Submitted: Type:

KIMBERLY YEE (REGULATOR) Submitted By:

EVAX TECHNOLOGIES INC. FUEL REMOVAL Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748489

Document Type: Site Documents **Document Date:** 9/7/1993

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

KIMBERLY YEE (REGULATOR) Submitted By:

SAN RAFAEL BUS FACILITY FUEL TANK REMOVALS, CONTRACT 91-BT-5 - REPORT ON MONITORING Title:

WELL DATA

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748417

Document Type: Site Documents Document Date: 7/21/1993

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

REPORT OF LABORATORY ANALYSES FOR SAMPLES RECEIVED JULY16 1993

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748496 Title Link:

Site Documents 7/8/1993 Document Type: **Document Date:**

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

PERMIT APPLICATION ACKNOWLEDGEMENT Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748421

Site Documents Document Type: Document Date: 6/23/1993

Type: CORRESPONDENCE Submitted: Submitted By: KIMBERLY YEE (REGULATOR)

Title: GOLDEN GATE BRIDGE HIGHWAY AND TRANSPORTATION DEPARTMENT, SAN RAFAEL BUS FACILITY

Order No: 24072600476

CONTAMINATED SOIL PROJECT

Number of Elev/Diff Site DΒ Map Key Direction Distance Records (mi/ft) (ft)

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748367

6/16/1993 Document Type: Site Documents Document Date:

CAP/RAP - OTHER REPORT Submitted: Type:

Submitted By: ASHA TURMAN (REGULATOR) REPORT REMEDIAL INVESTIGATION Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5835078

Site Documents Document Date: 5/20/1993 Document Type:

CORRESPONDENCE Submitted: Type:

Submitted By: (REGULATOR)

Title: CORRESPONDENCE - REMEDIAL INVESTIGATION REPORT

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5742850 Title Link:

Document Type: Site Documents Document Date: 4/29/1993

TANK REMOVAL REPORT / UST SAMPLING Type: Submitted:

REPORT

KIMBERLY YEE (REGULATOR) Submitted By:

Title: SAN RAFAEL BUS FACILITY FUEL TANK REMOVALS-CONTRACT 91-BT-5-SUMMARY OF TEST RESULTS Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748448

Document Type: Site Documents Document Date: 3/23/1993

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

HAZARDOUS MATERIALS PERMIT RENEWAL FORM Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748368

Submitted:

Submitted:

Submitted:

Site Documents Document Type: Document Date: 3/19/1993

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR)

NOTICE OF VIOLATION-HAZARDOUS MATERIAL PERMIT EXPIRED

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748384

Site Documents Document Type: **Document Date:** 3/4/1993

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR)

SAN RAFAEL BUS FACILITY - TANK TEST RESULTS Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748427 Title Link:

Document Type: Site Documents **Document Date:** 2/22/1993

OTHER REPORT / DOCUMENT Type: Submitted By: KIMBERLY YEE (REGULATOR)

SAN RAFAEL BUS FACILITY - MONITORING WELLS Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748440

Document Date: Document Type: Site Documents 2/18/1993

OTHER REPORT / DOCUMENT Type: Submitted:

KIMBERLY YEE (REGULATOR) Submitted By:

INVOICE FOR ANALYTICAL SERVICES - REGULATOR RESPONSE

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5744190

Document Type: Site Documents Document Date: 2/18/1993

OTHER REPORT / DOCUMENT Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

INVOICE FOR ANALYTICAL SERVICES Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5744190 Title Link:

Site Documents Document Type: Document Date: 12/28/1992

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

KIMBERLY YEE (REGULATOR)

SAN RAFAEL BUS FACILITY FUEL TANK REMOVALS

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748418 Title Link:

Document Type: Site Documents Document Date: 12/18/1992

UNAUTHORIZED RELEASE FORM Type:

Submitted: KIMBERLY YEE (REGULATOR)

Submitted By:

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) I CONTAMINATION SITE REPORT Title: Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748415

Order No: 24072600476

Submitted By:

Title:

Title:

Document Date: Site Documents 12/17/1992 Document Type:

OTHER REPORT / DOCUMENT Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR) Title: CHAIN OF CUSTODY RECORD

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748341 Title Link:

Site Documents Document Date: 8/18/1992 Document Type:

CLOSURE/NO FURTHER ACTION LETTER Submitted: Type:

ASHA TURMAN (REGULATOR) Submitted By:

CASE CLOSURE FOR GOLDEN GATE BRIDGE DISTRICT (GGBD), NORTH END NEAR HWY 101 Title:

SOUTH/VISTA POINT, MARIN COUNTY

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&enforcement_id=6239407 Title Link:

Site Documents 8/12/1992 Document Type: Document Date:

CORRESPONDENCE Submitted: Type:

Submitted By: ASHA TURMAN (REGULATOR)

BRIDGE DIESEL FUEL TANK REMOVAL, CONTRACT 91-B-3 Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5835073

Document Type: Site Documents Document Date: 8/4/1992

OTHER REPORT / DOCUMENT Type: Submitted:

KIMBERLY YEE (REGULATOR) Submitted By:

Title: METHANOL TANK CLEANING AT GOLDEN GATE TRANSIT

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748383 Title Link:

Document Type: Site Documents Document Date: 7/7/1992

CORRESPONDENCE Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

GOLDEN GATE BRIDGE DISTRICT LETTER OF JUNE 5, 1992 Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748364 Title Link:

Document Type: Site Documents Document Date: 6/25/1992

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

ASHA TURMAN (REGULATOR) Submitted By:

BRIDGE DIESEL FUEL TANK REMOVAL, CONTRACT 91-B-3 Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5835069 Title Link:

Site Documents Document Date: 6/23/1992 Document Type:

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

MW-1 CLIENT NAME GOLDEN GATE BRIDGE Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5744191 Title Link:

Document Type: Site Documents Document Date: 6/5/1992

CORRESPONDENCE Submitted: Type:

KIMBERLY YEE (REGULATOR) Submitted By:

SOIL AND GROUNDWATER INVESTIGATION Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748502

Document Type: Site Documents Document Date: 4/8/1992

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

EVALUATION OF ANALYTICAL RESULTS FROM SOIL SAMPLING Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748403 Title Link:

Document Date: 3/5/1992 Document Type: Site Documents

CORRESPONDENCE Submitted: Type:

KIMBERLY YEE (REGULATOR) Submitted By: Title:

REVISED MONITORING WELL AND SOIL BORING PROGRAM

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748498

Document Type: Site Documents **Document Date:** 2/25/1992

Type: CORRESPONDENCE Submitted:

KIMBERLY YEE (REGULATOR) Submitted By:

Title: PROPOSED WORK PLAN - SOIL AND GROUNDWATER INVESTIGATION

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748406 Title Link:

Submitted:

Document Type: Site Documents **Document Date:** 2/12/1992

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

Title: PERMIT

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748443

Document Type: Site Documents Document Date: 12/11/1991

Type: CORRESPONDENCE

Submitted By: KIMBERLY YEE (REGULATOR)

Title: UNDERGROUND STORAGE TANK PERMIT - EXPIRED

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748458

Document Type: Site Documents **Document Date:** 12/6/1991

Type: CORRESPONDENCE Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

Title: LETTER OF DECEMBER 2, 1991; GOLDEN GATE TRANSPORTATION AND HIGHWAY DISTRICT, UST

PERMIT

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748380

Document Type: Site Documents **Document Date:** 11/14/1991

Type: CORRESPONDENCE Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

Title: PROPOSED WORK PLAN - SOIL & GROUNDWATER INVESTIGATION

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748424

Document Type: Site Documents Document Date: 9/26/1991

Type: CORRECTIVE ACTION PLAN / REMEDIAL Submitted:

ACTION PLAN

Submitted By: ASHA TURMAN (REGULATOR)

Title: WORK PLAN REMEDIAL INVESTIGATION

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5835084

Submitted:

Submitted:

Submitted:

Order No: 24072600476

Document Type: Site Documents Document Date: 8/28/1991

Type: OTHER REPORT / DOCUMENT

Submitted By: KIMBERLY YEE (REGULATOR)

Title: PERMI

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748442

Document Type: Site Documents Document Date: 8/5/1991

Type: OTHER REPORT / DOCUMENT

Submitted By:KIMBERLY YEE (REGULATOR)Title:WELL SAMPLING DATA

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748409

Document Type:Site DocumentsDocument Date:6/11/1991Type:OTHER REPORT / DOCUMENTSubmitted:

Type: OTHER REPORT / DOCUMENT
Submitted By: KIMBERLY YEE (REGULATOR)

Submitted By:KIMBERLY YEE (REGUTitle:TEST TANK RESULTS

EST TANK RESULTS

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748446

Document Type: Site Documents Document Date: 5/23/1991

Type: CORRESPONDENCE Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

Title:PRELIMINARY PLAN REVIEW FOR PROPOSED INSTALLATION OF THREE 20000 GALLON USTSTitle Link:https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748492

Document Type: Site Documents Document Date: 5/15/1991

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

REPORT OF SOILTEST LEAK MASTER LINE TEST

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748497

Document Type: Site Documents **Document Date:** 5/15/1991

Type: OTHER REPORT / DOCUMENT

KIMBERLY YEE (REGULATOR)

AINLAY TANK TIGHTNESS TEST NO. 2

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748338

Document Type: Site Documents Document Date: 5/3/1991

Submitted By:

Title:

Number of Direction Elev/Diff Site DΒ Map Key Distance Records (mi/ft) (ft)

Submitted:

CORRESPONDENCE Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

INFORMATIVE LETTER TO CHEIF MARCUCCI Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748381

Site Documents 3/28/1991 Document Type: Document Date:

Type: CORRESPONDENCE

Submitted By: KIMBERLY YEE (REGULATOR)

Title: ITEMS THAT REQUIRE ATTENTION REGARDING THE UNDERGROUND STORAGE TANKS

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748379 Title Link:

Document Type: Site Documents Document Date: 3/25/1991

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

PERMIT APPLICATION ACKNOWLEDGEMENT Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748487 Title Link:

Document Type: Site Documents Document Date: 11/30/1990

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

Submitted By: KIMBERLY YEE (REGULATOR) Title:

UNDERGROUND OIL TANK RÉMOVALS

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5744194 Title Link:

Document Type: Site Documents Document Date: 11/19/1990

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

HAZARDOUS MATERIALS RELEASE - UNDERGROUND DIESEL STORAGE TANK INVESTIGATION, CLEAN-Title:

Submitted:

UP AND ABATEMENT ORDER

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748369

Document Type: Site Documents Document Date: 11/19/1990

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR)

ANNUAL INSPECTION CHECKLIST FOR EXISTING UNDERGROUND STORAGE TANKS

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748339 Title Link:

Document Date: 10/30/1990 Document Type: Site Documents

Type: CORRESPONDENCE Submitted:

KIMBERLY YEE (REGULATOR) Submitted By:

Title: EVALUATION OF ANALYTICAL RESULTS FROM SOIL SAMPLING PARK & RIDE SITE

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748343 Title Link:

Site Documents Document Date: 10/29/1990 Document Type: Submitted:

CORRESPONDENCE Type:

KIMBERLY YEE (REGULATOR) Submitted By:

DEPOSITION OF OIL LADEN SOIL ON ANDERSEN DRIVE SITE, TELEPHONE CONVERSATION OF Title:

OCTOBER 26, 1990

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748346

Site Documents Document Date: 10/16/1990 Document Type:

OTHER REPORT / DOCUMENT Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

FIELD REPORT Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748365

Document Type: Site Documents Document Date: 10/4/1990

Type: OTHER REPORT / DOCUMENT Submitted:

Submitted By: KIMBERLY YEE (REGULATOR)

SAN RAFAEL FIRE DEPARTMENT PERMIT

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748457 Title Link:

Document Type: Site Documents Document Date: 8/3/1990

CORRESPONDENCE Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR) Title:

HAZARDOUS MATERIALS RELEASE CLEAN-UP AND ABATEMENT ORDER

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748376

Order No: 24072600476

Document Type: Site Documents **Document Date:** 7/10/1990

Title:

Submitted: CORRESPONDENCE Type:

Submitted By: KIMBERLY YEE (REGULATOR)

HAZARDOUS MATERIALS RELEASE, CLEAN-UP AND ABATEMENT ORDER Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748375

Document Type: Site Documents 5/16/1990 Document Date: Submitted:

Type: CORRESPONDENCE Submitted By:

KIMBERLY YEE (REGULATOR)

Title: UNDERGROUND STORAGE TANK - DIESEL TANK NO.1

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748461

Document Type: Site Documents Document Date: 4/27/1990

CORRESPONDENCE Type: Submitted:

KIMBERLY YEE (REGULATOR) Submitted By:

LEAKING UNDERGROUND DIESEL TANK NO.1 Title:

 $https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054\&document_id=5748430$ Title Link:

Document Type: Site Documents Document Date: 4/13/1990

CORRESPONDENCE Submitted: Type:

Submitted By: MADELEINE LITTLE (REGULATOR)

UST FACILITY - DIESEL TANK NO.1 FURTHER INVESTIGATION Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5993877

Site Documents Document Date: 4/6/1990 Document Type:

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

Submitted By: KIMBERLY YEE (REGULATOR)

UST REMOVAL/ABANDONMENT INSPECTION CHECKLIST Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748407 Title Link:

4/4/1990 Document Type: Site Documents **Document Date:**

OTHER REPORT / DOCUMENT Type:

KIMBERLY YEE (REGULATOR)

Submitted By:

UNDERGROUND STORAGE TANK - DIESEL TANK NO.1 Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748460

Submitted:

Submitted:

Document Type: Site Documents Document Date: 3/30/1990

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR)

CLIENT REFERENCE INFORMATION-SAMPLE ANALYSIS Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748450 Title Link:

Document Type: Site Documents 3/29/1990 Document Date:

TANK REMOVAL REPORT / UST SAMPLING Submitted: Type:

REPORT

Submitted By: KIMBERLY YEE (REGULATOR) Title:

UNDERGROUND STORAGE TANK TEST RESULTS

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748459 Title Link:

Document Type: Site Documents Document Date: 2/15/1990

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR) LOG OF EXPLORATORY BORINGS Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748382

Document Type: Site Documents **Document Date:** 1/17/1990

OTHER REPORT / DOCUMENT Submitted: Type:

KIMBERLY YEE (REGULATOR) Submitted By:

PROPOSAL - SUBSURFACE HYDROGEOLOGIC INVESTIGATION

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748423 Title Link:

Document Type: Site Documents Document Date: 12/18/1989

OTHER REPORT / DOCUMENT Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR) Title: METCALF & EDDY MEETING

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748490 Title Link:

Order No: 24072600476

Site Documents **Document Date:** 12/5/1989 Document Type:

OTHER REPORT / DOCUMENT Submitted: Type:

Number of Direction Elev/Diff Site DΒ Map Key Distance Records (mi/ft) (ft)

KIMBERLY YEE (REGULATOR) Submitted By:

SOIL MOVEMENT FROM 1011 ANDERSEN SAN RAFAEL Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748503 Title Link:

Document Type: Site Documents Document Date: 10/27/1989

CORRESPONDENCE Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

INFORMATION REQUESTED BY FORREST CRAIG Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748452

Site Documents **Document Date:** 4/21/1989 Document Type:

CORRESPONDENCE Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

DETECTION OF WATER IN 6000 GALLON UNLEADED FUEL TANK Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748451

Site Documents Document Date: 1/13/1989 Document Type:

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR) Title: PROPOSED SITE INVESTIGATION

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748420 Title Link:

Submitted:

Submitted:

Submitted:

Submitted:

Document Type: Site Documents Document Date: 1/3/1989

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR)

PHOTOS OF EXPLORATORY TRENCHING. SHORING INSTALLATION. EMPTYING WASTE & DRAIN OIL Title:

TANKS, ETC.

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748398 Title Link:

Document Type: Site Documents Document Date: 11/10/1988

OTHER REPORT / DOCUMENT Type:

Submitted By: MADELEINE LITTLE (REGULATOR) PRECISION TANK TEST REPORT Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document id=5993880 Title Link:

10/10/1988 Document Type: Site Documents Document Date:

Type: UNAUTHORIZED RELEASE FORM

KIMBERLY YEE (REGULATOR) Submitted By:

Title: UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) I CONTAMINATION SITE REPORT https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748414 Title Link:

Site Documents Document Date: 10/10/1988 Document Type:

OTHER REPORT / DOCUMENT Submitted: Type:

Submitted By: MADELEINE LITTLE (REGULATOR)

Title: UST UNAUTHORIZED RELEASE CONTAMINATION SITE REPORT

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5993879 Title Link:

Document Type: Site Documents Document Date: 10/4/1988

UNAUTHORIZED RELEASE FORM Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/CONTAMINATED SITE REPORT Title: Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748413

Document Type: Site Documents Document Date: 9/14/1988

CORRESPONDENCE Submitted: Type:

KIMBERLY YEE (REGULATOR) Submitted By:

INFORMATION DISCUSSED SEPT.9 REGARDING UNDERGROUND FUEL STORAGE TANKS Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748378 Title Link:

Document Type: Site Documents **Document Date:** 9/9/1988

CORRESPONDENCE Submitted: Type:

KIMBERLY YEE (REGULATOR) Submitted By:

FOLLOW-UP TO PREVIOUS CONVERSATION

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748363 Title Link:

Order No: 24072600476

Document Type: Site Documents Document Date: 8/26/1988

Type: OTHER REPORT / DOCUMENT Submitted:

KIMBERLY YEE (REGULATOR) Submitted By:

UNDERGROUND TANK MANAGEMENT PROJECT-AUTHORIZATION FOR TESTING (ACTION) Title:

Number of Direction Distance Elev/Diff Site DΒ Map Key Records (mi/ft) (ft)

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748438 Title Link:

Document Type: Site Documents Document Date: 4/29/1988

CORRESPONDENCE Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR) SAMPLE ANALYSES RESULTS Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748454

Site Documents **Document Date:** 2/5/1988 Document Type:

CORRESPONDENCE Submitted: Type:

Submitted By: KIMBERLY YEE (REGULATOR)

Title: HAZARDOUS MATERIAL DISCLOSURE

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748355 Title Link:

Document Type: Site Documents Document Date: 1/6/1988

CORRESPONDENCE Type: Submitted:

Submitted By: KIMBERLY YEE (REGULATOR) HAZARDOUS MATERIAL DISCLOSURE Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748356 Title Link:

Document Type: Site Documents 12/31/1987 Document Date:

CORRESPONDENCE Type: Submitted By: KIMBERLY YEE (REGULATOR)

URGENT PRIORITY ANALYSIS OF TWO SAMPLES IDENTIFIED AS "1211-1 AND -2" RECEIVED DEC.11 1987 Title:

Submitted:

Submitted:

Submitted:

Submitted:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748411

Document Type: Site Documents Document Date: 10/14/1987

TANK REMOVAL REPORT / UST SAMPLING Type: Submitted:

REPORT

KIMBERLY YEE (REGULATOR) Submitted By:

PERMIT TO REMOVE UNDERGROUND STORAGE TANK Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748422

Document Type: Site Documents **Document Date:** 3/9/1987

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR)

HAZARDOUS WASTE PREDISPOSAL EVALUATION Title:

https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748437 Title Link:

7/1/1984 Document Type: Site Documents **Document Date:**

OTHER REPORT / DOCUMENT Type:

Submitted By: KIMBERLY YEE (REGULATOR)

HAZARDOUS SUBSTANCE STORAGE STATEMENT Title:

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748377

Document Date: 10/27/1972 Document Type: Site Documents

OTHER REPORT / DOCUMENT Type: KIMBERLY YEE (REGULATOR) Submitted By:

Title: BORING LOCATION PLAN

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0604100054&document_id=5748488

77 3 of 16 SSW 0.19/ 6.51/ GOLDEN GATETRANSIT. **AST** 1011 ANDERSEN DRIVE 1,002.60 2

SAN RAFAEL CA 94901

GOLDEN GATE BRIDGE DIST. Total Capacity(Gal): 10,100 Owner Name:

CUPA: Marin County: Marin

4 of 16 SSW 0.19/ 6.51/ Golden Gate Transit 77 **CUPA MARIN**

1.002.60 1011 Andersen Drive, San Rafael 2

Order No: 24072600476

CA

Permit No: 30-0378 UFC: No Type of Permit: **HWG Tons:** 0.0 Cross Ref: HWG Recycle: No

Status: Active **RCRALQG** HWG Type Gen:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site		DB
US Tanks: AG Tanks: HMBP: Cal ARP:	3 4 25 No			Tiered: PBR HHW Green: Facility Pi		No No No (415) 257-4553	
77	5 of16	ssw	0.19 / 1,002.60	6.51 / 2	GOLDEN GATE TRANSIT 1011 ANDERSON DR SAN RAFAEL CA 94901		HHSS
County: Tank Details Microfiche:		Marin http://geotracke	Marin http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002923e.pdf				

77 6 of 16 SSW 0.19 / 6.51 / Golden Gate Transit CERS TANK 1,002.60 2 1011 ANDERSEN DR SAN RAFAEL CA 94901

 Site ID:
 33657

 Latitude:
 37.955900

 Longitude:
 -122.504100

Regulated Programs

EI ID: 227495

El Description: Industrial Facility Storm Water

EI ID: 10031590

El Description: Aboveground Petroleum Storage

EI ID: 10031590

El Description: Chemical Storage Facilities

EI ID: T0604100054

El Description: Leaking Underground Storage Tank Cleanup Site

EI ID: 10031590

El Description: Hazardous Waste Generator

EI ID: 10031590

El Description: Underground Storage Tank

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 22 CCR 15 66265.51 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.51

Violation Notes:

Returned to compliance on 10/09/2017. At time of inspection, there was no hazardous waste emergency response contingency plan available. Site is a large quantity generator; therefore, required to have a contingency plan. The HMBP emergency response contingency plan can be used both for HMBP and Hazardous Waste. Complete within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to prepare and implement a written Contingency Plan to minimize hazards to human health or the environment from fires, explosions, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Notes:

Returned to compliance on 11/16/2017. At time of inspection, used antifreeze did not have proper labeling for hazardous waste. In addition, used oil tank stored in shed will also need proper hazardous waste labeling. Complete within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: APSA Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Notes:

Returned to compliance on 11/28/2017. At time of inspection, inventory in the SPCC Plan did not match with the hazardous materials business plan inventory. Please update within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to address in the SPCC Plan the type of oil and storage capacity for each fixed container, and either the type of oil and storage capacity for each mobile or portable container, or an estimate of the potential number of mobile or portable containers, the types of oil, and anticipated storage capacities.

Violations

Violation Date: 05/16/2022 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2636(f)(1) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(1)

Violation Notes:

Returned to compliance on 06/16/2022. Owner/Operator did not maintain leak detection equipment with an audible and visual alarm. Tank 2 STP L3 sensor failed. Retest Tank 2 sump sensor within 30 days and send the test report to Marin CUPA within 30 days of the test.

Violation Description:

Failure of the leak detection equipment to have an audible and visual alarm as required.

Violations

Violation Date:07/02/2007Violation Source:SMARTSViolation Program:INDSTWViolation Division:Water Boards

Citation: 2014-0057-DWQ - Industrial General Permit

Violation Notes:

Failure to submit the 2006-2007 Annual Report by 7/1/07 due date.

Violation Description:

SW - Late Report

Violations

Violation Date:07/02/1999Violation Source:SMARTSViolation Program:INDSTWViolation Division:Water Boards

Citation: 2014-0057-DWQ - Industrial General Permit

Violation Notes:

Non-submittal of Annual Report. Due 7//1/1999

Violation Description:

SW - Deficient Report

Violations

Violation Date: 05/07/2018 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665

Violation Notes:

Returned to compliance on 06/12/2018. At time of inspection, spill bucket test for Tank #1 failed during AMC. Please fix issue and conduct re-test within 30 days. Install or repair spill bucket so that it is liquid-tight, has a minimum capacity of five gallons, has a functional drain valve or other method for the removal of liquid from the spill bucket/spill container, and is resistant to galvanic corrosion. Submit verification.

Violation Description:

Failure to comply with one or more of the following:

Failure to install or maintain a liquid-tight spill bucket.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container.

Be resistant to galvanic corrosion.

Violations

Violation Date: 05/09/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)

Violation Notes:

Returned to compliance on 06/09/2017. At time of inspection, CERS submissions were not all current and correct in regards to tank components. Please update and reflect current tank components. Complete within 30 days, and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to have an approved UST Monitoring Plan.

Violations

Violation Date: 05/09/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2715(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(i)

Violation Notes:

Returned to compliance on 05/19/2017. At time of inspection, annular sensor for tank #2 kept going into alarm when EPIC Compliance was putting the sensor back into its annular space. Due to the secondary containment test that was done prior to the AMC, it may have resulted in water intrusion to the annular area. EPIC removed liquid from annular space, but the alarm kept going off. Therefore, facility must remove all water by 5/19 to stop further alarm and enable all functions to be normal.

Violation Description:

Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.).

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 22 CCR 15 66265.174 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.174

Violation Notes:

Returned to compliance on 11/30/2017. At time of inspection, facility was not recording weekly hazardous waste inspections. Facility is a large quantity generator; therefore, required to conduct recordkeeping. Provide proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to inspect weekly, areas where hazardous waste containers are stored or transferred. The owner or operator shall look for leaking containers and for deterioration of containers and the containment system caused by corrosion or other factors.

Violations

Violation Date: 05/07/2018 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.7 25299(a)(9) - California Health and Safety Code, Chapter 6.7, Section(s) 25299(a)(9)

Violation Notes:

Returned to compliance on 05/07/2018. At time of inspection, DO inspection report indicated that on 2/11/18 and 2/13/18, ATG probes were taken out for tank ID #1 and tank ID #2. Information was provided that probes were taken out by the Owner/Operator, not by a licensed UST contractor. Owner/Operator tampered with leak detection equipment in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak. Owner/Operator shall not tamper with monitoring equipment. Moving forward, Owner/Operator must consult with EPIC Compliance (or another licensed UST contractor) to modify/fix/repair any UST related issues. If the Owner/Operator repeats this violation, Marin County CUPA will Red Tag the facility.

Violation Description:

Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak.

Violations

Violation Date: 07/19/2019 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2712(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(f)

Violation Notes:

Returned to compliance on 07/25/2019. Owner/Operator did not implement the corrections specified in the inspection report within 30 days of receiving an inspection report from either the CUPA or special inspector. Correct all deficiencies identified on the inspection report provided by the CUPA or special inspector within 15 days.

Violation Description:

Failure to implement the corrections specified in the inspection report within 30 days of receiving an inspection report from either the UPA or special inspector.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HMRRP Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: HSC 6.95 25505(c) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(c)

Violation Notes:

Returned to compliance on 11/28/2017. At time of inspection, business plan was not available (only electronic copy). Please print out a copy of the HMBP business plan and leave it at the site. Complete within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to have a business plan readily available to personnel of the business or the unified program facility with responsibilities for emergency response or training.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: APSA Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Notes:

Returned to compliance on 11/28/2017. At time of inspection, facility did not have available written procedures for inspections and tests. Provide proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to discuss in the SPCC Plan procedures to test or inspect each aboveground container for integrity in accordance with industry standards:

- 1. On a regular schedule.
- 2. After material repairs are made.
- 3. By qualified personnel.
- 4. The frequency and type of testing and inspections based on container size, configuration, and design.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 22 CCR 23 66273.34 - California Code of Regulations, Title 22, Chapter 23, Section(s) 66273.34

Violation Notes:

Returned to compliance on 11/16/2017. At time of inspection, facility was not managing used fluorescent tubes and batteries per universal waste standards (labeling and storage required). Provide proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to label or mark each individual or container or the designated area of universal waste as required. 1) Waste batteries shall be marked with "Universal Waste-Battery(ies)". 2) Mercury containing equipment shall be marked with "Universal Waste -Mercury-Containing Equipment". 3) Lamps shall be marked with "Universal Waste-Lamp(s)". 4)Each electronic devices or the container or the designated area shall be marked with "Universal Waste-CRTs or the container or the designated area shall be marked with "Universal Waste-CRT glass or the designated area shall be marked with "Universal Waste-CRT glass".

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: APSA Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Notes:

Returned to compliance on 11/16/2017. At time of inspection, facility did not have available records of inspections for the aboveground storage tanks. Begin conducting inspections and maintain records onsite for 3 years. In addition, have inspections/tests signed by a supervisor or inspector. Provide proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to comply with one or more of the following requirements:

1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector.

2. Keep written procedures and records of inspections and integrity tests for at least three years.

3. Keep comparison records.

Violations

Violation Date: 07/19/2019 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2

Violation Notes:

Returned to compliance on 07/25/2019. Owner/Operator failed to meet one or more of the following spill container requirements: install or maintain spill container which is liquid-tight, has a minimum capacity of five gallons, has a functional drain valve or other method for the removal of liquid from the spill container, and is resistant to galvanic corrosion; did not perform tightness test at installation, every 12 months thereafter, or within 30 days after a repair; did not have tested using manufacturer's guidelines, industry codes, engineering standards, or method approved by PE, or was not tested by a certified UST service technician; or failed to maintain testing records for 36 months. Install or repair spill buckets to meet all of the listed requirements, have tightness tested using approved method, by certified UST service technician, and submit documentation to verify compliance within 15 days. Maintain all testing records for 36 months.

Violation Description:

"Failure to meet one or more of the following requirements:

Install or maintain a liquid-tight spill container.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill container.

Be resistant to galvanic corrosion.

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Tested by a certified UST service technician.

Maintain records of spill containment testing for 36 months.

Violations

Violation Date: 05/16/2023 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)

Violation Notes:

Returned to compliance on 05/16/2023. Line leak detector for tank #2 failed to detect a release of 3.0 gallons per hour at 10 p.s.i.g. The LLD was adjusted and passed retest so no action is required at this time.

Violation Description:

Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.

Violations

Violation Date: 02/27/2023 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 40 CFR 1 265.201(c)(5) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.201(c)(5)

Violation Notes:

Returned to compliance on 02/27/2023. OBSERVATION: Weekly hazardous waste tank inspections for the [HAZARDOUS WASTE] tank have not been conducted. Conduct weekly inspections of the hazardous waste tank according to the requirements identified above and submit a copy of the documentation to the CUPA.

Violation Description:

Failure to inspect hazardous waste tanks for the following, when present:

- 4) The construction materials of the tank at least weekly to detect corrosion or leaking of fixtures or seams.
- 5) The construction materials of, and the area immediately surrounding, discharge confinement structures (e.g., dikes) at least weekly to detect erosion or obvious signs of leakage (e.g., wet spots or dead vegetation).

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HMRRP Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Notes:

Returned to compliance on 10/26/2017. At time of inspection, facility map did not include storm/sewer drains, access/exit points, evacuation staging area, hazardous materials and hazardous waste areas, gas/water/electric shut off, etc. Within 30 days, upload an updated site map into CERS.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 05/16/2022 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)

Violation Notes:

Returned to compliance on 06/16/2022. Tank 1 LLD failed to detect a release of 3.0 gallons per hour at 10 p.s.i.g. Retest Tank 1 LLD within 30 days and send the test report to Marin CUPA within 30 days of the test.

Violation Description:

Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: APSA Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Notes:

Returned to compliance on 11/28/2017. At time of inspection, SPCC Plan was not stamped/signed by a professional engineer. Please have a licensed professional engineer review and certify the SPCC Plan within 30 days, and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to have a licensed professional engineer properly review and certify the SPCC Plan.

Violations

Violation Date: 05/16/2022 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2632(c)(2)(A)&(B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632(c)(2)(A)&(B)

Violation Notes:

Returned to compliance on 06/16/2022. Owner/Operator did not continuously monitor the interstitial space of the USTs such that the leak detection activates an audible/visual alarm when a leak is detected. Tank 1 L2 annular sensor took a while to go into alarm and then when it finally did it took a while for the alarm to clear. Retest Tank 1 L2 annular sensor within 30 days and send the test report to Marin CUPA within 30 days of the test.

Violation Description:

Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: APSA Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Notes:

Returned to compliance on 11/28/2017. At time of inspection, SPCC Plan did not include a facility diagram. Please update SPCC Plan to include facility diagram. Complete within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to include in the SPCC Plan an adequate facility diagram, or no facility diagram included.

The facility diagram is not required on a Tier I qualified facility SPCC Plan.

Violations

Violation Date: 05/07/2018 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)

Violation Notes:

Returned to compliance on 06/08/2018. At time of inspection, facility did not have an approved Monitoring Plan. See email for details on what to correct in CERS. Maintain an Approved Monitoring Plan.

Violation Description:

Failure to have an approved UST Monitoring Plan.

Violations

Violation Date: 05/09/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mamt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665

Violation Notes:

Returned to compliance on 05/09/2017. At time of inspection, spill bucket tank #1 and tank #2 did not pass. EPIC Compliance tightened the gasket and re-tested the spill buckets. Spill buckets passed the re-test. Issue has been corrected onsite.

Violation Description:

Failure to comply with one or more of the following:

Failure to install or maintain a liquid-tight spill bucket.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container.

Be resistant to galvanic corrosion.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: APSA Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Notes:

Returned to compliance on 11/28/2017. At time of inspection, SPCC Plan failed to include current facility contacts, cleanup contractors, Federal, State, and local agencies in the case of a discharge. Update SPCC Plan within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to include in the SPCC Plan:

- 1. A contact list and phone numbers for the facility response coordinator, National Response Center, cleanup contractors with an agreement for response, and all Federal, State, and local agencies who must be contacted in case of a discharge
- 2. Information and procedures that would enable a person reporting an oil discharge to relate all information as described in 40 CFR 112.7(a)(4), unless facility submitted a Facility Response Plan.

Violations

Violation Date: 05/23/2019 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2

Violation Notes:

Returned to compliance on 07/25/2019. Owner/Operator failed to meet one or more of the following spill container requirements: install or maintain spill container which is liquid-tight, has a minimum capacity of five gallons, has a functional drain valve or other method for the removal of liquid from the spill container, and is resistant to galvanic corrosion; did not perform tightness test at installation, every 12 months thereafter, or within 30 days after a repair; did not have tested using manufacturer's guidelines, industry codes, engineering standards, or method approved by PE, or was not tested by a certified UST service technician; or failed to maintain testing records for 36 months. - tank 2 Install or repair spill bucket for tank 2 to meet all of the listed requirements, have tightness tested using approved method, by certified UST service technician, and submit documentation to verfiy compliance. Maintain all testing records for 36 months.

Violation Description:

"Failure to meet one or more of the following requirements:

Install or maintain a liquid-tight spill container.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill container.

Be resistant to galvanic corrosion.

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Tested by a certified UST service technician.

Maintain records of spill containment testing for 36 months.

11

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 22 CCR 15 66265.195(c) - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.195(c)

Violation Notes:

Returned to compliance on 11/16/2017. At time of inspection, facility was not conducting daily tank inspections for two used oil hazardous waste tanks. Facility is a large quantity generator; therefore, required to conduct recordkeeping. Provide proof of correction to Marin County CUPA within 30 days.

Violation Description:

Failure to conduct and document inspections of hazardous waste tank systems each operating day and retain records of those inspections at the facility.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: APSA Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Notes:

Returned to compliance on 11/28/2017. At time of inspection, facility was conducting annual SPCC training; however, training components did not meet SPCC training requirements per CFR 112.7(f). Please update training program within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to provide the following training to all oil-handling personnel:

- 1. Operation and maintenance of equipment to prevent discharges.
- 2. Discharge procedure protocols.
- 3. Applicable pollution control laws, rules, and regulations.
- 4. General facility operations.
- 5. Contents of the SPCC Plan.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 22 CCR 23 66273.33.5 - California Code of Regulations, Title 22, Chapter 23, Section(s) 66273.33.5

Violation Notes:

Returned to compliance on 11/16/2017. At time of inspection, used batteries and used fluorescent tubes were not placed in containers to prevent release of universal waste. Please correct within 30 days and provide proof of correction to Marin County CUPA.

Violation Description:

Failure of the universal waste handler of electronic devices, CRTs, and CRT glass to prevent the release of the universal waste to the environment under reasonable conditions by the following methods:

- 1) Immediately clean spills and leaks of universal wastes; and
- 2) Place all universal waste spills and leaks in containers that are structurally sound and compatible with the universal waste."

Violations

Violation Date: 05/09/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: 23 CCR 16 2715(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(i)

Violation Notes:

Returned to compliance on 05/19/2017. At time of inspection, EPIC Compliance was unable to test LLDs due to technical difficulties with adjusting the electrical wires. Will need to schedule another day to conduct LLD test with an electrician. Complete within two weeks.

Violation Description:

Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.).

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HMRRP Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Notes:

Returned to compliance on 10/09/2017. At time of inspection, facility had an outdated emergency response/contingency plan. Please upload updated emergency response/contingency into CERS within 30 days.

Violation Description:

Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.

Violations

Violation Date: 05/21/2021 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Order No: 24072600476

Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2

Violation Notes:

Returned to compliance on 10/04/2021. Owner/Operator failed to meet one or more of the following spill container requirements: install or maintain spill container which is liquid-tight, has a minimum capacity of five gallons, has a functional drain valve or other method for the removal of liquid from the spill container, and is resistant to galvanic corrosion; did not perform tightness test at installation, every 12 months thereafter, or within 30 days after a repair; did not have tested using manufacturer's guidelines, industry codes, engineering standards, or method approved by PE, or was not tested by a certified UST service technician; or failed to maintain testing records for 36 months. At time of inspection diesel bucket # 2 failed @ bottom of bucket while trying to clean drain valve. Install or repair spill buckets to meet all of the listed requirements, have tightness tested using approved method, by certified UST service technician, and submit documentation to verfi... [TRUNCATED: Refer to full Inspection Report]

Violation Description:

"Failure to meet one or more of the following requirements:

Install or maintain a liquid-tight spill container.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill container.

Be resistant to galvanic corrosion.

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Tested by a certified UST service technician.

Maintain records of spill containment testing for 36 months.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 22 CCR 15 66265.174 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.174

Violation Notes:

Returned to compliance on 12/07/2017. This violation has been elevated from a notice to comply to a class II. Please provide proof of documentation that weekly hazardous waste inspections are being documented since the site is classified as a large quantity generator. Complete by 12/22/17.

Violation Description:

Failure to inspect weekly, areas where hazardous waste containers are stored or transferred. The owner or operator shall look for leaking containers and for deterioration of containers and the containment system caused by corrosion or other factors.

Violations

Violation Date: 08/11/2017 Violation Source: CERS

Violation Program: HW Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: HSC 6.5 25201 - California Health and Safety Code, Chapter 6.5, Section(s) 25201

Violation Notes:

Returned to compliance on 11/16/2017. At time of inspection, waste antifreeze and waste paint-related material both exceeded 90 day accumulation period. Please remove waste within 30 days, provide proof of correction to Marin County CUPA.

Violation Description:

Failure to obtain a permit or grant of interim status after generator has accumulated hazardous waste on-site for longer than 90 days.

Violations

Violation Date: 05/09/2017 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Citation: 23 CCR 16 2715(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(f)

Violation Notes:

Returned to compliance on 06/22/2017. At time of inspection, DO training form was done 5/3/16; therefore, facility is past due for 2017 training. Conduct training within 30 days, and provide proof of correction to Marin County CUPA.

Violation Description:

Failure to have at least one employee present during operating hours that has been trained in the proper operation and maintenance of the UST system by a designated operator (DO).

Violations

Violation Date:07/04/2005Violation Source:SMARTSViolation Program:INDSTWViolation Division:Water Boards

Citation: 2014-0057-DWQ - Industrial General Permit

Violation Notes:

Failure to submit 2004/2005 annual report by July 1, 2005

Violation Description:

SW - Late Report

Violations

Violation Date: 05/07/2018 Violation Source: CERS

Violation Program: UST Violation Division: Marin County Dept of Public Works, Waste

Mgmt, CUP

Elev/Diff DB Map Key Number of Direction Distance Site Records (mi/ft) (ft)

HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34 Citation:

Violation Notes:

Returned to compliance on 06/08/2018. At time of inspection, Financial responsibility documents were not current in CERS. Current financial responsibility documents are required to be submitted annually. Upload updated Financial Responsibility and CFO Letter into CERS within 30 days. Complete and submit a copy of the financial responsibility by 6/6/2018.

Violation Description:

Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.

Violations

Violation Date: 05/09/2017 Violation Source: **CERS**

UST Violation Division: Marin County Dept of Public Works, Waste Violation Program:

Mamt. CUP

Order No: 24072600476

23 CCR 16 2715(c) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c) Citation:

Violation Notes:

Returned to compliance on 05/09/2017. At time of inspection, 0.5 gallons of water from secondary containment was removed for all 3 tanks. Contractor removed water and issue was corrected onsite.

Violation Description:

Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements:

Be performed by an ICC certified DO.

Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers.

Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented.

Verify that all facility employees have been properly trained.

Enforcements

Enf Action Program: Enf Action Date: 07/19/2019 UST Notice of Violation (Unified Program) Enf Action Source: **CERS** Enf Action Type:

Marin County Dept of Public Works, Waste Mgmt, CUP Enf Action Division:

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enf Action Notes:

Spill bucket passed re-test 7/25/2019 after reducing length of fill pipe.

Evaluations

Eval Date: 02/27/2023

Violations Found: No

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: **HMRRP** Eval Source: **CERS**

Eval Notes:

Sean Phillips granted access Updated CERS; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/05/2014

Violations Found:

Eval General Type: Compliance Evaluation Inspection Routine done by local agency Eval Type:

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: **HMRRP** Eval Source: **CERS**

Eval Notes:

Eval Date: 05/06/2015

Violations Found: No

Eval General Type:Compliance Evaluation InspectionEval Type:Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Eval Date: 07/19/2019

Violations Found: Yes

Eval General Type: Other/Unknown

Eval Type: Other, not routine, done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Eval Date: 05/07/2018

Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

UST Technician: Brian Dunahay with EPIC Compliance (ICC #8021436, Exp. 2/16/19), (Veeder-Root #B42886, Exp. 3/14/19), (VMi #3498, Exp. 3/4/2020). 2/21/18- High water alarm, issue was corrected by Epic Compliance. Per email with John Gazzoli, ATG probes were removed on 2/11/18 and 2/13/18 to attempt removal of water, which turned out to be an unknown solid (i.e. sediment).; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/05/2014

Violations Found: No

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Eval Date: 05/29/2020

Violations Found:

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Tec Accutite Adrian Perez ICC 8724424 exp 03/14/2023 SB989 Conducted 8/28/2020 JB for CC; Note: data in [EVAL Notes] field for some records is truncated from the source.

Order No: 24072600476

Eval Date: 05/19/2016

Violations Found: No

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Eval Date: 05/21/2021 **Violations Found:** Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Tec Accutite Adrian Perez ICC 8724424 exp 03/14/2023 At time of inspection diesel bucket # 2 failed @ bottom of bucket while trying to clean drain valve. Please submit application to Marin CUPA repair Diesel bucket # 2.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/11/2017

Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HMRRP Eval Source: CERS

Eval Notes:

NOTE: Initial due date was scheduled for 9/11/17; however, site asked for an extension till 10/11/17. Site is in progress with getting the items completed; however, due to staffing schedule- they requested an extension. Gave the facility till 11/30/17 with no elevated violation. If not complete by 11/30, will be elevating to a Class II NOV.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/09/2017 Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

NOTE: Tank #2 annular sensor kept going into alarm when EPIC was attempting to the put the sensor back in its annular space. When I arrived to the site on 5/19, John G. from Golden Gate Transit had already pumped out the liquid from the annular space, and no more alarms were activated. Since I did not witness the removal, I indicated "Unobserved" as the RTC Qualifier.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/11/2018 **Violations Found:** No

Eval General Type: Other/Unknown

Eval Type: Other, not routine, done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Visited the facility on 1/11/2018 to witness cold-start. There were unnecessary items showing up on the alarm history printouts and system status report that were irrelevant to the tank systems. Issues occurred with probe 2 during the Veeder-Root updates. Contractor replaced board and CPU in Veeder-Root, then conducted cold-start. We completed sensor out, fail safe. All items passed. Due to cold-start, site is possibly looking into conducting an Annual Monitoring Certification at an earlier date.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/23/2019 Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Overfill NOT tested. Spill bucket for tank 2 failed after second attempt. Tank 1 passed after second attempt. Audio and visual alarm adjacent to tanks is not functioning as it is supposed to. The only time it turned on was when the system was reconnected and the pumps were powering on. UST

Technician: Brian Dunahay (ICC #8021436, Exp. 3/08/21), (Veeder-Root #B42886, Exp. 3/08/21), (VMi #3498, Exp. 3/4/2020).; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:07/25/2019Violations Found:NoEval General Type:Other/Unknown

Eval Type: Other, not routine, done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Spill Bucket PASSED!; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/16/2022 Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Tester Andrew Pace with TEC Accutite (ICC 1/10/24)(VR 7/30/22)(VMI 10/20/22)(EVR 8/28/22)(CL762034). Tank 1 annular couldn't get it to go into alarm and then when it did it took a while for the alarm to clear. Tank 2 STP sensor failed (wire broke/cut). Tank 1 LLD couldn't be tested. Tank 3 what was the line that was sealed in March. All 3 spill buckets replaced in last few months.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/27/2023
Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW Eval Source: CERS

Eval Notes:

Asbury -waste oil, unviversal waste , paint waste 1/25/23 700 gallons waste oil Safety Kleen for waste paint related materials eManifests; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/05/2014

Violations Found: No

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW Eval Source: CERS

Eval Notes:

Eval Date: 08/11/2017

Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: APSA Eval Source: CERS

Eval Notes:

Facility is a non-qualified facility (>10,000 gallons of petroleum products). NOTE: Initial due date was scheduled for 9/11/17; however, site asked for an extension till 10/11/17. Site is in progress with getting the items completed; however, due to staffing schedule- they requested an extension. Gave the facility till 11/30/17 with no elevated violation. If not complete by 11/30, will be elevating to a Class II NOV.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Order No: 24072600476

Eval Date: 01/20/2004

Violations Found: No

Eval General Type: Other/Unknown

Eval Type: Construction Storm Water Compliance Evaluation

Eval Division:Water BoardsEval Program:INDSTWEval Source:SMARTS

Eval Notes:

Eval Date: 08/11/2017 Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection

Eval Type: Routine done by local agency
Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: HW Eval Source: CERS

Eval Notes:

NOTE: Initial due date was scheduled for 9/11/17; however, site asked for an extension till 10/11/17. Site is in progress with getting the items completed; however, due to staffing schedule- they requested an extension. Gave the facility till 11/30/17 with no elevated violation. If not complete by 11/30, will be elevating to a Class II NOV.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/16/2023

Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection Eval Type: Routine done by local agency

Eval Division: Marin County Dept of Public Works, Waste Mgmt, CUP

Eval Program: UST Eval Source: CERS

Eval Notes:

Andrew Pace with TEC Accutite (ICC 1/10/24)(VR 8/1/24)(OPW 9/19/24) (VMI 10/26/24)(CL762034). Contact Mike D (or Tim) at GGT to help change lines for the LLD test. Upload and submit in CERS the updated CFO letter by 5/25/2023. Upload and submit in CERS the updated Response Plan.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Order No: 24072600476

Affiliations

Affil Type Desc: Operator Entity Name: Sean Phillips

Entity Title:
Address:
City:
State:
Country:

Zip Code: Phone: (415) 257-4519

Affil Type Desc: UST Property Owner Name Entity Name: UST Property Owner Name

Entity Title:

Address: 1011 Andersen Drive

City: San Rafael State: CA

Country: United States Zip Code: 94901

Phone: (415) 257-4519

Affil Type Desc: Owner/Operator

Entity Name: Golden Gate Bridge District

Entity Title: Operator

Address: 1011 Anderson Dr City: San Rafael

State: CA

Country:

Zip Code: 94901

Phone:

Parent Corporation Affil Type Desc:

Entity Name: Golden Gate Bridge Highway and Transportation District Entity Title:

Address: City: State: Country: Zip Code:

Affil Type Desc: Local Agency Caseworker

Entity Name: BRADLEY R. MARK - SAN RAFAEL, CITY OF

Entity Title:

Address: 1039 C STREET City: SAN RAFAEL State: CA

Country:

Zip Code: Phone:

Phone:

UST Tank Owner Affil Type Desc: Entity Name: Entity Title: Golden Gate Transit

Address: 1011 Andersen Drive

City: San Rafael

State: CA

Country: **United States** Zip Code: 94901 (415) 257-4519 Phone:

Affil Type Desc: **Document Preparer** Sean Phillips

Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:

Property Owner Affil Type Desc: Entity Name: Entity Title: Golden Gate Bridge Dist.

Address: P.O. Box 9000 City: San Francisco

State: CA Country: **United States**

Zip Code: 94129 (415) 921-5858 Phone:

Affil Type Desc: **UST Permit Applicant** Entity Name: Karen Shelar **EH&S Specialist**

Entity Title: Address:

City: State: Country: Zip Code:

Phone: (415) 257-4519

Affil Type Desc: **Facility Mailing Address** Entity Name: Mailing Address

Entity Title:

Address: 1011 Andersen Drive

San Rafael City:

State: CA Country:

Zip Code: 94901

Phone:

Number of Direction Elev/Diff Site DB Map Key Distance Records (mi/ft) (ft)

Identification Signer Affil Type Desc: Sean Phillips Entity Name: Entity Title: EH&S Specialist

Address: City: State: Country: Zip Code: Phone:

Affil Type Desc: **UST Tank Operator** Entity Name: Golden Gate Transit

Entity Title:

1011 Andersen Drive Address:

San Rafael City: State: CA

United States Country: Zip Code: 94901

Phone: (415) 257-4519

Affil Type Desc: **CUPA** District Marin County CUPA Entity Name: Entity Title:

Address: 1600 Los GamosSuite 210

City: San Rafael

State: CA

Country:

Zip Code: 94903

Phone: (415) 473-6647

Affil Type Desc: **Environmental Contact**

Entity Name: Sean Phillips

Entity Title:

Address: 1011 Andersen Drive

San Rafael City: State: CA

Country:

94901 Zip Code:

Phone:

Affil Type Desc: Legal Owner

Entity Name: Golden Gate Bridge, Highway and Trans.

Entity Title:

Address: 1011 Andersen Drive San Rafael

City: State: CA

Country: **United States** Zip Code: 94901

Phone: (415) 257-4519

Coordinates

Env Int Type Code: **SMSWIND** Longitude: -122.509010

Program ID: 227495 Coord Name:

Latitude: 37.958690 Ref Point Type Desc: Unknown

7 of 16 SSW 0.19/ 6.51/ Golden Gate Transit **77 UST** 1011 Andersen Drive 1,002.60 San Rafael CA 94901

Order No: 24072600476

Facility ID: 21-000-300378 Latitude: 37.9559 CERS ID: 10031590 Longitude: -122.5041 County: Marin CalEnviroScrn 4 Pct: 70-75%

Marin County Dept of Public Works, Waste Management Division Permitting Agency:

Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)

Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca. Note:

gov/search

Tank Details

Epa Region: No. of Closed UST: 0 No. of Inuse UST:

No. of Oos UST:

Owner Type: Local Agency/District

Tank ID No.: UL234037 Tank Status: Confirmed/Updated Information

Tank Type: Double Wall Tank Alarms: Yes

Tank Ball Float: No Tank Operator Name: Golden Gate Transit 1011 Andersen Drive Tank Operator Mail Address:

Tank Operator Mail City: San Rafael Tank Operator Mail State: CA 94901 Tank Operator Mail Zip:

Tank Owner Name: Golden Gate Transit Tank Owner Mailing Address: 1011 Andersen Drive

Nο

Tank Owner Mailing City: San Rafael Tank Owner Mailing State: CA Tank Owner Mailing Zip: 94901 Tank Capacity Gallons: 20000 Tank Piping Construction: **Double Walled** Tank Piping Type: Pressure Tank Pw Piping Construction: **Fiberglass** Tank Sacrificial Anode:

Tank Closure Date:

Stand Alone Tank Tank Configuration:

Tank Contents: Diesel Tank Cp Impr Curr: No Tank Cp Shutoff: Yes

Tank Installatn Dt: 12/20/1991 12:00:00 AM

Tank No of Compart: Tank Pc Constructn: Steel Tank Spill Bucket: Yes Tribal Lands: Nο

Tank Details

Epa Region: 9 No. of Closed UST: 0 No. of Inuse UST: No. of Oos UST:

Local Agency/District Owner Type:

Tank ID No.: UL234036

Tank Status: Confirmed/Updated Information

Tank Type: Double Wall Tank Alarms: Yes

Tank Ball Float: No

Golden Gate Transit Tank Operator Name: Tank Operator Mail Address: 1011 Andersen Drive

Tank Operator Mail City: San Rafael Tank Operator Mail State: CA 94901 Tank Operator Mail Zip:

Golden Gate Transit Tank Owner Name: Tank Owner Mailing Address: 1011 Andersen Drive

San Rafael Tank Owner Mailing City: Tank Owner Mailing State: CA Tank Owner Mailing Zip: 94901 20000 Tank Capacity Gallons: Double Walled Tank Piping Construction: Tank Piping Type: Pressure Tank Pw Piping Construction: **Fiberglass**

Tank Sacrificial Anode: Nο Tank Closure Date:

Stand Alone Tank Tank Configuration:

Tank Contents: Diesel Tank Cp Impr Curr: No Tank Cp Shutoff: Yes

Tank Installatn Dt: 12/20/1991 12:00:00 AM

Tank No of Compart: Tank Pc Constructn: Steel Tank Spill Bucket: Yes Tribal Lands: No

Tank Details

Epa Region: 9 No. of Closed UST: 0

No. of Inuse UST: No. of Oos UST:

Owner Type: Local Agency/District Tank Closure Date:

Tank Configuration: Stand Alone Tank

Order No: 24072600476

Diesel Tank Contents: Tank Cp Impr Curr: No Tank Cp Shutoff: Yes

Tank ID No.: UL234038 Tank Installatn Dt: 12/20/1991 12:00:00 AM

Tank Status:Confirmed/Updated InformationTank Type:Double Wall

Tank Alarms: Yes
Tank Ball Float: No

Tank Operator Name: Golden Gate Transit
Tank Operator Mail Address: 1011 Andersen Drive

Tank Operator Mail City:San RafaelTank Operator Mail State:CATank Operator Mail Zip:94901

Tank Owner Name:Golden Gate TransitTank Owner Mailing Address:1011 Andersen Drive

Tank Owner Mailing City:San RafaelTank Owner Mailing State:CATank Owner Mailing Zip:94901Tank Capacity Gallons:20000Tank Piping Construction:Double WalledTank Piping Type:PressureTank Pw Piping Construction:Fiberglass

Tank Installath Dt: 12/20/1991 12:00:00 AN Tank No of Compart: 1

Tank Pc Constructn: Steel
Tank Spill Bucket: Yes
Tribal Lands: No

77 8 of 16 SSW 0.19 / 6.51 / GOLDEN GATE TRANSIT EMISSIONS 1,002.60 2 1011 ANDERSEN DRIVE SAN RAFAEL CA 94901

2003 Criteria Data

Tank Sacrificial Anode:

Facility ID: 12572 CERR Code:

No

 Facility SIC Code:
 5511
 TOGT:
 .256

 CO:
 21
 ROGT:
 .1

 Air Basin:
 SF
 COT:

 District:
 BA
 NOXT:

 COID:
 MRN
 SOXT:

 DISN:
 BAY AREA AQMD
 PMT:

 CHAPIS:
 PM10T:

2003 Toxic Data

Facility ID: 12572 COID: MRN

Facility SIC Code: 5511 DISN: BAY AREA AQMD

 CO:
 21
 CHAPIS:

 Air Basin:
 SF
 CERR Code:

 District:
 BA

TS: Health Risk Asmt:

Non-Cancer Chronic Haz Ind: Non-Cancer Acute Haz Ind:

 77
 9 of 16
 SSW
 0.19 / 6.51 / GOLDEN GATE BRIDGE & EMISSIONS

 1.002.60
 2
 TRANSIT DISTRICT

1011 ANDERSEN DRIVE SAN RAFAEL CA 94901

Order No: 24072600476

2014 Criteria Data

Facility ID: 1793 CERR Code:

 Facility SIC Code:
 4111
 TOGT:
 .054916575

CO: 21 ROGT:

Air Basin: SF COT: .027310316 District: BA NOXT: .12537929 COID: MRN SOXT: .000423512 DISN: **BAY AREA AQMD** .002328647 PMT: